



Marion IL

Lead Service Line Full Inspection Report



Water System Name:		Marion LSLI		System ID Number:		IL1990550		Current Inventory Date:		12/31/2024	
Total Service Lines:	9055	Total Lead:		Total Non-Lead:	9055	Total Galvanized Requiring Replacement:		Total Unknown:	0	Website Link to Material Inventory:	https://cityofmarionil.gov/wp-content/uploads/2025/01/LSLI-report-31DEC24.pdf

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Copper - No Lead Solder (C)		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)								
Copper - Lead Solder (CLS)		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)	Copper - Lead Solder (CLS)								
Galvanized (G)		Galvanized (G)					Galvanized (G)	Unknown (U)	Galvanized (G)								
Lead (L)		Galvanized Requiring Replacement (GRR)				Galvanized Requiring Replacement (GRR)	Non-Lead (NL)	Lead (L)									
Lead (L)		Lead (L)				Lead (L)		Lead (L)									
Cast/Ductile Iron or Transite (O)		Cast/Ductile Iron or Transite (O)				Cast/Ductile Iron or Transite (O)		Cast/Ductile Iron or Transite (O)									
Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Plastic - PVC, HDPE, PEX (P)													
Unknown (U)	Unknown (U)	Unknown (U)		Unknown (U)													
Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)		Unknown Not Lead (UNL)													
608 E MERIDIAN ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
605 S MADISON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1111 S MECHANIC ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
207 S MADISON ST D		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
703 S MECHANIC ST		No	No	1930	1930	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
207 S MADISON ST A		No	No	1978	1978	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
207 S MADISON ST C		No	No	1978	1978	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
903 S BUCHANAN ST		No	No	1905	1905	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1400 S MECHANIC ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
706 S BUCHANAN ST		No	No	1905	1905	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
302 E ALLEN AVE		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
404 E MITCHELL ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
606 E MERIDIAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
806 S VIRGINIA AVE		No	No	1912	1912	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
611 E MERIDIAN ST		No	No	1912	1912	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1406 S BUCHANAN ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)					Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)		
103 E MITCHELL ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1408 S BUCHANAN ST		No	No	1967	1967	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
918 S VIRGINIA AVE	LP1A087	No	No	1950	1950	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
205 S MARKET ST		No	No	2017	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
201 S MARKET ST		No	Yes	2017	2024	Maintenance Records	Plastic	P	P	NL	N	9/4/2024	Yes	12/5/2024	P	No	
204 E THORN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
609 E MERIDIAN ST		No	No	1925	1925	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
513 S MARKET ST		No	No	2017	1885	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
407 S MARKET ST		No	No	2017	1940	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
511 S MARKET ST		No	No	2017	1993	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1014 S BUCHANAN ST		No	No	2022	1925	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
412 E THORN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
403 S MARKET ST		No	No	2017	1886	Visual Inspection	Plastic	P	P	NL	N	N/R	No		No		
1100 S BUCHANAN ST		No	No	1980	1980	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
501 S MARKET ST		No	No	2017	1885	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
507 S MARKET ST		No	No	2017	1905	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
519 S MARKET ST		No	No	2017	1930	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
515 S MARKET ST		No	No	2017	1910	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1106 S MADISON ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
606 S MECHANIC ST		No	No	1910	1910	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
901 S MECHANIC ST B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1105 S MECHANIC ST B		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
302 E MITCHELL ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
505 S MECHANIC ST B		No	No	1926	1926	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
207 E MITCHELL ST		No	No	2005	2005	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
505 S MECHANIC ST A		No	No	1926	1926	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
901 S MECHANIC ST A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1013 S MECHANIC ST		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
603 S MECHANIC ST A		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
411 E MARION ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
605 S MARKET ST		No	No	1900	1900	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
108 E THORN ST		No	No	1914	1914	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
111 ALLEN AVE		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
412 E MARION ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
606 S BUCHANAN ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
700 S BUCHANAN ST		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
303 E EVERETT ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
703 S BUCHANAN ST		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
601 S BUCHANAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
406 S BUCHANAN ST		No	No	2019	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
601 S MADISON ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1001 S MECHANIC ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
107 E MARION ST		No	No	1890	1890	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
904 S BUCHANAN ST A		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
707 S BUCHANAN ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
807 S MARKET ST		No	No	1930	1930	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
105 E MITCHELL ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
106 ALLEN AVE		No	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No		No		
309 S BUCHANAN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
307 E THORN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
200 CAPRON ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
306 E THORN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
401 S BUCHANAN ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 S VIRGINIA AVE		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
904 S BUCHANAN ST B		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1201 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1110 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
714 S VIRGINIA AVE		No	No	1926	1926	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
716 S VIRGINIA AVE		No	No	1926	1926	Survey Response	Unknown	P	G	NL	N	N/R	No		No		
706 S VIRGINIA AVE		No	No	1926	1926	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
707 S VIRGINIA AVE		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
511 S MECHANIC ST		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
614 S VIRGINIA AVE		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 S VIRGINIA AVE		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
704 S VIRGINIA AVE	LP1C022	No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
703 S VIRGINIA AVE		No	No	1910	1910	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
302 E BOYTON ST B		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1208 S MECHANIC ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1207 S MECHANIC ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1402 S BUCHANAN ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1212 S MECHANIC ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
302 E BOYTON ST A		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
807 S VIRGINIA AVE #A		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
606 S VIRGINIA AVE		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
500 S MECHANIC ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
901 S VIRGINIA AVE		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1101 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
909 S BUCHANAN ST		No	No	1913	1913	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1105 S MECHANIC ST A		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1000 S BUCHANAN ST		No	No	1890	1890	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1003 S BUCHANAN ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1109 S BUCHANAN ST		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1106 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1007 S BUCHANAN ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
303 S MECHANIC ST		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
509 S MECHANIC ST		No	No	Unknown	Unknown	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
206 E WARDER ST		No	No	2020	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
411 E EVERETT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
513 S MECHANIC ST		No	No	2019	2023	Construction Records	Plastic	C	P	NL	N	N/R	No			No	
405 E MARION ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
304 E MARION ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
205 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1005 S MADISON ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
405 S BUCHANAN ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
506 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
807 S VIRGINIA AVE #B		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
605 E MERIDIAN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1011 S BUCHANAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
602 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
510 S BUCHANAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
307 E MARION ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1014 S MECHANIC ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
401 E ALLEN AVE		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
303 ALLEN AVE		No	No	1880	1880	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
303 S BUCHANAN ST		No	No	1920	1920	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
300 E THORN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1003 S MECHANIC ST B		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
907 S BUCHANAN ST		No	No	1915	1915	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
301 S MECHANIC ST		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
506 S VIRGINIA AVE		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
204 E MARION ST		No	No	1900	1900	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1013 S BUCHANAN ST		No	No	1935	1935	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
912 S VIRGINIA AVE		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
903 PARK DR #BATH		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1401 S BUCHANAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
203 E TEXAS AVE		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1409 S BUCHANAN ST		No	No	1969	1969	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1516 S BUCHANAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
202 CAPRON ST		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
508 S VIRGINIA AVE		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
405 E THORN ST		No	No	1910	1910	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
702 S MADISON ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
107 ALLEN AVE		No	No	1904	1904	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1305 S BUCHANAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1304 S BUCHANAN ST		No	No	1948	1948	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1403 S BUCHANAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
903 PARK DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
503 S BUCHANAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
903 S MADISON ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
504 S VIRGINIA AVE		No	No	1900	1900	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
514 S MECHANIC ST		No	No	1904	1904	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
600 S MECHANIC ST		No	No	1923	1923	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
1010 S MECHANIC ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1003 S MECHANIC ST A		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
802 S VIRGINIA AVE #B		No	No	1936	1936	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
710 S VIRGINIA AVE		No	No	1926	1926	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
610 S VIRGINIA AVE		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
913 S VIRGINIA AVE		No	No	1940	1940	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
712 S VIRGINIA AVE		No	No	1926	1926	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
708 S VIRGINIA AVE		No	No	1926	1926	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
613 E MERIDIAN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
604 E MERIDIAN ST B		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
601 E MERIDIAN ST		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
803 S VIRGINIA AVE		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
715 CIRCLE DR		No	No	1941	1941	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
614 E MERIDIAN ST		No	No	1941	1941	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
914 S VIRGINIA AVE		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1101 S MECHANIC ST		No	No	1930	1930	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
604 E MERIDIAN ST A		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
501 E MERIDIAN ST		No	No	1930	1930	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1111 S BUCHANAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
906 PARK DR		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 PARK DR		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
902 PARK DR		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
910 S VIRGINIA AVE		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
916 S VIRGINIA AVE		No	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1204 S BUCHANAN ST		No	No	2022	2022	Construction Records	Copper	C	P	NL	N	N/R	No		No		
607 E MERIDIAN ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
502 S VIRGINIA AVE		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
904 PARK DR		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1306 S BUCHANAN ST		No	No	1925	1925	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
1405 S BUCHANAN ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
508 PARISH AVE		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1308 S BUCHANAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
506 PARISH AVE		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
520 PARISH AVE		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1307 S BUCHANAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1205 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
917 S VIRGINIA AVE		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
900 PARK DR		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
501 S MECHANIC ST		No	No	2020	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
207 S MADISON ST B		No	No	1978	1978	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1200 S MECHANIC ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1211 S MECHANIC ST A		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1211 S MECHANIC ST B		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
518 PARISH AVE		No	No	1943	1943	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1300 S MECHANIC ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1411 S MECHANIC ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1416 S MECHANIC ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
516 PARISH AVE		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
510 S VIRGINIA AVE		No	No	1884	1884	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
910 PARK DR		No	No	1857	1857	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
802 S VIRGINIA AVE #A		No	No	1936	1936	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
615 E MERIDIAN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
713 S VIRGINIA AVE		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
909 S VIRGINIA AVE		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
911 S VIRGINIA AVE		No	No	1970	1970	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
801 S MARKET ST		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
110 ALLEN AVE		No	No	1915	1915	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
201 E MITCHELL ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
201 E MARION ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
404 E EVERETT ST #A-B		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 S MARKET ST		No	No	1940	1940	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
207 S MARKET ST		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
601 S MARKET ST "Empty Lot"		No	No	1900	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
400 E BOYTON ST B		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
400 E BOYTON ST A		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1205 S MADISON ST	LP1A047	No	Yes	2024	2024	Maintenance Records	Plastic	P	P	NL	Y	9/4/2024	Yes	9/17/2024	P	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
305 E MARION ST		No	No	1904	1904	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
406 E MARION ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
414 E MARION ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
502 BAINBRIDGE RD		No	No	2019	2019	Construction Records	Copper	C	P	NL	N	N/R	No		No		
502 COMFORT DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
110 S FIRST ST		No	No	1930	1930	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
302 S CARBON ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
600 HALFWAY RD		No	No	1969	1969	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
HALFWAY RD. KAY LOU TRAILER CT.		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2601 HENRY DR #SPRINK		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2601 HENRY DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
900 HALFWAY RD		No	No	1963	1963	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
110 S CARBON ST		No	No	1940	1940	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
103 S THIRD ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1805 W MAIN ST		No	No	1939	1939	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2603 W MAIN ST		No	No	1951	1951	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
104 S CARBON ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2604 W MAIN ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
2602 W MAIN ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2702 CREE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
305 POE DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
OLD RT 13 WEST/ RT 57 OFFRAMP		No	No	2009	2009	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
2600 WANDA DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
2601 W MAIN ST #SPRINK		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
601 HALFWAY RD		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2314 W MAIN ST #SPRINK		No	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No		No		
102 COMFORT DR #SPRIN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
204 HALFWAY RD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
442 COMFORT DR #SPRINK		Yes	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2602 WANDA DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
2713 MERCHANT ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2700 CREE DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2714 MERCHANT ST		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
605 HALFWAY RD		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
802 HALFWAY RD		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
700 HALFWAY RD		No	No	1964	1964	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
407 BAINBRIDGE RD		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
407 S SECOND ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
904 HALFWAY RD		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
702 HALFWAY RD		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
603 HALFWAY RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
903 HALFWAY RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2601 W MAIN ST # RV BARN		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2601 W MAIN ST #STABLES		No	No	1951	1951	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2707 W MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
204 HALFWAY RD #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2601 W MAIN ST #HOUSE		No	No	1969	1969	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
205 S SECOND ST		No	No	1956	1956	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
204 S SECOND ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2702 MERCHANT ST		No	No	1969	1969	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
401 S SECOND ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 S SECOND ST		No	No	1935	1935	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
316 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
107 S SECOND ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1903 W CHERRY ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
103 S SECOND ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
108 S FIRST ST		No	No	1940	1940	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
103 S FIRST ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
101 S FIRST ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
108 S FIRST ST #REAR		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
201 S SECOND ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
107 S FIRST ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
105 S FIRST ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2001 W MAIN ST		No	No	2019	1910	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
112 S FIRST ST		No	No	1930	1930	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
106 S FIRST ST		No	No	1940	1940	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
300 S SECOND ST		No	No	1942	1942	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
303 S SECOND ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2000 W MAPLE ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1904 W WALNUT ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
318 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
322 S SECOND ST		No	No	2024	2024	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
403 S SECOND ST		No	No	1945	1945	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
409 S SECOND ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
314 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
503 S SECOND ST		No	No	1945	1945	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
320 S SECOND ST		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
324 S SECOND ST		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
505 S SECOND ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
328 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
326 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
501 S SECOND ST		No	No	1950	1950	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
507 S SECOND ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
312 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
301 S THIRD ST		No	No	1940	1940	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
316 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
105 S THIRD ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2002 W CHERRY ST		No	No	1956	1956	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
304 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	P	G	NL	N	N/R	No			No	
203 S THIRD ST		No	No	1935	1935	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
202 S THIRD ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
302 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
308 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
404 BAINBRIDGE RD		No	No	1951	1951	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
2314 W MAIN ST		No	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No			No	
2700 W MAIN ST		No	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No			No	
2605 W MAIN ST #MAINT BLDG		No	No	1951	1951	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
324 S 4TH ST		No	No	1995	1995	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
515 S SECOND ST		No	No	1950	1950	Visual Inspection	Unknown	P	G	NL	N	N/R	No			No	
513 S SECOND ST		No	No	1942	1942	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
2306 W MAIN ST		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
330 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
334 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
332 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
321 S 4TH ST		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
511 S SECOND ST		No	No	1945	1945	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
408 BAINBRIDGE RD		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
202 S SECOND ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
104 S THIRD ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
108 S CARBON ST #A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2310 W MAIN ST		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
206 S SECOND ST		No	No	1930	1930	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		
104 S FIRST ST		No	No	1905	1905	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
109 S FIRST ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
306 S SECOND ST		No	No	2016	2016	Construction Records	Plastic	P	C	NL	N	N/R	No			No		
310 S SECOND ST		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
416 BAINBRIDGE RD		No	No	1953	1953	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No		
422 BAINBRIDGE RD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No		
106 S THIRD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
312 S SECOND ST		No	No	1942	1942	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No		
300 S THIRD ST		No	No	1942	1942	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No		
2600 HENRY DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
308 S THIRD ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
108 S CARBON ST #B		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
500 BAINBRIDGE RD		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
101 S THIRD ST A-B		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
515 BAINBRIDGE RD		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
513 BAINBRIDGE RD		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
406 CHARLOTTE RD		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
512 BAINBRIDGE RD		No	No	1953	1953	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
518 BAINBRIDGE RD		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No		
408 CHARLOTTE RD		No	No	1955	1955	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)					Copper - No Lead Solder (C)		
	Yes (Y) or No (N)					Examples:	Lead (L)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)		
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead Service Line was replaced.		
							Unknown (U)	Unknown (U)	Unknown (U)								
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
510 BAINBRIDGE RD		No	No	1953	1953	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
412 CHARLOTTE RD		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
413 CHARLOTTE RD		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
409 CHARLOTTE RD		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
507 BAINBRIDGE RD		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
417 CHARLOTTE RD		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
411 CHARLOTTE RD		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
415 CHARLOTTE RD		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
506 BAINBRIDGE RD		No	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
416 CHARLOTTE RD		No	No	1972	1972	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
414 CHARLOTTE RD		No	No	1958	1958	Visual Inspection	Unknown	G	G	NL	N	N/R	No			No	
418 CHARLOTTE RD		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
419 CHARLOTTE RD		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
508 BAINBRIDGE RD		No	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
511 BAINBRIDGE RD		No	No	1952	1952	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
503 BAINBRIDGE RD		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
509 BAINBRIDGE RD		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
501 BAINBRIDGE RD		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
412 BAINBRIDGE RD		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
410 BAINBRIDGE RD		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
406 BAINBRIDGE RD		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
419 BAINBRIDGE RD		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2309 W MAIN ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
420 BAINBRIDGE RD		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 BAINBRIDGE RD		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
414 BAINBRIDGE RD		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
418 BAINBRIDGE RD		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
504 BAINBRIDGE RD		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
400 BAINBRIDGE RD		No	No	1947	1947	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
409 BAINBRIDGE RD		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
417 BAINBRIDGE RD		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
413 BAINBRIDGE RD		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
415 BAINBRIDGE RD		No	No	1954	1954	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
421 BAINBRIDGE RD		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
402 BAINBRIDGE RD		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
410 CHARLOTTE RD		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
401 CHARLOTTE RD		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
403 CHARLOTTE RD		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 CHARLOTTE RD		No	No	1957	1957	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
402 CHARLOTTE RD		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
407 CHARLOTTE RD		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
404 CHARLOTTE RD		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
102 COMFORT DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2312 W MAIN ST		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
305 COMFORT DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2201 W MAIN ST		No	No	2024	2024	Construction Records	Copper	C	C	NL	N	N/R	No			No	
108 S CARBON ST #C		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
400 CHARLOTTE RD		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
902 S CARBON ST		No	No	1945	1945	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
108 S CARBON ST #D		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2708 MERCHANT ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2102 W CHERRY ST		No	No	1984	1984	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
307 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
327 S 4TH ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
313 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
310 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
309 S THIRD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
306 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
325 S 4TH ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
329 S 4TH ST		No	No	1951	1951	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
331 S 4TH ST		No	No	1954	1954	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
315 S 4TH ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
329 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
309 S 4TH ST		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
323 S 4TH ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
328 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
326 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...					If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
330 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
331 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
327 S THIRD ST		No	No	1943	1943	Maintenance Records	Copper	C	G	NL	N	N/R	No			No	
323 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
322 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
303 S 4TH ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
304 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
320 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
325 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
324 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
1807 W CHERRY ST		No	No	1950	1950	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1803 W CHERRY ST		No	No	1955	1955	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1805 W CHERRY ST		No	No	1952	1952	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1804 W CHERRY ST		No	No	1952	1952	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
305 S 4TH ST		No	No	1948	1948	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
315 S THIRD ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
319 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
332 S THIRD ST		No	No	1943	1943	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
334 S THIRD ST		No	No	1948	1948	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
335 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2104 W COPELAND ST		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
333 S THIRD ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
333 S 4TH ST		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
317 S THIRD ST		No	No	1948	1948	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
311 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
321 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
314 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
318 S THIRD ST		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2110 W CHERRY ST		No	No	1951	1951	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
301 S 4TH ST		No	No	1943	1943	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1811 W CHERRY ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
702 N CARBON ST		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
700 N CARBON ST		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1911 JULIANNE DR		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
111 S CARBON ST		No	No	1945	1945	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
1717 W CHERRY ST		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1705 TURNAGE LN		No	No	1956	1956	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1012 CASTELLANO AVE		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1706 TURNAGE LN		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1703 TURNAGE LN		No	No	1956	1956	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1010 CASTELLANO AVE		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1804 SUZANNE DR		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
403 S EISENHOWER DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
205 S BENTLEY ST #A		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1703 W CHESTNUT ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1903 W WARREN ST		No	No	1959	1959	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1804 JULIANNE DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1700 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1709 REDBUD LN		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1302 W END ST #B		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1302 W END ST #A		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
501 DOGWOOD LN #A		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1906 SUZANNE DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1911 SUZANNE DR		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1807 W WARREN ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1902 SUZANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1908 SUZANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1909 SUZANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 S CARBON ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1707 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1701 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1705 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1902 W WARREN ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1702 JULIANNE DR		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1900 W WARREN ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1808 WARREN ST		No	No	1958	1958	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1800 W WARREN ST		No	No	2024	1977	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1807 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1811 JULIANNE DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1813 JULIANNE DR		No	No	1964	1964	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1812 JULIANNE DR		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1806 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1809 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1901 JULIANNE DR		No	No	1963	1963	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1403 W CHERRY ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1712 W CHESTNUT ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1611 W CHESTNUT ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1707 W CHESTNUT ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1313 W CHERRY ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1603 W HENDRICKSON ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1402 W END ST		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1720 W COPELAND ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1709 W WALNUT ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1701 W CHESTNUT ST		No	No	1870	1870	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 ROBERTA DR #D		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1005 ROBERTA DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 ROBERTA DR #B		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1003 ROBERTA DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1014 CASTELLANO AVE		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1908 W WARREN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1805 JULIANNE DR		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1808 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1810 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1906 W WARREN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1905 W WARREN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 ROBERTA DR #C		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1007 ROBERTA DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1009 ROBERTA DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1909 W WARREN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1911 W WARREN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1907 W WARREN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1803 JULIANNE DR	LP1A053	No	No	1967	1967	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1302 W CHERRY ST #A		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1709 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1900 JULIANNE DR		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1910 W WARREN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1912 JULIANNE DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1910 JULIANNE DR		No	No	1971	1971	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1710 JULIANNE DR		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1907 JULIANNE DR		No	No	1969	1969	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1902 JULIANNE DR		No	No	1967	1967	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1903 JULIANNE DR		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1800 JULIANNE DR		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1802 JULIANNE DR		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1300 W CHESTNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1904 W WARREN ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1807 SUZANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1809 W COPELAND ST #1,2,7		No	No	1946	1946	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1809 W COPELAND ST #6		No	No	2024	1946	Maintenance Records	Copper	C	C	NL	N	N/R	No		No		
1711 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1713 JULIANNE DR		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1708 JULIANNE DR		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1305 W CHERRY ST		No	No	1936	1936	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1704 JULIANNE DR		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1706 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1013 ROBERTA DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1015 ROBERTA DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1008 ROBERTA DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1006 ROBERTA DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1015 CASTELLANO AVE		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1601 TURNAGE LN		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1905 JULIANNE DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1011 ROBERTA DR		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
618 S CARBON ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1903 SUZANNE DR		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1010 ROBERTA DR		No	No	1941	1941	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 ROBERTA DR #A		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
512 S CARBON ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1909 JULIANNE DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1904 JULIANNE DR		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1900 SUZANNE DR	LP1A055	No	No	1967	1967	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1906 JULIANNE DR		No	No	1963	1963	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1809 W COPELAND ST #5		No	No	1946	1946	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1809 W COPELAND ST #3		No	No	2024	1946	Maintenance Records	Copper	C	C	NL	N	N/R	No		No		
1006 CASTELLANO AVE		No	No	1960	1960	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1302 W CHERRY ST #B		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1811 SUZANNE DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1802 W WARREN ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1811 W WARREN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1809 W WARREN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1008 CASTELLANO AVE		No	No	1963	1963	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1408 W CHERRY ST		No	No	1925	1925	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1302 W END ST #D		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1805 W WARREN ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1806 W WARREN ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1804 W WARREN ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1901 W WARREN ST		No	No	1960	1960	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1303 W CHERRY ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1302 W END ST #C		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1405 W CHESTNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1601 W MAIN ST		Yes	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
300 S RUSSELL ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
302 S EISENHOWER DR		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
904 S CARBON ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1808 SUZANNE DR		No	No	1957	1957	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1805 SUZANNE DR		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1810 SUZANNE DR		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1806 SUZANNE DR		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1901 SUZANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1205 W CHERRY ST		No	No	1947	1947	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1302 W CHERRY ST #C		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
404 S FIRST ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
402 S FIRST ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
408 S FIRST ST		No	No	1932	1932	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
501 DOGWOOD LN #B		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1905 SUZANNE DR		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1803 W WARREN ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1907 SUZANNE DR		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1801 W WARREN ST	LP1A054	No	No	1960	1960	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1809 W COPELAND ST #4		No	No	1946	1946	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1809 SUZANNE DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1609 W MAIN ST #LOGAN GYM		Yes	No	1949	1949	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
107 S RUSSELL ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1208 W CHERRY ST #B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1208 W CHERRY ST #C		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1208 W CHERRY ST #A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1208 W CHERRY ST #D		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
205 S BENTLEY ST #B		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
406 S FIRST ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
505 S FIRST ST		No	No	1940	1940	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
420 SHERRY RD		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
418 SHERRY RD		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
421 SHERRY RD		No	No	1952	2023	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
422 SHERRY RD		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1009 CASTELLANO AVE		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1603 TURNAGE LN		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
413 SHERRY RD		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1605 TURNAGE LN		No	No	1956	1956	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
411 SHERRY RD		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
406 SHERRY RD		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
408 SHERRY RD		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1701 TURNAGE LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1607 TURNAGE LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
407 SHERRY RD		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
407 S FIRST ST		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
400 SHERRY RD		No	No	1945	1945	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1804 W WALNUT ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
409 SHERRY RD		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
404 SHERRY RD		No	No	1948	1948	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
416 SHERRY RD		No	No	1950	1950	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
512 S FIRST ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
403 SHERRY RD		No	No	1933	1933	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 S FIRST ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
506 S FIRST ST		No	No	1941	1941	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
508 S FIRST ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
509 S FIRST ST		No	No	1948	1948	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
507 S FIRST ST		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1007 CASTELLANO AVE		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
410 SHERRY RD		No	No	1933	1933	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
412 SHERRY RD		No	No	1933	1933	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
419 SHERRY RD		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
415 SHERRY RD		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
417 SHERRY RD		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 SHERRY RD		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1804 W COPELAND ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
402 SHERRY RD		No	No	1945	1945	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1901 W CHESTNUT ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
503 S FIRST ST		No	No	1967	1967	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
401 S FIRST ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
403 SHERRY RD #B		No	No	1955	1955	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
403 S FIRST ST		No	No	1955	1955	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
500 S FIRST ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
510 S FIRST ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
504 S FIRST ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
501 S FIRST ST		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
502 S FIRST ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1700 W CHERRY ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
414 SHERRY RD		No	No	1950	1950	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1300 W END ST #A		No	No	1964	1964	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1300 W END ST #C		No	No	1964	1964	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1910 SUZANNE DR		No	No	1956	1956	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1714 W CHESTNUT ST		No	No	1930	1930	Visual Inspection	Unknown	G	P	NL	N	N/R	No		No		
1404 W END ST #C		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1404 W END ST #D		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1804 W CHESTNUT ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1806 W CHESTNUT ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
501 S CARBON ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1708 W WALNUT ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1802 W CHESTNUT ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
411 S CARBON ST		No	No	1925	1925	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1404 W END ST #B		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1613 W CHERRY ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1711 W CHERRY ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1701 W CHERRY ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1309 W MAIN ST		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1204 W CHERRY ST #A		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1201 W CHERRY ST		No	No	1955	1955	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1204 W CHERRY ST #B		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1709 W CHESTNUT ST		No	No	1910	1910	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
425 SHERRY RD		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
113 S RUSSELL ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1505 W CHESTNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
809 S CARBON ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1400 W END ST #A		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1612 W WALNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1401 W END ST		No	No	1983	1983	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1316 W CHERRY ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1404 W END ST #A		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1618 W CHESTNUT ST		No	No	1962	1962	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1614 W CHESTNUT ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1615 W CHESTNUT ST		No	No	1950	1950	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1620 W CHESTNUT ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1616 W CHESTNUT ST		No	No	1903	1903	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1302 W CHERRY ST #D		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1613 W WALNUT ST #B		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1704 W WALNUT ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1300 W END ST #B		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1403 W END ST		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1613 W WALNUT ST #A		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1400 W END ST #B		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1710 W CHERRY ST		No	No	2005	2005	Visual Inspection	Lead	C	C	NL	N	N/R	No			No	
1714 W CHERRY ST		No	Yes	2024	2024	Maintenance Records	Plastic	P	P	NL	Y	9/4/2024	Yes	9/4/2024	P	No	
1709 W CHERRY ST		No	No	1935	1935	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
1707 W CHERRY ST		No	No	1910	1910	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1703 W CHERRY ST		No	No	1952	1952	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1702 W CHESTNUT ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1708 W CHESTNUT ST		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1705 W CHESTNUT ST		No	No	1900	1900	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
412 S CARBON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
500 S CARBON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1810 W CHESTNUT ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1808 W CHESTNUT ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1706 W CHESTNUT ST #A-B		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 W WALNUT ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1700 W WALNUT ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1706 W WALNUT ST		No	No	1955	1955	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1701 W WALNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1507 W CHESTNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1707 W WALNUT ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1705 W WALNUT ST		No	No	1950	1950	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1008 S CARBON ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1713 REDBUD LN		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1705 W HENDRICKSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1907 S FOSSE RD		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1604 CASTELBERY DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1611 EUGENE LN		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1711 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1709 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1702 CAROL DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1706 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1708 CAROL DR		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1704 CAROL DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1707 CAROL DR		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1622 EUGENE LN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
909 S RUSSELL ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1618 EUGENE LN		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1609 CASTELBERY DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1704 JOSEPHINE LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1815 WOLFF DR		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1701 S CAESAR LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1509 LISA LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1602 EUGENE LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1709 DALLAS LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1409 DANIELLE CT		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 W WALNUT ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1400 DANIELLE CT		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1401 DANIELLE CT		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1701 JOSEPHINE LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1607 CASTELBERY DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1704 CASTELBERY DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1203 FOSSE RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2202 STEEPLECHASE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1403 MARIONNA DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1302 CAMDEN CT		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1700 CASTELBERY DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1401 FOSSE RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1201 ABBY LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1811 WOLFF DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2000 S CARBON ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1801 TESTA DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1305 S CARBON ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1603 EUGENE LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1703 JOSEPHINE LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1713 CASTELBERY DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2200 BRENTWOOD DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1300 FOSSE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1705 CASTELBERY DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1405 DANIELLE CT		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1701 CASTELBERY DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2102 FOXBORO CT		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1613 EUGENE LN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1605 EUGENE LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1700 DALLAS LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1801 PAULA LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1710 DALLAS LN		No	No	2002	2002	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1606 CASTELBERY DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1404 DANIELLE CT		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1808 TESTA DR		No	No	1985	1985	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1505 W COPELAND ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1602 CARMIE LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1817 WOLFF DR		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1603 CARMIE LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1601 CARMIE LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2111 LERIN LN		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2205 BRENTWOOD DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2101 WINDSOR DR		No	No	2002	2002	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1808 PAULA LN		No	No	1982	1982	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1810 PAULA LN		No	No	1987	1987	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1408 W WALNUT ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1402 DANIELLE CT		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 NAGEL DR		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1600 SOUTH LAKE DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1609 SOUTH LAKE DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1611 SOUTH LAKE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1402 MARIONNA DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 CASTELBERY DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2001 S CARBON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1708 S DALLAS LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1703 CASTELBERY DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1603 S DALLAS LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1602 LISA LN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1600 LISA LN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1708 CASTELBERY DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1700 JOSEPHINE LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1601 S DALLAS LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1503 LISA LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1712 CASTLEBERRY DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1502 FOSSE RD		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 CASTELBERY DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2102 LERIN LN		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1810 TESTA DR		No	No	1984	1984	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1403 FOSSE RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1404 FOSSE RD		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2303 PAMELA DR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2302 PAMELA DR		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2207 KINGSPORTE DR #SPRIN		No	No	2019	2018	Construction Records	Plastic	P	C	NL	N	N/R	No			No	
1600 FOSSE RD		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2103 LERIN LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2302 W DOUGLAS DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2307 W DOUGLAS DR		No	No	1989	1989	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2207 KINGSPORTE DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1400 W HENDRICKSON ST		Yes	No	1949	1949	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1802 PAULA LN		No	No	1982	1982	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1800 PAULA LN		No	No	1995	1995	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1700 WILDCAT DR #SPRIN		No	No	2016	2016	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2205 KINGSPONTE DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2306 W DOUGLAS DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1503 BRYAN DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 BRYAN DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1510 BRYAN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1601 LISA LN		No	No	2001	2001	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 W JOSEPHINE LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2103 FOXBORO CT		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2101 FOXBORO CT		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1402 FOSSE RD		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2201 STEEPLECHASE DR		No	No	1993	1993	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2801 WESTMINSTER DR		No	No	1994	1994	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1400 FOSSE RD		No	No	1980	1980	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
2100 FOXBORO CT		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2201 WESTMINSTER DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 FOSSE RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 JOSEPHINE LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2208 KINGSPONTE DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
2102 WINDSOR DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2105 WINDSOR DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2201 KINGSPONTE DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
605 S AIKMAN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
801 DOGWOOD LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1600 W MAPLEWOOD ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
815 DOGWOOD LN		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
805 S RUSSELL ST #REAR		No	No	1951	1951	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1413 JULIANNE DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1417 JULIANNE DR		No	No	1961	1961	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1416 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1110 LAURA LN		No	No	1961	1961	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1600 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1602 JULIANNE DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1202 LAURA LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1201 JEFFREY LN	LP1A051	No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1605 SOUTH LAKE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1601 SOUTH LAKE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1202 FOSSE RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2311 FOREST CT		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1200 S CARBON ST		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1613 SOUTH LAKE DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1404 BRYAN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1502 BRYAN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2305 W DOUGLAS DR		No	No	1990	1990	Maintenance Records	Unknown/Not Lead	P	G	NL	N	N/R	No			No	
2604 WESTMINSTER DR		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1420 BRYAN DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2300 W DOUGLAS DR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
1300 CAMDEN CT		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1607 EUGENE LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 LISA LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2204 BRENTWOOD DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1600 EUGENE LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2204 BRENTWOOD DR #SPRINK		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2207 BRENTWOOD DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2203 BRENTWOOD DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2008 WESTMINSTER DR		No	No	1999	1999	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2200 BRENTWOOD DR #SPRINK		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2009 WESTMINSTER DR		No	No	1991	1991	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2111 WESTMINSTER DR		No	No	2005	2005	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1608 SOUTH LAKE DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1410 BRYAN DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1301 FOSSE RD		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1609 S CARBON ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1601 EUGENE LN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
1606 SOUTH LAKE DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1607 SOUTH LAKE DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 COLLINS LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1604 SOUTH LAKE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 COLLINS LN		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 CAMDEN CT		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 COLLINS LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 DALLAS LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 DALLAS LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1610 SOUTH LAKE DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1706 JOSEPHINE LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2209 STEEPLECHASE DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1504 FOSSE RD		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2104 LERIN LN		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2107 LERIN LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2203 STEEPLECHASE DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1602 SOUTH LAKE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1707 S CAESAR LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2203 WESTMINSTER DR		No	No	2005	2005	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2207 WESTMINSTER DR		No	No	2004	2004	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1603 SOUTH LAKE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2205 WESTMINSTER DR		No	No	2004	2004	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1615 SOUTH LAKE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1714 DALLAS LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1712 DALLAS LN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2201 BRENTWOOD DR # SPRIN		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2202 BRENTWOOD DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2201 BRENTWOOD DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2202 BRENTWOOD DR #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2209 WESTMINSTER DR		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1200 CAMBRIDGE CT		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1424 JULIANNE DR 3		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1422 JULIANNE DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1424 JULIANNE DR 6		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1421 JULIANNE DR		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1424 JULIANNE DR 4		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1424 JULIANNE DR 5		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1419 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1424 JULIANNE DR 2		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1420 JULIANNE DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1412 JULIANNE DR		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1414 JULIANNE DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
600 S RUSSELL ST #A		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
600 S RUSSELL ST #E		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
600 S RUSSELL ST #F		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
600 S RUSSELL ST #C		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
600 S RUSSELL ST #D		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
600 S RUSSELL ST #B		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1712 CAROL DR		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1809 WOLFF DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1812 WOLFF DR		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1816 WOLFF DR		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1818 WOLFF DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1804 WOLFF DR		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1807 WOLFF DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1814 WOLFF DR		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1803 WOLFF DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
2202 WESTMINSTER DR		No	No	1992	1992	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2200 WESTMINSTER DR		No	No	1989	1989	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2003 WESTMINSTER DR		No	No	1995	1995	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1202 ABBY LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1102 LAURA LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1107 LAURA LN		No	No	1959	1959	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1203 LAURA LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1507 BRYAN DR		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2105 LERIN LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1104 LAURA LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1006 LAURA LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1004 LAURA LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1702 W COPELAND ST		No	No	1955	1955	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
1501 NAGEL DR		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1303 S CARBON ST		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1817 TESTA DR		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2005 WESTMINSTER DR		No	No	1981	1981	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1815 TESTA DR		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1403 NAGEL DR		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1801 WESTMINSTER DR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1710 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1816 TESTA DR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1505 LISA LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1604 CARMIE LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1202 CAMBRIDGE CT		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1814 TESTA DR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1203 ABBY LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1809 TESTA DR		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1813 TESTA DR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1812 TESTA DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1805 TESTA DR		No	No	2023	1983	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1425 JULIANNE DR #28		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1807 TESTA DR		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1803 TESTA DR		No	No	2023	1988	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
2304 PAMELA DR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1604 EUGENE LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2109 LERIN LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1606 EUGENE LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1905 WESTMINSTER DR		No	No	2020	1991	Maintenance Records	Plastic	P	C	NL	N	N/R	No		No		
1805 WOLFF DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1304 HUNTERS RUN DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1803 PAULA LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2101 BRISTOL DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2101 LERIN LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1201 LAURA LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1500 BRYAN DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1201 FOSSE RD		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1309 FOSSE RD		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2207 STEEPLECHASE DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1402 BRYAN DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
2205 STEEPLECHASE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 FOSSE RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1423 JULIANNE DR 8		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
1302 LAURA LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1210 LAURA LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1209 LAURA LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1504 W MAPLEWOOD ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1304 LAURA LN		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1425 JULIANNE DR #29		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1400 NAGEL DR		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1817 PAULA LN		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1109 LAURA LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1810 WOLFF DR		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1404 NAGEL DR		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1205 CAMBRIDGE CT		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2001 WESTMINSTER DR		No	No	1990	1990	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1203 CAMBRIDGE CT		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1205 ABBY LN		No	No	1986	1986	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1200 LAURA LN		No	No	1962	1962	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1204 ABBY LN		No	No	1987	1987	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1811 TESTA DR		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1201 CAMBRIDGE CT		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1101 LAURA LN A		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1800 WOLFF DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1802 WOLFF DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1427 JULIANNE DR #22		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1808 WOLFF DR		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1804 PAULA LN		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1502 NAGEL DR		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1504 NAGEL DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1813 WOLFF DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1806 WOLFF DR		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1002 LAURA LN		No	No	1962	1962	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2209 BRENTWOOD DR #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2303 W DOUGLAS DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1300 COLLINS LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1608 SOUTH LAKE DR #SPRIN		No	No	2016	2016	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1427 JULIANNE DR #23		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1423 JULIANNE DR 7		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1705 S CAESAR LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1423 JULIANNE DR 10		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1427 JULIANNE DR #21		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1423 JULIANNE DR 11		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1805 PAULA LN		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1100 LAURA LN		No	No	1958	1958	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1108 LAURA LN		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1008 LAURA LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
1105 LAURA LN		No	No	1962	1962	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1101 LAURA LN B		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1001 LAURA LN	LP1A049	No	No	1958	1958	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1402 NAGEL DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1500 NAGEL DR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2100 WINDSOR DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2103 BRISTOL DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2104 BRISTOL DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2209 KINGSPOINTE DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2204 KINGSPOINTE DR		No	No	2010	2010	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2100 BRISTOL DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2208 BRENTWOOD DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1302 HUNTERS RUN DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2209 BRENTWOOD DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2105 BRISTOL DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2206 BRENTWOOD DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1804 TESTA DR		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
2102 BRISTOL DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2103 WINDSOR DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2309 W DOUGLAS DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1812 PAULA LN		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1813 PAULA LN		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1809 PAULA LN		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
Yes (Y) or No (N)		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)	Copper - Lead Solder (CLS)							
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)	Galvanized (G)							
Yes (Y) or No (N)		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)	Lead (L)							
		Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...					Lead (L)	Lead (L)		Cast/Ductile Iron or Transite (O)							
							Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)		Plastic - PVC, HDPE, PEX (P)												
Unknown (U)	Unknown (U)	Unknown (U)		Unknown (U)													
Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)		Unknown Not Lead (UNL)													
1819 PAULA LN		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1806 PAULA LN		No	No	1982	1982	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1818 PAULA LN		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1814 PAULA LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1816 PAULA LN		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1811 PAULA LN		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1901 PAULA LN		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1815 PAULA LN		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1502 LISA LN		No	No	1995	1995	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1903 WESTMINSTER DR		No	No	1991	1991	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1603 LISA LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1800 TESTA DR		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1802 TESTA DR		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1807 PAULA LN		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1205 LAURA LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1207 LAURA LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1504 LISA LN		No	No	1994	1994	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1200 ABBY LN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
801 S RUSSELL ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
803 S RUSSELL ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1309 RITCHEY DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1307 RITCHEY DR	LP1A050	No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1206 LAURA LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1204 LAURA LN		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1211 LAURA LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1213 LAURA LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1602 W COPELAND ST #C		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1106 LAURA LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1303 RITCHEY DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1305 RITCHEY DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1208 LAURA LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1200 FOSSE RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1427 JULIANNE DR #25		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1322 RITCHEY DR		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1321 RITCHEY DR		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1326 RITCHEY DR		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1315 RITCHEY DR		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1320 RITCHEY DR		No	No	2024	1981	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
1323 RITCHEY DR		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1313 RITCHEY DR		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1324 RITCHEY DR		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1325 RITCHEY DR		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1319 RITCHEY DR		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1329 RITCHEY DR		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1317 RITCHEY DR		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1616 EUGENE LN		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1700 WILDCAT DR		Yes	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1425 JULIANNE DR #27		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1700 WILDCAT DR #CAFETERIA		No	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2205 BRENTWOOD DR #SPRINK		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1327 RITCHEY DR		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1705 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1700 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1703 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1202 JEFFREY LN		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1603 CAROL DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1601 CAROL DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1704 W MAPLEWOOD ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1605 CAROL DR		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1701 CAROL DR	LP1A052	No	No	1967	1967	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1203 JEFFREY LN		No	No	1961	1961	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2205 KINGSPONTE DR #SPRIN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1705 REDBUD LN		No	No	1977	1977	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2100 LERIN LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1510 W COPELAND ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 FOSSE RD #SPRINK		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1713 CAROL DR		No	No	1965	1965	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
2207 BRENTWOOD DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1507 LISA LN		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1703 S CAESAR LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 W COPELAND ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1704 W COPELAND ST		No	No	1955	1955	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1601 W MAPLEWOOD ST		No	No	1958	1958	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1604 W WALNUT ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1604 W COPELAND ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1607 W COPELAND ST		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1603 W COPELAND ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1602 W COPELAND ST #A		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
604 S FOZZARD ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1701 W COPELAND ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1602 W WALNUT ST		No	No	1962	1962	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1506 W WALNUT ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1507 W WALNUT ST		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1425 JULIANNE DR #26		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1505 W MAPLEWOOD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
602 S RUSSELL ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1500 W MAPLEWOOD ST		No	No	1939	1939	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
505 S FOZZARD ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
507 S FOZZARD ST		No	No	1955	1955	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
508 S FOZZARD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
603 S FOZZARD ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
504 S FOZZARD ST		No	No	1962	1962	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1601 W COPELAND ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1606 W MAPLEWOOD ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1609 W COPELAND ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1700 W COPELAND ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1706 W COPELAND ST		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1718 W COPELAND ST		No	No	1959	1959	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1703 W COPELAND ST #REAR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1602 W COPELAND ST #B		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1604 W MAPLEWOOD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1602 W COPELAND ST #D		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
501 S DAYTON ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1601 W WALNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1603 W MAPLEWOOD ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
605 S FOZZARD ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1506 W COPELAND ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1719 W COPELAND ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1721 W COPELAND ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1507 W MAPLEWOOD ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
500 S DAYTON ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1509 W COPELAND ST #A		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1509 W COPELAND ST #B		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1512 BROWN LN		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1505 BROWN LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1502 BROWN LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1504 BROWN LN		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
809 DOGWOOD LN		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1700 REDBUD LN		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1508 BROWN LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1300 W WALNUT ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
811 DOGWOOD LN		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
707 DOGWOOD LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
800 DOGWOOD LN		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1511 BROWN LN		No	No	1960	1960	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
1503 BROWN LN		No	No	1959	1959	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1510 BROWN LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
813 DOGWOOD LN		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
802 DOGWOOD LN		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1700 W MAPLEWOOD ST		No	No	1940	1940	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
1607 W MAPLEWOOD ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1705 W MAPLEWOOD ST		No	No	1965	1965	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
1501 W MAPLEWOOD ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
1709 W MAPLEWOOD ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1605 W MAPLEWOOD ST		No	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
806 DOGWOOD LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
808 DOGWOOD LN		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1509 BROWN LN		No	No	1959	1959	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
805 DOGWOOD LN		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
705 DOGWOOD LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1507 BROWN LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
803 DOGWOOD LN		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
607 S CARBON ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
805 S RUSSELL ST		No	No	1951	1951	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1506 W MALDEN ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1707 REDBUD LN		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1702 REDBUD LN		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1712 REDBUD LN		No	No	1972	1972	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1701 REDBUD LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
812 DOGWOOD LN		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1502 W MALDEN ST		No	No	1958	1958	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
703 DOGWOOD LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1504 W MALDEN ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1710 REDBUD LN		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1508 W MALDEN ST		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1706 W MAPLEWOOD ST		No	No	1949	1949	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1711 W MAPLEWOOD ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1718 W MAPLEWOOD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1717 W MAPLEWOOD ST		No	No	1930	1930	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1402 W MAPLEWOOD ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1108 W HENDRICKSON ST		No	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1300 W CONCORD ST "Empty lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
907 S EISENHOWER DR		No	No	1963	1963	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1218 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1205 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
912 S DUNCAN ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1300 BEVABECK DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1008 S VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1110 MIDWAY CT "Empty Lot"		No	No	1945	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1317 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1204 MIDWAY CT		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1119 MIDWAY CT		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1204 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1115 MIDWAY CT #B "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1209 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1325 W HENDRICKSON ST		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1108 MIDWAY CT "Empty Lot"		No	No	1945	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1013 S DUNCAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1124 MIDWAY CT "Empty Lot"		No	No	1942	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1216 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1240 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1139 MIDWAY CT #C & D "Empty Lot"		No	No	1994	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No		
1139 MIDWAY CT #A & B "Empty Lot"		No	No	1994	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No		
1125 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1130 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1132 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1001 MIDWAY CT		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1146 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1134 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1101 MIDWAY CT #A "Empty Lot"		No	No	1999	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No		
1010 MIDWAY CT		No	No	1941	1941	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1014 S VICKSBURG ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1206 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1219 W HENDRICKSON ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1200 MIDWAY CT		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1118 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1301 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1215 MIDWAY CT "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1217 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1228 MIDWAY CT "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
1224 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1211 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1144 MIDWAY CT		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1129 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1238 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1310 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1205 MIDWAY CT		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1206 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1137 MIDWAY CT #C & D "Empty Lot"		No	No	1994	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No	
1107 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1210 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1010 S VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1008 MIDWAY CT		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1128 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1137 MIDWAY CT A-B "Empty Lot"		No	No	1994	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No	
1220 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1012 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1117 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1121 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1143 MIDWAY CT #C & D "Empty Lot"		No	No	1994	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No	
1203 MIDWAY CT		No	No	1946	1946	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1006 MIDWAY CT		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
1222 MIDWAY CT		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1218 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1308 W CONCORD ST		No	No	1941	1941	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1312 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1244 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1314 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1004 MIDWAY CT		No	No	1945	1945	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1112 W CONCORD ST		No	No	1941	1941	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1138 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1101 MIDWAY CT #B "Empty Lot"		No	No	1999	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No	
1143 MIDWAY CT #A & B "Empty Lot"		No	No	1994	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No	
1219 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1100 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1207 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1154 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1011 S DUNCAN ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1304 W CONCORD ST "Empty Lot"		No	No	1942	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1007 S DUNCAN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1250 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1202 MIDWAY CT		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1306 W CONCORD ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1231 MIDWAY CT		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1229 MIDWAY CT		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1233 MIDWAY CT "Empty Lot"		No	No	1957	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1012 S DUNCAN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1221 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1234 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1100 S DUNCAN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1102 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1236 MIDWAY CT		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1003 MIDWAY CT "Empty Lot"		No	No	1945	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1140 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1203 W HENDRICKSON ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1315 W CONCORD ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1014 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1109 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1148 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1158 MIDWAY CT		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1103 W HENDRICKSON ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1009 S DUNCAN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1246 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1242 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1215 W CONCORD ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1205 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Galvanized Requiring Replacement (GRR) Unknown (U) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1317 W CONCORD ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1201 W HENDRICKSON ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1105 W HENDRICKSON ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
909 S AIKMAN ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1305 W HENDRICKSON ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1000 MIDWAY CT		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1116 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1214 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1015 S DUNCAN ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1208 W CONCORD ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1114 MIDWAY CT		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1111 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1112 MIDWAY CT		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1209 W HENDRICKSON ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1106 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1100 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1232 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1001 S DUNCAN ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1102 S DUNCAN ST		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
709 S BENTLEY ST		No	No	1943	1943	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1226 MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1102 MIDWAY CT "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
1101 W CHERRY ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1003 S DUNCAN ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1005 S DUNCAN ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
802 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1211 W HENDRICKSON ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1207 W HENDRICKSON ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1109 MIDWAY CT F		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1007 W MALDEN ST		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
909 S BENTLEY ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 S BENTLEY ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1200 W HENDRICKSON ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1009 MIDWAY CT "Empty Lot"		No	No	1950	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1109 MIDWAY CT #A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1300 W HENDRICKSON ST		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1109 MIDWAY CT #B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1109 MIDWAY CT #D		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1109 MIDWAY CT #E		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
710 S BENTLEY ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1008 W CHESTNUT ST		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1010 W CHESTNUT ST		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
406 S BENTLEY ST		No	No	1918	1918	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
714 S DUNCAN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
800 S DUNCAN ST		No	No	1921	1921	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
710 S AIKMAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1109 MIDWAY CT #C		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
707 S EISENHOWER DR		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1218 BEVABECK DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1214 BEVABECK DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1203 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
909 S EISENHOWER DR		No	No	1977	1977	Maintenance Records	Unknown	C	CLS	NL	N	N/R	No		No		
908 S EISENHOWER DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1201 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
910 S EISENHOWER DR		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1217 BEVABECK DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1200 S DUNCAN ST		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1219 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1216 S DUNCAN ST		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1300 HEMLOCK DR		No	No	1971	1971	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1310 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1217 S DUNCAN ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1308 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1214 S DUNCAN ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
504 S BENTLEY ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1000 S VICKSBURG ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)									
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
	Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)														
	Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)														
		Unknown Not Lead (UNL)	Unknown Not Lead (UNL)														
1006 S VICKSBURG ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
310 S DUNCAN ST		No	No	1900	1900	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
1213 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1211 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1210 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1206 BEVABECK DR		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1204 BEVABECK DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1212 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1207 BEVABECK DR		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1213 BEVABECK DR		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1215 S DUNCAN ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1208 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1205 S DUNCAN ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1209 S DUNCAN ST		No	No	1960	1960	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1204 S DUNCAN ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1202 S DUNCAN ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1306 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1307 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1303 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1304 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1305 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1206 S DUNCAN ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1207 S DUNCAN ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1200 BEVABECK DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1202 BEVABECK DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1302 HEMLOCK DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1216 BEVABECK DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1203 BEVABECK DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1201 BEVABECK DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1300 S DUNCAN ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
906 S EISENHOWER DR		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
903 S EISENHOWER DR		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1400 W MALDEN ST		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
901 S EISENHOWER DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
900 S EISENHOWER DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1211 BEVABECK DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1212 BEVABECK DR		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1209 BEVABECK DR		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1215 BEVABECK DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1205 BEVABECK DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1210 BEVABECK DR		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1200 W PRAIRIE ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1208 BEVABECK DR		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1307 W HENDRICKSON ST "Empty Lot"		No	No	1941	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1209 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1313 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1207 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1309 W HENDRICKSON ST "Empty Lot"		No	No	1941	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No	No	
1107 S DUNCAN ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1304 W MALDEN ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No	No	
1002 S VICKSBURG ST "Empty Lot"		No	No	1941	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No	No	
1101 S DUNCAN ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1007 W CHESTNUT ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
801 S BENTLEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
804 S AIKMAN ST		No	No	1936	1936	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
1010 W MAPLEWOOD ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
801 S AIKMAN ST		No	No	1915	1915	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
800 S AIKMAN ST		No	No	2018	2018	Construction Records	Copper	C	P	NL	N	N/R	No		No	No	
800 S BENTLEY ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
1400 W MAPLEWOOD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
711 S AIKMAN ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
800 S EISENHOWER DR		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
801 S EISENHOWER DR		No	No	1948	1948	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
1009 W MAPLEWOOD ST		No	No	1895	1895	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
1302 W MAPLEWOOD ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
404 S SPILLMAN ST F		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
909 W PRAIRIE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
930 W CHERRY ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
914 W CHESTNUT ST		No	No	1910	1910	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
404 S SPILLMAN ST E		No	No	1997	1997	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
918 W CHESTNUT ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1006 W CHERRY ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
914 W WALNUT ST C		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
914 W WALNUT ST D		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
908 W PRAIRIE ST		No	No	1935	1935	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
806 W CHERRY ST		No	No	1935	1935	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
415 S SPILLMAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
908 S COURT ST #LAUNDRY		No	No	1989	1989	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1001 W MAIN ST		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
917 W MAIN ST #HUB		No	No	2004	2004	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
907 W CHERRY ST F		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
907 W CHERRY ST B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
907 W CHERRY ST C		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
907 W CHERRY ST E		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
907 W CHERRY ST A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
907 W CHERRY ST D		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
208 S COURT ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 S VICKSBURG ST		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
907 W CHERRY ST F REAR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
907 W CHERRY ST A REAR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
917 W CHERRY ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
410 S VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
502 S SPILLMAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
108 S VICKSBURG ST #1-10		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
905 W MAIN ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
909 S VICKSBURG ST		No	No	1945	1945	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
409 S COURT ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
403 S VICKSBURG ST D		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
403 S VICKSBURG ST F		No	No	1996	1996	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
915 W CHESTNUT ST F		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
403 S VICKSBURG ST E		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
915 W CHESTNUT ST C		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
903 S VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
403 S VICKSBURG ST A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
803 S VICKSBURG ST #A&B		No	No	1920	1920	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
506 S VICKSBURG ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
310 S VICKSBURG ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
110 S VICKSBURG ST		No	No	1890	1890	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
403 S VICKSBURG ST B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
403 S VICKSBURG ST C		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
318 S VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
411 S SPILLMAN ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
915 W CHESTNUT ST A		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
309 S VICKSBURG ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
417 S SPILLMAN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
501 S SPILLMAN ST		No	No	1870	1870	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
915 W CHESTNUT ST B		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
504 S SPILLMAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
414 S VICKSBURG ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1003 W CHERRY ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1101 W MAIN ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
106 S VICKSBURG ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
915 W CHESTNUT ST E		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
915 W CHESTNUT ST D		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
805 S VICKSBURG ST #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
805 S VICKSBURG ST #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
805 S VICKSBURG ST #C		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
805 S VICKSBURG ST #D		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
910 W PRAIRIE ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
905 S VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
907 S VICKSBURG ST		No	No	1947	1947	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1000 W MALDEN ST		No	No	1969	1969	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
901 S VICKSBURG ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
807 S VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
804 S VICKSBURG ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
902 S VICKSBURG ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
900 S VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
114 S VICKSBURG ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
406 S VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
112 S VICKSBURG ST		No	No	2013	2013	Construction Records	Copper	C	P	NL	N	N/R	No		No		
312 S VICKSBURG ST		No	No	1970	1970	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
602 S VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
706 S VICKSBURG ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
505 S VICKSBURG ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
604 S VICKSBURG ST		No	No	1951	1951	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
700 S VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 S VICKSBURG ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
601 S VICKSBURG ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
501 S VICKSBURG ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
708 S VICKSBURG ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1001 W MAPLEWOOD ST #B		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
802 S VICKSBURG ST		No	No	1885	1885	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1001 W MAPLEWOOD ST #A		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 W MAPLEWOOD ST #C		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 W MAPLEWOOD ST #D		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
308 S COURT ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
911 W MAPLEWOOD ST		No	No	1928	1928	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
902 W MAPLEWOOD ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
914 W MAPLEWOOD ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
910 W MAPLEWOOD ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
901 W MAPLEWOOD ST 1-4		No	No	1957	1957	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
406 S MARKET ST #1-4		No	No	2017	1870	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
402 S MARKET ST		No	No	2017	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1101 S COURT ST		No	No	1948	1948	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
514 W GENT ST A		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No		No		
203 S MONROE ST #A		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
203 S MONROE ST #B		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
800 TOWER SQUARE PLAZA		No	No	2023	1997	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
401 W BOYTON ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1204 S VICKSBURG ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
409 W BURNETT ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
817 W LEXINGTON ST #3		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
817 W CONCORD ST		No	No	1935	1935	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
817 W LEXINGTON ST #4		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
817 W LEXINGTON ST #2		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1205 S VICKSBURG ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
703 W MAIN ST		No	No	2003	2003	Visual Inspection	Lead	C	C	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
522 S MARKET ST		No	No	2017	1890	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1008 S HOLLAND ST		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
811 W LEXINGTON ST		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
502 S MARKET ST		No	No	2017	1890	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
516 S MARKET ST #A		No	No	2017	1900	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
512 S MARKET ST		No	No	2017	1890	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
508 S MARKET ST		No	No	2017	1900	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
516 S MARKET ST #B		No	No	2017	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
812 W CONCORD ST		No	No	1924	1924	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
913 BOSTON AVE		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
911 BOSTON AVE		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
813 W CONCORD ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
515 W GENT ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
815 W LEXINGTON ST		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
514 W GENT ST B		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No		No		
520 S MARKET ST		No	No	2017	1902	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
302 S MARKET ST		No	No	2017	1938	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
304 S MARKET ST		No	No	2017	1959	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
306 S MARKET ST		No	No	2017	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1102 S HOLLAND ST "Empty Lot"		No	No	1986	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
504 S MARKET ST		No	No	2017	1960	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
909 W HENDRICKSON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
914 BOSTON AVE		No	No	2014	2014	Construction Records	Copper	C	P	NL	N	N/R	No			No	
910 W HENDRICKSON ST		No	No	1949	1949	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
817 W HENDRICKSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
815 W HENDRICKSON ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
518 S MARKET ST		No	No	2017	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
813 W LEXINGTON ST		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
707 S HOLLAND ST		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1316 S VAN BUREN ST #LOADING DOCK		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
907 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
905 W HENDRICKSON ST		No	No	1958	1958	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
901 W HENDRICKSON ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
704 W BOYTON ST		No	No	1950	1950	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
906 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
803 W HENDRICKSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
903 W CONCORD ST		No	No	1949	1949	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
816 W CONCORD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
902 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
900 W CONCORD ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
818 W CONCORD ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
904 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
821 W CONCORD ST		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
901 W CONCORD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
707 W MAIN ST		No	No	2003	2003	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
1321 S VAN BUREN ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
801 W MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1220 S COURT ST		No	No	1970	1970	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
905 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
907 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
812 W LEXINGTON ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
910 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
909 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
911 W CONCORD ST		No	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
808 W LEXINGTON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
900 BOSTON AVE		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 W CONCORD ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
906 W CONCORD ST		No	No	1952	1952	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
407 S VAN BUREN ST		No	No	1930	1930	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
500 W SIMMONS ST A-D		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
500 S MONROE ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
201 HARTWELL ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
304 S VAN BUREN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
514 S MARKET ST		No	No	2017	1969	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
908 W HENDRICKSON ST #A-F		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
506 W COPELAND ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
507 W COPELAND ST		No	No	1930	1930	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1202 S VICKSBURG ST		No	No	1955	1955	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1110 S VICKSBURG ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1108 S VICKSBURG ST		No	No	1966	1966	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
807 W LEXINGTON ST		No	No	1954	1954	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1200 S VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
809 W LEXINGTON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
812 W HENDRICKSON ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
808 W HENDRICKSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
811 W HENDRICKSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
802 W HENDRICKSON ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
806 W HENDRICKSON ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
904 W HENDRICKSON ST		No	No	1942	1942	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
810 W HENDRICKSON ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
902 W HENDRICKSON ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
909 BOSTON AVE		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
912 BOSTON AVE		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
814 W LEXINGTON ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
816 W LEXINGTON ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
903 BOSTON AVE		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
901 BOSTON AVE		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
904 BOSTON AVE		No	No	1953	1953	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
905 BOSTON AVE		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1222 S COURT ST		No	No	1989	1989	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
805 S LIBERTY ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
906 BOSTON AVE		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
105 S LIBERTY ST G		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
105 S LIBERTY ST D		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
105 S LIBERTY ST C		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
105 S LIBERTY ST F		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
105 S LIBERTY ST B		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
108 S MONROE ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
411 S VAN BUREN ST		No	No	1958	1958	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
308 S LIBERTY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
301 W COLLEGE ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
203 S LIBERTY ST		No	No	1915	1915	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
105 S LIBERTY ST A		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
208 W COLLEGE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
105 S LIBERTY ST E		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1204 S VAN BUREN ST		No	No	1968	1968	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1109 S COURT ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
407 S LIBERTY ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1208 S COURT ST "Empty Lot"		No	No	1945	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
1100 S VAN BUREN ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
112 W BOYTON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
910 BOSTON AVE		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1302 S COURT ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1316 S VAN BUREN ST		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
701 S MARKET		No	No	2018	2018	Construction Records	Plastic	P	C	NL	N	N/R	No		No		
1001 S COURT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
709 W MAIN ST		No	No	2003	2003	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
1305 S COURT ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1316 S VAN BUREN ST #DOG POUND		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
204 S MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
206 S MARKET ST	LP1C014	No	No	2017	1916	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1305 S MONROE ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
902 BOSTON AVE		No	No	1950	1950	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
507 W MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1225 S COURT ST		No	No	1915	1915	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
817 W LEXINGTON ST #1		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1108 S COURT ST		No	No	1906	1906	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1308 S VAN BUREN ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1004 S COURT ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1100 S COURT ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1006 S COURT ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1002 S COURT ST		No	No	1923	1923	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1007 S LIBERTY ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1100 S LIBERTY ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
905 S LIBERTY ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
601 W BOYTON ST		No	No	2024	1930	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1300 S COURT ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
502 W BOYTON ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
501 W DAVIS ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
200 W BOYTON ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
501 W BOYTON ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1309 S LIBERTY ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 S LIBERTY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
202 W BOYTON ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
111 W BOYTON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1305 S LIBERTY ST		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
514 1/2 W SIMMONS ST "Empty Lot"		No	No	1950	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1104 S COURT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1202 S COURT ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1105 S COURT ST		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1210 S COURT ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1201 S COURT ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
503 W COPELAND ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1007 S COURT ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
300 W COLLEGE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
110 BOSWELL RD		No	No	1968	1968	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
109 BOSWELL RD		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3202 ZELLER AVE #F		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3202 JAMIE AVE C		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 JAMIE AVE A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3202 JAMIE AVE B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3202 JAMIE AVE D		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 JAMIE AVE B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3202 JAMIE AVE A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
105 N PLAINS AVE		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3201 JAMIE AVE D		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 JAMIE AVE H		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 JAMIE AVE C		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 JAMIE AVE G		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 JAMIE AVE F		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
303 LINGALE AVE		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3201 JAMIE AVE E		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
602 WHIPPOORWILL LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
600 WHIPPOORWILL LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
603 WHIPPOORWILL LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3207 MARK TWAIN AVE #B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
652 LAKE HARBOR DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
500 WHIPPOORWILL LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
617 SALUKI DR N		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
613 SALUKI DR N		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3205 MARK TWAIN AVE #A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
656 LAKE HARBOR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
659 LAKE HARBOR DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3215 MARK TWAIN AVE #B		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3309 SUNSET TERRACE		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3217 MARK TWAIN AVE #A		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3215 MARK TWAIN AVE #A		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 ZELLER AVE #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
651 LAKE HARBOR DR		No	No	2006	2006	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
645 LAKE HARBOR DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
655 LAKE HARBOR DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
3209 MARK TWAIN AVE #A		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
603 SKYLINE DR #B		No	No	1979	1979	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
608 LAKE HARBOR DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3309 W HAWTHORNE CT		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
604 WHIPPOORWILL LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
713 N SALUKI DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3209 MARK TWAIN AVE #B		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
610 LAKE HARBOR DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)					Copper - Lead Solder (CLS)		
		Yes (Y) or No (N)				Examples:	Lead (L)	Lead (L)	Lead (L)	Non-Lead (NL)				Plastic - PVC, HDPE, PEX (P)			
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead Service Line was replaced.		
							Unknown (U)	Unknown (U)	Unknown (U)								
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
3202 JAMIE AVE F		No	No	2005	2005	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 JAMIE AVE E		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
638 LAKE HARBOR DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3004 OAK CT		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
607 SALUKI DR N		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
609 SALUKI DR N		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
641 LAKE HARBOR DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 JAMIE AVE G		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
639 LAKE HARBOR DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
615 LAKE HARBOR DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
658 LAKE HARBOR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
657 LAKE HARBOR DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3211 MARK TWAIN AVE #A		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3211 MARK TWAIN AVE #B		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
603 SALUKI DR N		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
111 N CHAMBERLAIN DR		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
114 N CHAMBERLAIN DR		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
661 LAKE HARBOR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
653 LAKE HARBOR DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
708 SALUKI DR N		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
611 SALUKI DR N		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
715 SALUKI DR N		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
615 SALUKI DR N		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2720 W MAIN ST #A-C		No	No	2017	2017	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3307 W HAWTHORNE CT		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
103 LINGALE AVE #A		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
3217 MARK TWAIN AVE #B		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3213 MARK TWAIN AVE #B		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
606 LAKE HARBOR DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3214 MARK TWAIN AVE #B		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
613 LAKE HARBOR DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
654 LAKE HARBOR DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
707 SALUKI DR N		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3207 MARK TWAIN AVE #A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
712 SALUKI DR N		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
619 SALUKI DR N		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
701 SALUKI DR N		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
702 SALUKI DR N		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
506 WHIPPOORWILL LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 SUNSET TERRACE		No	No	1969	1969	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
103 LINGALE AVE #B		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
2800 W MAIN ST		No	No	2016	2016	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
3205 MARK TWAIN AVE #B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3208 MARK TWAIN AVE #A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
633 LAKE HARBOR DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)					Copper - No Lead Solder (C)		
		Yes (Y) or No (N)				Examples:	Lead (L)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)		
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead Service Line was replaced.		
							Unknown (U)	Unknown (U)	Unknown (U)								
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
643 LAKE HARBOR DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
647 LAKE HARBOR DR		No	No	2000	2000	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2805 W MAIN ST		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3202 W MAIN ST #A-B		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
113 N PLAINS AVE		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
601 SALUKI DR N		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
600 LAKE HARBOR DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
102 N CHAMBERLAIN DR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3307 W LAKEVIEW RD		No	No	1977	1977	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
109 N PLAINS AVE		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3310 W LAKEVIEW RD		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3309 W LAKEVIEW RD		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
103 N CHAMBERLAIN DR		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
111 N PLAINS AVE		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3202 MARK TWAIN AVE #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3308 W LAKEVIEW RD		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
3304 W LAKEVIEW RD		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
100 N CHAMBERLAIN DR		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
105 N CHAMBERLAIN DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
3302 W LAKEVIEW RD		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3305 W LAKEVIEW RD		No	No	1977	1977	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
106 N CHAMBERLAIN DR		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
107 N PLAINS AVE		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
640 LAKE HARBOR DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3202 ZELLER AVE #G		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3006 CLIFTON CT		No	No	1979	1979	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
703 SALUKI DR N		No	No	1997	1997	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
606 SALUKI DR N		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2901 MEADOW CT		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3003 OAK CT		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
623 LAKE HARBOR DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3210 MARK TWAIN AVE #A		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3212 MARK TWAIN AVE #B		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
603 SKYLINE DR #A		No	No	1979	1979	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
711 SALUKI DR N		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
629 LAKE HARBOR DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
705 SALUKI DR N		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3202 ZELLER AVE #E		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3203 ZELLER AVE #C		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3104 W WOODLAWN PL		No	No	1963	1963	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
611 LAKE HARBOR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3203 ZELLER AVE #J		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
601 LAKE HARBOR DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
704 SALUKI DR N		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
101 SKYLINE DR		No	No	1890	1890	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)					Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)		
3200 MARK TWAIN AVE #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
210 WESTERNAIRE DR		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
3311 W HAWTHORNE CT		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3308 W HAWTHORNE CT		No	No	1978	1978	Maintenance Records	Unknown	P	CLS	NL	N	N/R	No		No		
3200 MARK TWAIN AVE #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3202 MARK TWAIN AVE #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3107 W LAKEVIEW RD		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
117 N PLAINS AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
103 SKYLINE DR		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
100 SKYLINE DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3110 W LAKEVIEW RD		No	No	1969	1969	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3306 W HAWTHORNE CT		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
507 WHIPPOORWILL LN		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
502 WHIPPOORWILL LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2905 MEADOW CT		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
504 WHIPPOORWILL LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
116 N CHAMBERLAIN DR		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
601 WHIPPOORWILL LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
3104 W LAKEVIEW RD		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3203 MARK TWAIN AVE #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3106 W LAKEVIEW RD		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
605 SALUKI DR N		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
606 WHIPPOORWILL LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
508 WHIPPOORWILL LN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
609 LAKE HARBOR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #F		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
621 LAKE HARBOR DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3210 MARK TWAIN AVE #B		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
607 LAKE HARBOR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
627 LAKE HARBOR DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
602 LAKE HARBOR DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3206 MARK TWAIN AVE #B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3208 MARK TWAIN AVE #B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
603 SKYLINE DR #D		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3206 MARK TWAIN AVE #A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #E		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #D		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3005 OAK CT		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
614 SALUKI DR N		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 ZELLER AVE #D		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
619 LAKE HARBOR DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #I		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #H		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
637 LAKE HARBOR DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
603 SKYLINE DR #C		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
625 LAKE HARBOR DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #K		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
631 LAKE HARBOR DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3212 MARK TWAIN AVE #A		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 ZELLER AVE #H		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
617 LAKE HARBOR DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3005 CLIFTON CT		No	No	1976	1976	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
3216 MARK TWAIN AVE #B		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
605 LAKE HARBOR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3201 ZELLER AVE #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3216 MARK TWAIN AVE #A		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3214 MARK TWAIN AVE #A		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 ZELLER AVE #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 ZELLER AVE #C		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
714 N SALUKI DR		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
207 WESTERNAIRE DR		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
108 BELINDA DR		No	No	1976	1976	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3306 SUNSET TERRACE		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
104 BELINDA DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
115 BELINDA DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
110 BELINDA DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
111 BELINDA DR		No	No	1961	1961	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3201 SUNSET TERRACE		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
104 N CHAMBERLAIN DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2900 MEADOW CT		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3000 W HONEYSUCKLE LN		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
101 N PLAINS AVE		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
604 SALUKI DR N		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
608 SALUKI DR N		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
610 SALUKI DR N		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3303 SUNSET TERRACE		No	No	1973	1973	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
3204 W LAKEVIEW RD		No	No	1969	1969	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3306 W MAIN ST		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3308 W MAIN ST		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3206 SUNSET TERRACE		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
302 SKYLINE DR		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
3303 W LAKEVIEW RD		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3204 SUNSET TERRACE		No	No	1966	1966	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3206 W LAKEVIEW RD		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3205 W HAWTHORNE CT		No	No	1974	1974	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
304 SKYLINE DR		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
303 SKYLINE DR		No	No	1966	1966	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3203 SUNSET TERRACE		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
209 BOSWELL RD		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3305 SUNSET TERRACE		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3307 SUNSET TERRACE		No	No	1977	1977	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3300 W HAWTHORNE CT		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3206 W HAWTHORNE CT		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3200 SUNSET TERRACE		No	No	2024	1970	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
3205 SUNSET TERRACE		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
109 N CHAMBERLAIN DR		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3311 W LAKEVIEW RD		No	No	1977	1977	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
203 SKYLINE DR		No	No	1962	1962	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
206 SKYLINE DR		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
604 LAKE HARBOR DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
115 N PLAINS AVE		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
108 N CHAMBERLAIN DR		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3202 ZELLER AVE #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
112 N CHAMBERLAIN DR		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
110 N CHAMBERLAIN DR		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3201 W HAWTHORNE CT		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
205 SKYLINE DR		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3102 W LAKEVIEW RD		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3105 W LAKEVIEW RD		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3100 W LAKEVIEW RD		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
3101 W LAKEVIEW RD		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
107 N CHAMBERLAIN DR		No	No	1976	1976	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3204 MARK TWAIN AVE #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3204 MARK TWAIN AVE #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3314 W LAKEVIEW RD		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
105 BELINDA DR		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
109 BELINDA DR		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
102 BELINDA DR		No	No	1972	1972	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3200 W HAWTHORNE CT		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
103 BELINDA DR		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
102 BOSWELL RD		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3202 W LAKEVIEW RD		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
106 BELINDA DR		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
105 BOSWELL RD		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3304 SUNSET TERRACE		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
204 SKYLINE DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
100 BELINDA DR		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3302 SUNSET TERRACE		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3311 SUNSET TERRACE		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3308 SUNSET TERRACE		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3300 SUNSET TERRACE		No	No	1976	1976	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
107 BOSWELL RD		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
3302 W HAWTHORNE CT		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
600 SALUKI DR N		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
602 SALUKI DR N		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3203 MARK TWAIN AVE #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3304 W HAWTHORNE CT		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
208 BOSWELL RD		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
205 BOSWELL RD		No	No	1969	1969	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
203 BOSWELL RD		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
103 BOSWELL RD		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3203 W HAWTHORNE CT		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
113 BELINDA DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
202 BOSWELL RD		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3112 W LAKEVIEW RD		No	No	1969	1969	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
107 BELINDA DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3103 W LAKEVIEW RD		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3109 W LAKEVIEW RD		No	No	1962	1962	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3202 W HAWTHORNE CT		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3204 W HAWTHORNE CT		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
202 SKYLINE DR		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3205 W LAKEVIEW RD		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3207 W LAKEVIEW RD		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3203 W LAKEVIEW RD		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3200 W LAKEVIEW RD		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
204 BOSWELL RD		No	No	1972	1972	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
106 BOSWELL RD		No	No	1972	1972	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3304 W MAIN ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3302 W MAIN ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
206 BOSWELL RD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
104 BOSWELL RD		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3101 EDGEWOOD PK		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3004 EDGEWOOD PK		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3107 W WOODLAWN PL		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3109 EDGEWOOD PK		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3111 EDGEWOOD PK		No	No	1967	1967	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3106 W WOODLAWN PL		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3109 W WOODLAWN PL		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3108 W WOODLAWN PL		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3107 EDGEWOOD PK		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3106 EDGEWOOD PK		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3105 W WOODLAWN PL		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3108 EDGEWOOD PK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
3104 EDGEWOOD PK		No	No	1969	1969	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3102 W WOODLAWN PL		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3100 EDGEWOOD PK		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3102 EDGEWOOD PK		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3002 CLIFTON CT		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
310 LINGALE AVE		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
311 LINGALE AVE		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2904 EDGEWOOD PK		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
305 LINGALE AVE		No	No	1969	1969	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
309 LINGALE AVE		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3007 W WOODLAWN PL		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3001 W WOODLAWN PL		No	No	1973	1973	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
100 LINGALE AVE		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3008 W WOODLAWN PL		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3000 W WOODLAWN PL		No	No	1974	1974	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
306 LINGALE AVE		No	No	1974	1974	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
312 LINGALE AVE		No	No	1967	1967	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3002 W MAIN ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
203 LINGALE AVE		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
209 LINGALE AVE		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
204 LINGALE AVE		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3005 W WOODLAWN PL		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3003 W WOODLAWN PL		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
102 LINGALE AVE		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
101 LINGALE AVE		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
205 LINGALE AVE		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
211 LINGALE AVE		No	No	1963	1963	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
302 LINGALE AVE		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
213 LINGALE AVE		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
301 LINGALE AVE		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
208 LINGALE AVE		No	No	1964	1964	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
207 LINGALE AVE		No	No	1959	1959	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3006 WOODLAWN PL		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3004 W WOODLAWN PL		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3002 W WOODLAWN PL		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
203 WESTERNAIRE DR		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
201 WESTERNAIRE DR		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
102 WESTERNAIRE DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
101 BOSWELL RD		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
104 WESTERNAIRE DR		No	No	1964	1964	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
204 WESTERNAIRE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
208 WESTERNAIRE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3301 W HAWTHORNE CT		No	No	1972	1972	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
211 WESTERNAIRE DR		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
202 WESTERNAIRE DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
200 WESTERNAIRE DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
205 WESTERNAIRE DR		No	No	1965	1965	Visual Inspection	Plastic	P	CLS	NL	N	N/R	No		No		
206 WESTERNAIRE DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
209 WESTERNAIRE DR		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
314 LINGALE AVE		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
304 LINGALE AVE		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
308 LINGALE AVE		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3008 EDGEWOOD PK		No	No	2016	2016	Construction Records	Copper	C	C	NL	N	N/R	No		No		
3010 EDGEWOOD PK		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3009 CLIFTON CT		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
3007 CLIFTON CT		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3011 EDGEWOOD PK		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3006 EDGEWOOD PK		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3009 EDGEWOOD PK		No	No	1968	1968	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
3007 EDGEWOOD PK		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3000 EDGEWOOD PK		No	No	1962	1962	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3004 CLIFTON CT		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
101 WESTERNAIRE DR		No	No	1974	1974	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2904 W MAIN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3102 W MAIN ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3005 EDGEWOOD PK		No	No	1962	1962	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2902 EDGEWOOD PK		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2900 EDGEWOOD PK		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
100 WHIPPOORWILL LN		No	No	1974	1974	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2903 EDGEWOOD PK		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
100 WESTERNAIRE DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
3002 EDGEWOOD PK		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
2905 EDGEWOOD PK		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3001 EDGEWOOD PK		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3003 EDGEWOOD PK		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
103 WESTERNAIRE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3108 W MAIN ST		No	No	1981	1981	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3104 W MAIN ST		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3206 W MAIN ST		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3004 W MAIN ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3001 CLIFTON CT		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2706 W MAIN ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3204 W MAIN ST		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3208 W MAIN ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
200 BOSWELL RD		No	No	1968	1968	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
3203 ZELLER AVE #G		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
603 LAKE HARBOR DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
101 N CHAMBERLAIN DR		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3103 W WOODLAWN PL		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3100 W WOODLAWN PL		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3003 CLIFTON CT		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3000 CLIFTON CT		No	No	1977	1977	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
3103 EDGEWOOD PK		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
3105 EDGEWOOD PK		No	No	1969	1969	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
3101 W WOODLAWN PL		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
602 LAKE CT		No	No	1990	1990	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
603 LAKE CT		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3303 W HAWTHORNE CT		No	No	1977	1977	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
3305 W HAWTHORNE CT		No	No	1972	1972	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
3208 W LAKEVIEW RD		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1614 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1403 HOWELL AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1404 N RUSSELL ST		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1508 N RUSSELL ST 1-4		No	No	1902	1902	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1506 N RUSSELL ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1701 SEIGLER DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1405 HOWELL AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1401 HOWELL AVE #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1501 MORGAN AVE		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1613 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1612 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1403 HOWELL AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1405 HOWELL AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1614 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1613 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1401 HOWELL AVE #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1612 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1702 JACOB DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1711 BEVERLY DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1404 HANNAH DR		No	No	2019	1999	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1400 HANNAH DR		No	No	1998	1998	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1607 SEIGLER DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1609 SEIGLER DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 MORGAN AVE		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1404 MORGAN AVE		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 CLAUDIA DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1611 SEIGLER DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1802 N HOLMES DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1604 MORGAN AVE		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1700 MORGAN AVE		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1402 HANNAH DR		No	No	2019	1999	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1612 EMERY LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1600 W YOST AVE		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1604 EMERY LN		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1702 EMERY LN		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1804 N HOLMES DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1603 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1402 N RUSSELL ST		No	No	1927	1927	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1504 MORGAN AVE		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1610 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1400 CLAUDIA DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1607 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1607 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1609 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1603 SEIGLER DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1402 CLAUDIA DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1605 SEIGLER DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1601 SEIGLER DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1611 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1602 N BENTLEY ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1207 BARBARA LN		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1204 BARBARA LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1206 BARBARA LN		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1402 HOWELL AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1401 N RUSSELL ST "Empty Lot"		No	No	1992	Unknown	Maintenance Records	Unknown/Not Lead	P	UNL	NL	N	N/R	No		No		
1704 N HOLMES DR		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
805 ROBINSON ST		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1203 BARBARA LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1611 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1615 W YOST AVE #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1604 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1615 W YOST AVE #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1803 N HOLMES DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 HANNAH DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1603 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1610 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1608 W YOST AVE #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1605 YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1605 YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1608 W YOST AVE #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1401 MORGAN AVE		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1501 N RUSSELL ST 2		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1501 N RUSSELL ST 4		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1405 MORGAN AVE		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1501 N RUSSELL ST 1		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1501 N RUSSELL ST 3		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1409 N RUSSELL ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1408 N RUSSELL ST		No	No	1935	1935	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1403 CLAUDIA DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1602 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1526 COX ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1602 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1524 COX ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1515 BRITTANY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1405 CLAUDIA DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1600 JACOB DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 N COURT ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
705 ROBINSON ST #EAST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1604 JACOB DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1604 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1606 YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1601 W YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1508 BRITTANY LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1606 YOST AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1507 BRITTANY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1505 BRITTANY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1517 BRITTANY LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1601 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1205 BARBARA LN		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1503 BRITTANY LN		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1202 BARBARA LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 N RUSSELL ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1602 N RUSSELL ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1800 N HOLMES DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 HANNAH DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
509 S MECHANIC		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1404 HOWELL AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1400 HOWELL AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1805 N HOLMES DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1400 HOWELL AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1603 JACOB DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1404 HOWELL AVE A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1402 HOWELL AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1700 JACOB DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1609 W YOST AVE B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1602 COX ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1701 N COURT ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
705 ROBINSON ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1509 MAUREEN DR		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2011 MORGAN AVE		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1541 MAUREEN DR		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1804 N COURT ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1304 SCOTSBORO RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 BEVERLY DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1700 BEVERLY DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1406 CORNELL AVE A		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1308 W MACK AVE		No	No	1978	1978	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1702 N HOLMES DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1707 N HOLMES DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1501 BRITTANY LN		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 MORGAN AVE		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1415 CORNELL AVE		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 N MC CLUSKIE RD #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1200 BARBARA LN		No	No	2007	2007	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1903 PRINCETON AVE		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1705 COX ST #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1210 MORGAN AVE		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1501 N RUSSELL ST 5		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1501 N RUSSELL ST 9		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1611 N RUSSELL ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1539 MAUREEN DR		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1706 N RUSSELL ST 1-3		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1708 N RUSSELL ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1703 COX ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1406 CORNELL AVE B		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1502 MAUREEN DR		No	No	1967	1967	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1532 COX ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1800 N COURT ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1202 W DU FOUR ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1200 W DU FOUR ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1502 N BENTLEY ST C		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1507 N BENTLEY ST A		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1610 N PEABODY ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1606 MORGAN AVE		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1606 N PEABODY ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 SCOTSBORO RD		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1306 SCOTSBORO RD		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1704 N COURT ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1814 N COURT ST		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1533 COX ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1806 N COURT ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1306 N RUSSELL ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1525 MAUREEN DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1518 MAUREEN DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1533 MAUREEN DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1527 MAUREEN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1516 MAUREEN DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1531 MAUREEN DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1510 MAUREEN DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1530 MAUREEN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1529 MAUREEN DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
1547 MAUREEN DR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1526 MAUREEN DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1524 MAUREEN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1535 MAUREEN DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 MAUREEN DR "Empty Lot"		No	No	1984	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1519 MAUREEN DR		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1702 N RUSSELL ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1701 BEVERLY DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1813 N COURT ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1515 MAUREEN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1513 MAUREEN DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1517 MAUREEN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1618 N PEABODY ST		No	No	1986	1986	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1821 N COURT ST		No	No	1986	1986	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1708 BEVERLY DR		No	No	1979	1979	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1706 BEVERLY DR		No	No	1991	1991	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1615 N PEABODY ST		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1604 N PEABODY ST		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1607 N PEABODY ST		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1707 BEVERLY DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1705 BEVERLY DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1819 N COURT ST		No	No	1967	1967	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1703 BEVERLY DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1611 N CASH ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1609 N CASH ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1609 N RUSSELL ST		No	No	1946	1946	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1612 N PEABODY ST		No	No	1994	1994	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1607 N CASH ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1609 N CASH ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1613 N PEABODY ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1615 N RUSSELL ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1607 N CASH ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1613 N CASH ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1611 N CASH ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1108 SCOTSBORO RD		No	No	1912	1912	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1304 W DU FOUR ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1502 N BENTLEY ST B		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1110 SCOTSBORO RD		No	No	1948	1948	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1505 N BENTLEY ST A		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1505 N BENTLEY ST B		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1312 MORGAN AVE		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1620 EMERY LN		No	No	1949	1949	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1710 N HOLMES DR		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1614 EMERY LN		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1700 COX ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1511 BRITTANY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1310 MORGAN AVE		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1509 BRITTANY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1313 MORGAN AVE		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1501 N RUSSELL ST 8		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
710 ROBINSON ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1534 COX ST		No	No	1979	1979	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1206 MORGAN AVE		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1300 MORGAN AVE		No	No	1923	1923	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1516 BRITTANY LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1523 MAUREEN DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1501 N RUSSELL ST 10		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1501 N RUSSELL ST 6		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
706 ROBINSON ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1610 EMERY LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1530 COX ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1616 EMERY LN		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1304 MORGAN AVE		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1528 COX ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1518 BRITTANY LN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1205 W MACK AVE C		No	No	1972	1972	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1209 W MACK AVE B		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1306 N MC CLUSKIE RD		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1213 W MACK AVE D		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1507 N BENTLEY ST B		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1209 W MACK AVE A		No	No	1977	1977	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1209 W MACK AVE C		No	No	1977	1977	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1213 W MACK AVE B		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1305 N RUSSELL ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1308 W DEYOUNG ST		No	No	2017	2017	Construction Records	Copper	C	C	NL	N	N/R	No		No		
1106 W DEYOUNG ST SPRIN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1202 SCOTSBORO RD C-D		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1607 W DU FOUR ST		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1610 N RUSSELL ST A-D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1608 W DU FOUR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1817 N COURT ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1820 N COURT ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1306 N ATCHISON AVE		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1403 N SAMPLES ST		No	No	1975	1975	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1205 N MC CLUSKIE RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1803 N RUSSELL ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1404 N MC CLUSKIE RD		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1401 N MC CLUSKIE RD		No	No	1969	1969	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)									
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
	Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)														
		Unknown Not Lead (UNL)	Unknown Not Lead (UNL)														
1619 N RUSSELL ST		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1305 W MACK AVE		No	No	1922	1922	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1504 N BENTLEY ST B		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1505 W DU FOUR ST		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1400 N MC CLUSKIE RD		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1206 W MACK AVE		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1507 N RUSSELL ST		No	No	1902	1902	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1822 N COURT ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1302 N BENTLEY ST B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1202 SCOTSBORO RD B		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1202 SCOTSBORO RD A		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1605 N BENTLEY ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 W MACK AVE C		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 W MACK AVE A		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 W MACK AVE B		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 W MACK AVE E		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1603 N BENTLEY ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 N BENTLEY ST A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 N MC CLUSKIE RD #B		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1303 N MC CLUSKIE RD #A		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 W MACK AVE #C		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1615 N CASH ST		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1200 SCOTSBORO RD		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1209 SCOTSBORO RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1907 PRINCETON AVE		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 W MACK AVE #D		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 W MACK AVE F		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 W MACK AVE D		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1205 SCOTSBORO RD		No	No	2012	2012	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1213 W MACK AVE #A		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1302 N MC CLUSKIE RD		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 N MC CLUSKIE RD B		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
908 W DU FOUR ST #12/13		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1204 SCOTSBORO RD		No	No	1921	1921	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1213 W MACK AVE C		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1307 N MC CLUSKIE RD C		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1616 N PEABODY ST		No	No	1986	1986	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1607 N BENTLEY ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1208 N JOHNSON ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1600 N BENTLEY ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1501 N BENTLEY ST B		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 W MACK AVE B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1204 N COURT ST		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1614 N PEABODY ST		No	No	1980	1980	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1301 W MACK AVE A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1511 N BENTLEY ST		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1504 N BENTLEY ST A		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1601 N BENTLEY ST		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1545 MAUREEN DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1709 BEVERLY DR		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1900 PRINCETON AVE		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1505 SCOTSBORO RD		No	No	1935	1935	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1710 BEVERLY DR		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1410 CORNELL AVE		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1713 BEVERLY DR		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1537 MAUREEN DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1712 BEVERLY DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1402 OXFORD AVE		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1704 N CASH ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1603 N CASH ST A		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1408 N MC CLUSKIE ST		No	No	1935	1935	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1605 N CASH ST A		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1406 W MACK AVE		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1603 N CASH ST B		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1400 N ATCHISON AVE		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1800 N RUSSELL ST		No	No	2023	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1605 N CASH ST B		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1402 N ATCHISON AVE		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1701 N RUSSELL ST		No	No	1987	1987	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 W DU FOUR ST		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 N MC CLUSKIE RD D		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1307 N MC CLUSKIE RD A		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1503 N BENTLEY ST B		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1503 N BENTLEY ST A		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1809 N COURT ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1402 N MCCLUSKIE RD		No	No	1900	1900	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1507 MAUREEN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1407 N BENTLEY ST		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1702 BEVERLY DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1100 W DEYOUNG ST		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1606 W DU FOUR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1404 W DEYOUNG ST		No	No	2013	2013	Construction Records	Copper	C	C	NL	N	N/R	No		No		
1302 SCOTSBORO RD		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1616 N RUSSELL ST A-D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1106 W DEYOUNG ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1206 N COURT ST #A&B		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
902 W DU FOUR ST #A-G		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1404 N BENTLEY ST		No	No	1915	1915	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1400 N BENTLEY ST		No	No	1905	1905	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1402 N BENTLEY ST		No	No	1915	1915	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1501 N BENTLEY ST A		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1201 W MACK AVE B		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1304 N BENTLEY ST A		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1201 W MACK AVE D		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1201 W MACK AVE A		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1607 N RUSSELL ST		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1401 N BENTLEY ST		No	No	1977	1977	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1405 N BENTLEY ST		No	No	1905	1905	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1205 W MACK AVE A		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1201 W MACK AVE C		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1303 N BENTLEY ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1304 N BENTLEY ST B		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1205 W MACK AVE #B		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1700 N COURT ST		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1209 W MACK AVE D		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
900 W DU FOUR ST		No	No	1963	1963	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1502 N BENTLEY ST A		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1206 N JOHNSON ST		No	No	1959	1959	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1509 N BENTLEY ST B		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1301 N COURT ST #FLAGPOLE		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1500 N BENTLEY ST B		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1507 N BENTLEY ST C		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1500 N BENTLEY ST A		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1509 N BENTLEY ST A		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1205 W MACK AVE D		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1305 MORGAN AVE		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 N MC CLUSKIE RD #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1208 MORGAN AVE		No	No	1970	1970	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1309 MORGAN AVE		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1309 CORNELL AVE		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1304 CORNELL AVE		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2002 BITTLE PLACE		No	No	1998	1998	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1807 N COURT ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1612 N RUSSELL ST A-D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1901 PRINCETON AVE		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1801 N RUSSELL ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1307 MORGAN AVE		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1200 W DEYOUNG ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1200 W DEYOUNG ST B		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1304 W MACK AVE		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1614 N RUSSELL ST A-D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1900 BITTLE PLACE		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
801 ROBINSON ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1906 BITTLE PLACE		No	No	1969	1969	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
703 ROBINSON ST		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
4425 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4477 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4483 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4403 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4427 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4401 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4473 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4479 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4407 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4409 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4405 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2769 KOKOPELLI DR # SPRINK		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2700 KOKOPELLI DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2769 KOKOPELLI DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2743 KOKOPELLI DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2752 KOKOPELLI DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1506 BALTUSROL DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1506 BALTUSROL DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2753 KOKOPELLI DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2720 KOKOPELLI DR #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2753 KOKOPELLI DR #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2752 KOKOPELLI DR #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2751 KOKOPELLI DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2751 KOKOPELLI DR #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1505 GLENEAGLE DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2762 KOKOPELLI DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1507 GLENEAGLE DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
4421 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4458 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4419 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4423 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4424 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4415 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4417 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4413 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2785 KOKOPELLI DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4437 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4433 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4429 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4431 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
1409 AUGUSTA DR #SPRINK		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2762 KOKOPELLI DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3300 BANTERRA DR #SHOW		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2700 W DEYOUNG ST C		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2723 KOKOPELLI DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2764 KOKOPELLI DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2909 WILLIAMSON CO PKWY		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 KOKOPELLI DR #D		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 KOKOPELLI DR #B		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 KOKOPELLI DR #A		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1517 RYDER CUP BLVD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
4435 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4453 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4439 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4455 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4457 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4459 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2708 WALTON WAY		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2719 KOKOPELLI DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2722 KOKOPELLI DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2719 KOKOPELLI DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2715 KOKOPELLI DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2765 KOKOPELLI DR #SPRINK		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1508 GLENEAGLE DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1502 CHART HILL DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1506 GLENEAGLE DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2747 KOKOPELLI DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2750 KOKOPELLI DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2747 KOKOPELLI DR #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2749 KOKOPELLI DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2785 KOKOPELLI DR # Sprink		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2789 KOKOPELLI DR		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2797 KOKOPELLI DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2789 KOKOPELLI DR #SPRINK		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2707 ST ANDREWS DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2711 ST ANDREWS DR #SPRINK		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2707 ST ANDREWS DR #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2709 ST ANDREWS DR #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2744 KOKOPELLI DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1503 SHINNECOCK CT		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 SHINNECOCK CT		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2724 KOKOPELLI DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2710 TURNBERRY DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1505 SHINNECOCK CT		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2704 TURNBERRY DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2766 KOKOPELLI DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2766 KOKOPELLI DR #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2763 KOKOPELLI DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2701 TURNBERRY DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2763 KOKOPELLI DR #SPRINK		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1502 CHART HILL DR #SPRINK		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2700 TURNBERRY DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1505 CHART HILL DR #SPRIN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1505 CHART HILL DR		No	No	2012	2012	Construction Records	Plastic	P	C	NL	N	N/R	No			No	
2729 KOKOPELLI DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2765 KOKOPELLI DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2728 KOKOPELLI DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3401 OFFICE PARK DR #SPRINK		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1311 HALFWAY RD		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No			No	
2703 SEVENTEENTH ST #E		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3001 WILLIAMSON CO PKWY #A&B		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1307 HALFWAY RD		No	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No			No	
4460 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4406 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4454 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4467 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
4463 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4474 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4476 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4462 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4471 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4465 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4414 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4443 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4447 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4461 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4452 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4446 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4469 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4448 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4456 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4412 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4441 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4449 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4451 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4445 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4408 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2744 KOKOPELLI DR #SPRINK		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2745 KOKOPELLI DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1502 HAZELTINE CT		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2745 KOKOPELLI DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2758 KOKOPELLI DR #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2757 KOKOPELLI DR #SPRINK		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2726 KOKOPELLI DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2710 ST ANDREWS DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2726 KOKOPELLI DR #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2710 ST ANDREWS DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1506 CHART HILL DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1511 CHART HILL DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2790 KOKOPELLI DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 SHINNECOCK CT #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2720 KOKOPELLI DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2757 KOKOPELLI DR		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1507 BALTUSROL DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1508 BALTUSROL DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2802 OUTER DR		No	No	2015	2015	Construction Records	Copper	C	C	NL	N	N/R	No			No	
2603 HILL VIEW WAY #WASH		No	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No			No	
2800 SEVENTEENTH ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2803 SEVENTEENTH ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2480 BLUE HERON DR #SPRINK		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2603 HILL VIEW WAY		No	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2706 WALTON WAY		No	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2607 BLUE HERON DR		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2731 KOKOPELLI DR		No	No	1997	1997	Maintenance Records	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2737 KOKOPELLI DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2737 KOKOPELLI DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2797 KOKOPELLI DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2708 KOKOPELLI DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2711 KOKOPELLI DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2708 TURNBERRY DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2702 TURNBERRY DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2702 TURNBERRY DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1502 HAZELTINE CT #SPRINK		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2708 TURNBERRY DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1507 CHART HILL DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2730 KOKOPELLI DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2733 KOKOPELLI DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2711 ST ANDREWS DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2735 KOKOPELLI DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2709 KOKOPELLI DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1510 CHART HILL DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1510 CHART HILL DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2709 KOKOPELLI DR #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1511 RYDER CUP BLVD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
4481 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4411 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2810 KOKOPELLI DR #A		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 KOKOPELLI DR #F		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2810 KOKOPELLI DR #C		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 KOKOPELLI DR #G		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 KOKOPELLI DR #E		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 KOKOPELLI DR #C		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2810 KOKOPELLI DR #B		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1507 BALTUSROL DR #SPRINK		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2759 KOKOPELLI DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2759 KOKOPELLI DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1509 CHART HILL DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2709 ST ANDREWS DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1511 CHART HILL DR #SPRINK		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1507 CHART HILL DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2810 KOKOPELLI DR #D		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1508 GLENEAGLE DR #SPRINK		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2717 CARNOUSTIE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1519 RYDER CUP BLVD		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2404 SKYLINE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2406 SKYLINE DR		No	No	2014	2014	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1510 APACHE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3423 OFFICE PARK DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
703 SKYLINE DR #B		No	No	1997	1997	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3903 W ERNESTINE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1502 APACHE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1503 APACHE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
716 SKYLINE DR		No	No	1985	1985	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1515 APACHE DR		No	No	1919	1919	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1506 CHEYENNE DR		No	No	2006	2006	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
703 SKYLINE DR #A		No	No	1997	1997	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1513 APACHE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 CHEYENNE DR		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
3204 CHEROKEE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2703 W DEYOUNG ST #SPRIN		No	No	2018	2018	Maintenance Records	Copper	C	C	NL	N	N/R	No		No		
900 SKYLINE DR #303		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1505 CHEYENNE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1503 CHEYENNE DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 APACHE DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1501 CHEYENNE DR		No	No	2005	2005	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples:	Examples:	Examples:	Examples:							
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)					Copper - Lead Solder (CLS)		
	Yes (Y) or No (N)					Examples:	Lead (L)	Lead (L)							Cast/Ductile Iron or Transite (O)		
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Plastic - PVC, HDPE, PEX (P)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Cast/Ductile Iron or Transite (O)		
							Unknown (U)	Unknown (U)	Unknown (U)						Leave blank if no Lead Service Line was replaced.		
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
1507 CHEYENNE DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1500 APACHE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
703 SKYLINE DR #C		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3200 CHEROKEE DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 APACHE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1407 AUGUSTA DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2700 MASTERS CT		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1519 CHAMPIONS DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2702 MASTERS CT		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1521 CHAMPIONS DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2700 MUIRFIELD CT		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1310 HALFWAY RD		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2702 PINEHURST CT		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1412 AUGUSTA DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2771 KOKOPELLI DR #SPRINK		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2703 PRESTWICK WAY		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2705 PRESTWICK WAY		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1509 YEARACK DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1409 AUGUSTA DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1403 AUGUSTA DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1408 AUGUSTA DR #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3212 CHEROKEE DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
812 SKYLINE DR #2		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1509 CHEYENNE DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
812 SKYLINE DR #1		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2784 KOKOPELLI DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2771 KOKOPELLI DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2767 KOKOPELLI DR #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2774 KOKOPELLI DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2767 KOKOPELLI DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2702 PINEHURST CT #SPRINK		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2702 PRESTWICK WAY		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2784 KOKOPELLI DR #SPRINK		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2768 KOKOPELLI DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1410 AUGUSTA DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2700 MASTERS CT #SPRINK		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2726 CARNOUSTIE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
2779 KOKOPELLI DR #SPRINK		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1412 AUGUSTA DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2781 KOKOPELLI DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2700 MUIRFIELD CT #SPRINK		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2702 MASTERS CT #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2781 KOKOPELLI DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
3209 CHEROKEE DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
3214 CHEROKEE DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3208 CHEROKEE DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3210 CHEROKEE DR		No	No	2003	2003	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3211 CHEROKEE DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1523 RYDER CUP BLVD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1515 RYDER CUP BLVD		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1521 CHAMPIONS DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1433 CHAMPIONS DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1407 AUGUSTA DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2779 KOKOPELLI DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1519 CHAMPIONS DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1509 CHAMPIONS DR #SPRINK		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1509 CHAMPIONS DR		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2700 TURNBERRY DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2780 KOKOPELLI DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2703 MASTERS CT		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2772 KOKOPELLI DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2704 PRESTWICK WAY		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2703 MASTERS CT #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2704 PRESTWICK WAY #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2480 BLUE HERON DR		No	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1411 AUGUSTA DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1311 HALFWAY RD #SPRINK		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2716 CARNOUSTIE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1508 APACHE DR		No	No	2001	2001	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1507 APACHE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1509 APACHE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1506 APACHE DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1511 APACHE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1505 APACHE DR		No	No	2005	2005	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3415 OFFICE PARK DR #D		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3415 OFFICE PARK DR #B & C		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3408 OFFICE PARK DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3301 W COMMERCIAL RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
1516 CHAMPIONS DR		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3304 WATER TOWER RD		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1500 RYDER CUP BLVD		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1510 CHEYENNE DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3207 CHEROKEE DR		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1511 CHEYENNE DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3401 PROFESSIONAL PARK DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3307 WATER TOWER RD		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3911 W ERNESTINE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
800 SKYLINE DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
812 SKYLINE DR #3		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1502 RYDER CUP BLVD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3309 WATER TOWER RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3411 OFFICE PARK DR		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1605 YEARACK DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3119 WILLIAMSON CO PKWY		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
3309 WATER TOWER RD #REAR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3402 HEARTLAND ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
900 SKYLINE DR #EXTRA		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2306 WILLIAMSON CO PKWY		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2708 WALTON WAY #SPRIN		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1003 N PENTECOST RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3905 W ERNESTINE DR #SPRINK		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1504 RYDER CUP BLVD		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2725 CARNOUSTIE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1506 RYDER CUP BLVD		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1508 RYDER CUP BLVD		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1514 RYDER CUP BLVD		No	No	2003	2003	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
4475 MEADOWLAND PKWAY		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1516 RYDER CUP BLVD		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2722 CARNOUSTIE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2724 CARNOUSTIE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1522 RYDER CUP BLVD		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2402 WILLIAMSON CO PKWY #52		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2402 WILLIAMSON CO PKWY #51		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1510 RYDER CUP BLVD		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1520 RYDER CUP BLVD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2407 BLACK DIAMOND DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2703 W DEYOUNG ST #B		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1433 CHAMPIONS DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2700 W DEYOUNG ST D		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2703 W DEYOUNG ST #A		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1508 CHEYENNE DR		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 BANTERRA DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2406 WILLIAMSON CO PKWY #9-J		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3211 BANTERRA DR		No	No	1972	1972	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
2701 SKYLINE DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
900 SKYLINE DR #304		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2605 BLUE HERON DR		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No		No		
5100 ED SMITH WAY #A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3201 BANTERRA DR		No	No	2004	2004	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
5102 ED SMITH WAY		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1602 SIOUX DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
5105 ED SMITH WAY		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
1400 CHAMPIONS DR		No	No	Unknown	Unknown	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1512 RYDER CUP BLVD		No	No	2000	2000	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
2783 KOKOPELLI DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2701 MUIRFIELD CT		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2783 KOKOPELLI DR #SPRINK		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1409 N CARBON ST		No	No	2019	1994	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1503 HAZELTINE CT		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
KOKOPELLI DR/WILLIAMSON CO. PKWY.		No	No	1989	1989	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 HALFWAY RD		No	No	2013	2013	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1300 REDCO DR		No	No	2016	2016	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2609 BLUE HERON DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2700 SEVENTEENTH ST		No	No	2005	2005	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1100 GLEN CLARIDA DR #SUITE		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 HALFWAY RD		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
4407 W DEYOUNG ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 HALFWAY RD #SPRINK		No	No	2013	2013	Construction Records	Copper	C	P	NL	N	N/R	No		No		
2403 BLACK DIAMOND DR		No	No	2012	2012	Construction Records	Copper	C	P	NL	N	N/R	No		No		
3300 W DEYOUNG ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2704 WALTON WAY		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2712 W DEYOUNG ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1517 RYDER CUP BLVD #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2717 CARNOUSTIE DR #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1518 RYDER CUP BLVD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1100 HALFWAY RD		No	No	1987	1987	Survey Response	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
2725 CARNOUSTIE DR #SPRINK		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1400 CHAMPIONS DR #SPRIN		No	No	2012	2012	Construction Records	Copper	C	P	NL	N	N/R	No			No	
2808 OUTER DR		No	No	2015	2015	Construction Records	Copper	C	C	NL	N	N/R	No			No	
3001 SKYLINE DR		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2704 W DEYOUNG ST SPRIN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2605 BLUE HERON DR #SPRINK		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No			No	
5309 MEADOWLAND PKWAY		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
3303 W COMMERCIAL RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1100 GOLF DR		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3305 W COMMERCIAL RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3309 W COMMERCIAL RD		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2700 W DEYOUNG ST E		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2801 SEVENTEENTH ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2700 W DEYOUNG ST A		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2710 W DEYOUNG ST #SPRIN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3006 CIVIC CIRCLE BLVD		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3411 PROFESSIONAL PARK DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2808 W DEYOUNG ST		No	No	2002	2002	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3333 W DEYOUNG ST #BOILER ROOM		Yes	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3333 W DEYOUNG ST #EAST		Yes	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
3331 W DEYOUNG ST		Yes	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2706 W DEYOUNG ST #SPRIN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2724 W DEYOUNG ST		No	No	1992	1992	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2500 WILLIAMSON CO PKWY		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3114 WILLIAMSON CO PKWY		Yes	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3115 WILLIAMSON CO PKWY		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3116 WILLIAMSON CO PKWY #SPRINK		Yes	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1309 HALFWAY RD		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No			No	
2706 W DEYOUNG ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2601 VERNELL RD		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2705 WALTON WAY		No	No	1991	1991	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
2709 WALTON WAY		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
809 SKYLINE DR		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
900 SKYLINE DR		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
3200 BANTERRA DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3209 W DEYOUNG ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
900 SKYLINE DR #100		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
3108 W DEYOUNG ST #A&B		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2611 VERNELL RD		No	No	1966	1966	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
9250 AISIN DR		No	No	2009	2009	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1008 HALFWAY RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3209 BANTERRA DR		No	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
3000 W DEYOUNG ST #600		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1802 BITTLE PLACE		No	No	1968	1968	Visual Inspection	Unknown	G	G	NL	N	N/R	No			No	
1806 BITTLE PLACE		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	G	NL	N	N/R	No			No	
3403 PROFESSIONAL PARK DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3419 PROFESSIONAL PARK DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3107 WILLIAMSON CO PKWY		No	No	1994	1994	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2724 W DEYOUNG ST #SPRIN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2704 W DEYOUNG ST		No	No	2012	2012	Construction Records	Copper	C	P	NL	N	N/R	No			No	
1710 W DEYOUNG ST		No	No	1922	1922	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2725 KOKOPELLI DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3909 W ERNESTINE DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1000 MINERS DR #STE		No	No	2007	2007	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2805 OUTER DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
703 SKYLINE DR #D		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3402 OFFICE PARK DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3412 OFFICE PARK DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
906 SKYLINE DR #200		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3401 OFFICE PARK DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3415 OFFICE PARK DR #A		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
906 SKYLINE DR #100		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3208 W COMMERCIAL RD		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3201 W DEYOUNG ST		No	No	1966	1966	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1401 N CARBON ST B		No	No	2019	1995	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
3310 WATER TOWER RD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
2743 KOKOPELLI DR #SPRINK		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1101 N PENTECOST RD		No	No	1999	1999	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1103 N PENTECOST RD		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1003 ASPEN ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2907 WILLIAMSON CO PKWY		No	No	2023	2005	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
5100 ED SMITH WAY #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3205 W COMMERCIAL RD		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2705 W DEYOUNG ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2608 W DEYOUNG ST		No	No	1973	1973	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1508 SIOUX DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2707 WALTON WAY		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 N CARBON ST A		No	No	2019	1995	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
3305 WATER TOWER RD		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2603 VERNELL RD		No	No	1985	1985	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
3307 W COMMERCIAL RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1100 GLEN CLARIDA DR #SPRIN		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1104 PENTECOST RD		No	No	2000	2000	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2611 BLUE HERON DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2606 W DEYOUNG ST		No	No	1973	1973	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
3405 OFFICE PARK DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2700 W DEYOUNG ST H		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2700 W DEYOUNG ST G		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3210 W COMMERCIAL RD		No	No	2023	1980	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
3306 WATER TOWER RD		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1406 N CARBON ST		No	No	2019	2019	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
2758 KOKOPELLI DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3202 CHEROKEE DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2714 WALTON WAY		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1704 W DEYOUNG ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2406 WILLIAMSON CO PKWY #1-A		No	No	2003	2003	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2400 WILLIAMSON CO PKWY		No	No	2000	2000	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2807 OUTER DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2702 W DEYOUNG ST		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2708 W DEYOUNG ST #SPRIN		No	No	1997	1997	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2710 W DEYOUNG ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3401 HEARTLAND ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3403 HEARTLAND ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3905 W ERNESTINE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1000 MINERS DR #C HSE		No	No	2007	2007	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1000 MINERS DR #BL B		No	No	2007	2007	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2800 OUTER DR		No	No	1995	1995	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2701 W DEYOUNG ST		No	No	1966	1966	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples:	Examples:	Examples:	Examples:							
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)					Copper - Lead Solder (CLS)		
	Yes (Y) or No (N)					Examples:	Lead (L)	Lead (L)	Lead (L)	Non-Lead (NL)				Plastic - PVC, HDPE, PEX (P)			
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead Service Line was replaced.		
							Unknown (U)	Unknown (U)	Unknown (U)								
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
1706 W DEYOUNG ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1000 MINERS DR #C & D		No	No	2007	2007	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1000 MINERS DR #SPRINK		No	No	2007	2007	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2708 W DEYOUNG ST		No	No	1997	1997	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
700 SKYLINE DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2801 CIVIC CIRCLE BLVD		No	No	2009	2009	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1527 CHAMPIONS DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2900 W DEYOUNG ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
3003 CIVIC CIRCLE BLVD #100		Yes	No	Unknown	Unknown	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
3123 WILLIAMSON CO PKWY		No	No	2001	2001	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2400 WILLIAMSON CO PKWY #A		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3206 CHEROKEE DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2806 OUTER DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3117 WILLIAMSON CO PKWY		Yes	No	1999	1999	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
3001 WILLIAMSON CO PKWY #C		No	No	2015	2015	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2402 WILLIAMSON CO PKWY #F		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2795 KOKOPELLI DR #SPRIN		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2402 WILLIAMSON CO PKWY #A-D		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1301 N CARBON ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1300 N CARBON ST		No	No	1989	1989	Maintenance Records	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
709 SKYLINE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
801 SKYLINE DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
707 SKYLINE DR		Yes	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2406 WILLIAMSON CO PKWY #2-B		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2702 SEVENTEENTH ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2704 SEVENTEENTH ST #2		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2704 SEVENTEENTH ST #1		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1300 N CARBON ST #2		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1403 JOE ABBOTT WAY		No	No	2019	2001	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
2795 KOKOPELLI DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3000 W DEYOUNG ST #100		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3008 CIVIC CIRCLE BLVD		No	No	2004	2004	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
3000 W DEYOUNG ST #REST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3003 CIVIC CIRCLE BLVD #200		Yes	No	Unknown	Unknown	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
3123 WILLIAMSON CO PKWY #2		No	No	2001	2001	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1305 N CARBON ST		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3400 OFFICE PARK DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1804 BITTLE PLACE		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2808 OUTER DR #SPRIN		No	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No		No		
3000 W DEYOUNG ST #500		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2402 WILLIAMSON CO PKWY #E		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2406 WILLIAMSON CO PKWY #3-C		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2812 OUTER DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2761 KOKOPELLI DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)		
	Yes (Y) or No (N)					Examples:	Lead (L)	Lead (L)	Lead (L)	Non-Lead (NL)				Plastic - PVC, HDPE, PEX (P)			
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead Service Line was replaced.		
							Unknown (U)	Unknown (U)	Unknown (U)								
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
1504 SIOUX DR		No	No	1997	1997	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1506 SIOUX DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2710 WALTON WAY		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2703 SEVENTEENTH ST #A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2712 WALTON WAY		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1002 PENTECOST RD		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
3000 W DEYOUNG ST #180		No	No	2023	2023	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
2405 BLACK DIAMOND DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3000 WILLIAMSON CO PKWY		No	No	2024	1997	Maintenance Records	Plastic	P	C	NL	N	N/R	No			No	
1515 CHAMPIONS DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2804 E OUTER DR		No	No	1995	1995	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2806 OUTER DR #SPRIN		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2406 WILLIAMSON CO PKWY #8-H		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2406 WILLIAMSON CO PKWY #6-G		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2406 WILLIAMSON CO PKWY #5-E		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2602 W DEYOUNG ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2604 W DEYOUNG ST		No	No	1973	1973	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2612 W DEYOUNG ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2406 WILLIAMSON CO PKWY #4-D		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
112 AIRWAY DR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
108 AIRWAY DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
8104 OLD ROUTE 13		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
10315 ROUTE 148		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
9629 ROUTE 148		No	No	1956	1956	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9804 ROUTE 148		No	No	1937	1937	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
9694 ROUTE 148		No	No	2017	2017	Construction Records	Copper	C	C	NL	N	N/R	No			No	
9450 ROUTE 148		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
8460 EXPRESS DR		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9644 PENTECOST RD		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9462 STANLEY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9366 MULLANS LN		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9427 STANLEY LN		No	No	1890	1890	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
7454 GUNNERS LN		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
7469 GUNNERS LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9813 ROUTE 148		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
7505 GUNNERS LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9337 STANLEY LN		No	No	1935	1935	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
9640 ROUTE 148		No	No	1959	1959	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
8152 OLD ROUTE 13		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9397 MULLANS LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9416 JOHNS LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
7802 OLD ROUTE 13		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
7762 OLD ROUTE 13		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9546 JOHNS LN		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
7561 GUNNERS LN		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
7716 OLD ROUTE 13 #A		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
7716 OLD ROUTE 13 #C		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
4501 W DEYOUNG ST #B-102		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
7716 OLD ROUTE 13 #B		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
4505 W DEYOUNG ST #S100		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
7301 COX DR		No	No	1962	1962	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
8526 OLD ROUTE 13		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
8440 OLD ROUTE 13		No	No	1986	1986	Survey Response	Unknown	P	P	NL	N	N/R	No		No	No	
9549 JOHNS LN		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
9673 ROUTE 148		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
8168 OLD ROUTE 13		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
7832 OLD ROUTE 13		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
8196 OLD ROUTE 13 #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
8836 OLD ROUTE 13		No	No	1950	1950	Survey Response	Unknown	P	P	NL	N	N/R	No		No	No	
7716 OLD ROUTE 13 #D		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
8196 OLD ROUTE 13 #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
9412 STANLEY LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
8280 OLD ROUTE 13		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
7920 OLD ROUTE 13		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
7161 COX DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
7562 OLD ROUTE 13		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
9499 PENTECOST RD		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
7540 OLD ROUTE 13		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
110 QUALITY WAY		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9487 NOBLE LN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
7962 OLD ROUTE 13		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
104 AIRWAY DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9620 PENTECOST RD		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
8972 OLD ROUTE 13 #B		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
5208 MEADOWLAND PKWAY		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9735 PENTECOST RD		No	No	1972	1972	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
113 QUALITY WAY		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
106 AIRWAY DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9635 PENTECOST RD		No	No	1972	1972	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
10021 OLD BAINBRIDGE TRAIL		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9690 PENTECOST RD		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
9651 PENTECOST RD		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1100 N PENTECOST RD		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
8304 OLD ROUTE 13		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
7650 OLD ROUTE 13		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
8870 OLD ROUTE 13		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9507 NOBLE LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9344 STANLEY LN		No	No	1925	1925	Survey Response	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
103 AIRWAY DR 1-3		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
10065 OLD BAINBRIDGE TRAIL		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
9234 OLD ROUTE 13		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
107 AIRWAY DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
9469 NOBLE LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
5101 W DEYOUNG ST		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
7657 GUNNERS LN		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
9830 BRIGGS RD #A-B		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
9954 ROUTE 148		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
10093 OLD BAINBRIDGE TRAIL		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
9939 OLD BAINBRIDGE TRAIL		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
7689 GUNNERS LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
7619 GUNNERS LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
7122 OLD ROUTE 13		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3907 W ERNESTINE DR		No	No	1991	1991	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
9200 OLD ROUTE 13		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
9186 OLD ROUTE 13		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
7070 OLD ROUTE 13		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
9314 OLD ROUTE 13		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
7514 GUNNERS LN		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
7090 OLD ROUTE 13		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
8208 OLD ROUTE 13 #BARN		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
9629 OLD BAINBRIDGE TRAIL		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
112 QUALITY WAY		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
8184 OLD ROUTE 13		No	No	1989	1989	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
8230 OLD ROUTE 13		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
7142 OLD ROUTE 13		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
9842 OLD BAINBRIDGE TRAIL		No	No	1947	1947	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9987 BRIGGS RD #BARN		No	No	2019	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9915 OLD BAINBRIDGE TRAIL		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
111 AIRWAY DR		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
102 AIRWAY DR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
5208 MEADOWLAND PKWAY #ANNEX		No	No	1996	1996	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
4503 W DEYOUNG ST #1A&1B		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
5200 MEADOWLAND PKWAY		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
105 AIRWAY DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9579 PENTECOST RD		No	No	1972	1972	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
109 QUALITY WAY		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
9451 NOBLE LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1000 N PENTECOST RD		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
8656 OLD ROUTE 13		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
9433 NOBLE LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9417 ROUTE 148		No	No	1984	1984	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
4503 W DEYOUNG ST #S100		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9738 ROUTE 148		No	No	1960	1960	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
9835 BAINBRIDGE TRAIL		No	No	2014	2014	Construction Records	Copper	C	C	NL	N	N/R	No			No	
9417 NOBLE LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
9490 ROUTE 148		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
10000 BRIGGS RD		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
4503 W DEYOUNG ST #11A-D		No	No	2012	2012	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
5203 MEADOWLAND PKWAY		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1102 TOWER SQUARE PLAZA		No	Yes	2023	1956	Maintenance Records	Copper	C	CLS	NL	N	11/7/2023	Yes	11/7/2023	C	No	
507 E EVERETT ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1604 E PICKETT LN		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
431 S FUTURE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1700 REMINGTON CT		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1701 REMINGTON CT		No	No	2002	2002	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
617 S CALUMET ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
505 S CALUMET ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
712 CIRCLE DR		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
520 E THORN ST		No	No	1935	1935	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
919 E MAIN ST B		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
919 E MAIN ST A		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
919 E MAIN ST D		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
600 S FUTURE ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1703 REMINGTON CT		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
508 S FUTURE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
609 E EVERETT ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1707 REMINGTON CT		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
523 E EVERETT ST		No	No	1917	1917	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1906 E PICKETT LN		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
515 E EVERETT ST	LP1C023	No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
519 E EVERETT ST		No	No	1910	1910	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
518 E EVERETT ST		No	No	1916	1916	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1702 E PICKETT LN #C		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
303 S FAIR ST		No	No	1920	1920	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1706 E PICKETT LN		No	No	2003	2003	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
512 E EVERETT ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
102 S GRAY ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
613 MARY LYNN DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1806 E PICKETT LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 REMINGTON CT		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
417 E COLLEGE ST C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
512 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1602 E PICKETT LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 E PICKETT LN #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1702 E PICKETT LN #A		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1704 E PICKETT LN #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1702 E PICKETT LN #B		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
1702 E PICKETT LN #D		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
711 E MAIN ST		No	No	1924	1924	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
919 E MAIN ST C		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1603 E KIOWA DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1005 E COLLEGE ST		No	No	1900	1900	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
1706 REMINGTON CT		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1704 REMINGTON CT		No	No	2001	2001	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
101 S FUTURE ST A		No	No	1890	1890	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
622 E MAIN ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
615 VALMAR DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
101 S FUTURE ST D		No	No	1920	1920	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
101 S FUTURE ST B		No	No	1890	1890	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
529 E EVERETT ST		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
607 VALMAR DR		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1708 REMINGTON CT		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1802 E PICKETT LN		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
602 VINEWOOD LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
600 MARY LYNN DR		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
602 MARY LYNN DR		No	No	1978	2024	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
605 VINEWOOD LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
608 VINEWOOD LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
609 VINEWOOD LN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1105 E COLLEGE ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
204 S FAIR ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1107 E COLLEGE ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1109 E COLLEGE ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
610 VALMAR DR		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
605 VALMAR DR		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
609 VALMAR DR		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
612 VALMAR DR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
610 VINEWOOD LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
601 MARY LYNN DR		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
911 E BEECH ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
517 E MARION ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
603 VALMAR DR		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 REMINGTON CT		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
606 S CALUMET ST		No	No	2019	2019	Construction Records	Copper	C	P	NL	N	N/R	No		No		
101 S FUTURE ST C		No	No	1890	1890	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1600 E PICKETT LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
705 S CALUMET ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
608 VALMAR DR		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
606 VALMAR DR		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
707 S CALUMET ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
605 S VIRGINIA AVE		No	No	1940	1940	Maintenance Records	Unknown	G	G	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
202 S GOVERNOR ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
105 S BUCHANAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1000 E COLLEGE ST		No	No	1903	1903	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
400 E COLLEGE ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
504 ALLEN AVE		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
612 PLEASANT CT		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
201 S BUCHANAN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
916 E COLLEGE ST #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
109 S GRAY ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
606 PLEASANT CT		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
607 PLEASANT CT		No	No	1927	1927	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
602 PLEASANT CT		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
526 E EVERETT ST		No	No	1918	1918	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
605 MARY LYNN DR #A		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
911 E COLLEGE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
515 E COLLEGE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
301 E COLLEGE ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1914 E PICKETT LN		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1609 E PICKETT LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
915 E COLLEGE ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
604 ALLEN AVE		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
609 PLEASANT CT		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
913 E COLLEGE ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
916 E COLLEGE ST B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
903 E COLLEGE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
207 S VIRGINIA AVE		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
208 S FAIR ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
605 MARY LYNN DR #B		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
613 S VIRGINIA AVE		No	No	1914	1914	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
407 E COLLEGE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
417 E COLLEGE ST B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
411 E COLLEGE ST		No	No	1927	1927	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
417 E COLLEGE ST A		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1500 E PICKETT LN		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
609 MARY LYNN DR #B		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
608 MARY LYNN DR		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
607 MARY LYNN DR		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
611 MARY LYNN DR		No	No	1975	1975	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
610 MARY LYNN DR		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
207 E COLLEGE ST		No	No	2008	2008	Maintenance Records	Copper	C	C	NL	N	N/R	No		No		
1908 E PICKETT LN		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
601 S VIRGINIA AVE		No	No	1969	1969	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
918 E COLLEGE ST		No	No	1900	1900	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
603 MARY LYNN DR #A		No	No	1981	1981	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
603 MARY LYNN DR #B		No	No	1981	1981	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1804 E PICKETT LN		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1808 E PICKETT LN		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
606 MARY LYNN DR		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
614 VALMAR DR		No	No	1983	1983	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1912 E PICKETT LN		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
604 MARY LYNN DR		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
611 VALMAR DR		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
611 S HADFIELD ST		No	No	1966	1966	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1601 E KIOWA DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
609 MARY LYNN DR #A		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
906 TOWER SQUARE PLAZA		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1705 E PICKETT LN		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1603 E PICKETT LN		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1800 E PICKETT LN		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
604 VALMAR DR		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
602 VALMAR DR		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
601 VALMAR DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1707 E PICKETT LN		No	No	1987	1987	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1607 E PICKETT LN		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1601 E PICKETT LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
300 S FUTURE ST	LP1A069	No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
511 E EVERETT ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
703 S CALUMET ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
305 E COLLEGE ST		No	No	1900	1900	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1607 E KIOWA DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1606 E KIOWA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1604 E KIOWA DR		No	No	1997	1997	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1609 E KIOWA DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
617 E THORN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
428 S FUTURE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
503 S CALUMET ST #A-B		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
506 E EVERETT ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
607 E EVERETT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
102 S FUTURE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
314 S FUTURE ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
613 VALMAR DR		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1602 E KIOWA DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
201 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
612 E EVERETT ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
307 S FUTURE ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
511 ALLEN AVE		No	No	1922	1922	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
108 S BUCHANAN ST		No	No	1950	1950	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
1505 E PICKETT LN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
701 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1415 E PICKETT LN		No	No	2000	2000	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
408 E COLLEGE ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
304 E COLLEGE ST		No	No	1910	1910	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No		
503 E COLLEGE ST 1-4		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
104 S FUTURE ST		No	No	1947	1947	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
106 S BUCHANAN ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1608 E KIOWA DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
305 S FAIR ST		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1100 E COLLEGE ST A		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
301 S FAIR ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1110 E COLLEGE ST		No	No	1919	1919	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1100 E COLLEGE ST B		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
707 S HADFIELD ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
703 S HADFIELD ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
412 S CALUMET ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
607 S VIRGINIA AVE		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
507 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
425 S FUTURE ST		No	No	1970	1970	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
419 S FUTURE ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
501 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
706 S HADFIELD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
609 S FUTURE ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
505 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
707 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
403 S FUTURE ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
705 S FUTURE ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
200 S FUTURE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
305 S FUTURE ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
703 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
611 S FUTURE ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
600 E HEMINGWAY DR		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
700 S HADFIELD ST		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
306 S FUTURE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
608 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
704 S HADFIELD ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
706 S FUTURE ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
710 S CALUMET ST		No	No	1935	1935	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
608 E EVERETT ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
421 S CALUMET ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
417 S CALUMET ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 CIRCLE DR		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
416 S CALUMET ST		No	No	1928	1928	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
419 S CALUMET ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
107 S GOVERNOR ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
524 E EVERETT ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
530 E EVERETT ST		No	No	1948	1948	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
607 E THORN ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
611 PLEASANT CT		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
700 S CALUMET ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
711 CIRCLE DR		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
608 S CALUMET ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
702 E PICKETT LN		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
610 S CALUMET ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 S CALUMET ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
906 E COLLEGE ST		No	No	2013	2013	Construction Records	Copper	C	C	NL	N	N/R	No		No		
601 PLEASANT CT		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
504 E COLLEGE ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
528 E THORN ST		No	No	1930	1930	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
414 S CALUMET ST		No	No	1930	1930	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
100 S GRAY ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
615 E THORN ST		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
409 S CALUMET ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
507 ALLEN AVE		No	No	1958	1958	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
513 ALLEN AVE		No	No	1944	1944	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
705 S HADFIELD ST		No	No	1955	1955	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
313 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 S FUTURE ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified?	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
605 S HADFIELD ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
515 S CALUMET ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
606 ALLEN AVE		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
420 S CALUMET ST		No	No	1948	1948	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
515 ALLEN AVE		No	No	1910	1910	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
621 S CALUMET ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
505 S VIRGINIA AVE		No	No	1960	1960	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
603 S VIRGINIA AVE		No	No	1941	1941	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
503 S VIRGINIA AVE		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
105 S GRAY ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
803 E COLLEGE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
905 E COLLEGE ST		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
514 E COLLEGE ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
519 S FUTURE ST		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
517 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
509 S FUTURE ST		No	No	1962	1962	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
404 S FUTURE ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
520 S FUTURE ST		No	No	1922	1922	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
518 S FUTURE ST		No	No	1950	1950	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
401 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
402 S FUTURE ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
601 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
417 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
407 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
408 S FUTURE ST		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
706 S CALUMET ST		No	No	1938	1938	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
606 S HADFIELD ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
609 S HADFIELD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
607 S HADFIELD ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
613 S HADFIELD ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
601 E HEMINGWAY DR		No	No	1958	1958	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
610 S HADFIELD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
607 S FUTURE ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
606 S FUTURE ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
605 S FUTURE ST		No	No	1956	1956	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
604 S FUTURE ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
603 S FUTURE ST		No	No	1957	1957	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
602 S FUTURE ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
601 S HADFIELD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
603 S HADFIELD ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
602 S HADFIELD ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
604 S HADFIELD ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
815 E MAIN ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
600 S HADFIELD ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1115 E MAIN ST		No	Yes	2024	2024	Maintenance Records	Plastic	P	C	NL	Y	9/4/2024	Yes	9/4/2024	C	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
415 E COLLEGE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1605 E PICKETT LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
412 E COLLEGE ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
515 E MARION ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
509 E MARION ST		No	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1821 COLONIAL DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1800 ROYE LN		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1712 GEORGE SIMS RD		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1805 COLONIAL DR		No	No	2017	2017	Construction Records	Plastic	P	C	NL	N	N/R	No		No		
1803 ROYE LN		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
104 E TIMBERLINE RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1802 ROYE LN		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
112 SYCAMORE LN		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1904 S MARKET ST		No	No	2021	1978	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1801 ROYE LN		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1700 E BOYTON ST #D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1803 COLONIAL DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1700 E BOYTON ST #C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
701 MARY LYNN DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1203 GOLF COURSE RD		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1102 OAKWOOD LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1106 OAKWOOD LN		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1010 OAKWOOD LN		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1104 OAKWOOD LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1212 E BOYTON ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1111 CEDAR LN		No	No	1990	1990	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1003 TAMARACK LN		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
807 E FORD AVE		No	No	1971	1971	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
904 CEDAR LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1000 CEDAR LN		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
902 CEDAR LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1012 HILLCREST DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1113 CEDAR LN		No	No	1990	1990	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
802 E FORD AVE		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
901 HILLCREST DR		No	No	1969	1969	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
805 E FORD AVE		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1100 CEDAR LN		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
903 CEDAR LN		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
906 HILLCREST DR	LP1A045	No	No	1967	1967	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1205 S HADFIELD ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
903 HILLCREST DR		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1213 & 1211 E BOYTON ST		No	No	1974	1974	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1501 CARDINAL DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2502 SADDLE LN		No	No	1999	1999	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Galvanized Requiring Replacement (GRR) Unknown (U) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
107 VALENTINE LN		No	No	2019	2000	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
2800 E HICKORY LN		No	No	1995	1995	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No		
1708 GEORGE SIMS RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1505 CARDINAL DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2300 S MARKET ST		No	No	2021	1910	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
2706 E HICKORY LN		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1702 E BOYTON ST #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
2700 S MARKET ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No		
1305 GOLF COURSE RD		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
1701 EASY ST #A		No	No	2012	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1503 GOLF COURSE RD		No	No	1978	1978	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No		
2501 S MARKET ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
3102 S MARKET ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
3300 S MARKET ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
3005 S MARKET ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
800 MOUNTAINEER LN #D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
800 MOUNTAINEER LN #C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
2706 WINTERS LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2705 WINTERS LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2400 S MARKET ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
3401 S MARKET ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1406 RIDGEVIEW DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
910 FAIRLANE DR		No	No	1976	1976	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
802 GOLF COURSE RD		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1814 COLONIAL DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2703 S MARKET ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3801 S MARKET ST		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1811 COLONIAL DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1701 EASY ST #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3100 S MARKET ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 CARDINAL DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1403 GOLF COURSE RD		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1905 S MARKET ST		No	No	2021	1940	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1404 GOLF COURSE RD		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2704 HICKORY LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
802 MOUNTAINEER LN #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
201 1/ E TIMBERLINE RD		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2506 SADDLE LN		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
100 GOLF COURSE RD		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2702 HICKORY LN		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1800 E BOYTON ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1407 GOLF COURSE RD		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
102 VALENTINE LN		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1506 E BOYTON ST #D		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
105 VALENTINE LN		No	No	1997	1997	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
703 MARY LYNN DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1710 GEORGE SIMS RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1701 WINCHESTER CT		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1809 COLONIAL DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1813 COLONIAL DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1806 COLONIAL DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1700 EASY ST #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1700 EASY ST #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
904 OLD CREAL SPRINGS RD "Empty Lot"		No	No	1970	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1700 EASY ST #D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2306 SPRING LN		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3204 OLD CREAL SPRINGS RD		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3202 OLD CREAL SPRINGS RD		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1700 EASY ST #C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
902 RIX DR		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1802 EAGLE DR		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1808 COLONIAL DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 WINCHESTER CT		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
800 MOUNTAINEER LN #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1009 KIMBERLY CT		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2601 HICKORY LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Non-Lead (NL) Unknown (U) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1701 COLONIAL DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
3301 S MARKET ST		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
2800 OLD CREAL SPRINGS RD		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
3000 OLD CREAL SPRINGS RD		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
2509 RAE ALAN LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2701 HICKORY LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2603 HICKORY LN		No	No	2002	2002	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1403 CARDINAL DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
1702 E BOYTON ST #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
2880 S MARKET ST		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
2507 RAE ALAN LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
3606 OLD CREAL SPRINGS RD		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1506 E BOYTON ST #F		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1503 E BOYTON ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
1504 E BOYTON ST #E		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1807 COLONIAL DR		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1702 EASY ST #A		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1506 E BOYTON ST #E		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1703 EASY ST #B		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1702 EASY ST #B		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1701 EASY ST #C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
2304 AUTUMN LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1506 E BOYTON ST #C		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
605 OLD CREAL SPRINGS RD #C		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1805 EAGLE DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1703 EASY ST #A		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
3303 S MARKET ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1506 E BOYTON ST #B		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1506 E BOYTON ST #A		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2700 SUMMER LN		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2300 AUTUMN LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3200 S MARKET ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
605 OLD CREAL SPRINGS RD #A		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2207 AUTUMN LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1007 KIMBERLY CT		No	No	1974	1974	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1804 EAGLE DR		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1806 EAGLE DR		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
3101 S MARKET ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
108 SYCAMORE LN		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
107 SYCAMORE LN		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1508 E BOYTON ST #A		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1508 E BOYTON ST #B		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
800 MOUNTAINEER LN #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
401 OLD CREAL SPRINGS RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1204 LINCOLN DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1205 LINCOLN DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1100 E BOYTON ST #C&D		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1002 KIMBERLY CT B		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1100 E BOYTON ST #A		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
803 CEDAR LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1206 LINCOLN DR		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1203 LINCOLN DR		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1100 E BOYTON ST #B		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
801 CEDAR LN		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1012 KIMBERLY CT		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1508 E BOYTON ST #D		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1508 E BOYTON ST #C		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2602 OLD CREAL SPRINGS RD		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2505 OLD CREAL SPRINGS RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2203 OLD CREAL SPRINGS RD		No	No	2000	2000	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2303 AUTUMN LN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 E BOYTON ST #F		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2205 AUTUMN LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2702 SUMMER LN		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3602 S MARKET ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1213 ANDERSON DR		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
607 VINEWOOD LN		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1003 KIMBERLY CT		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 KIMBERLY CT A		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1004 KIMBERLY CT B		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1008 KIMBERLY CT		No	No	1974	1974	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1015 KIMBERLY CT		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1005 KIMBERLY CT		No	No	1974	1974	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1011 KIMBERLY CT		No	No	1975	1975	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
210 DINAH LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
203 DINAH LN		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1013 KIMBERLY CT		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1010 KIMBERLY CT		No	No	1977	1977	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
800 CEDAR LN		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
801 VINEWOOD LN		No	No	1971	1971	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
205 DINAH LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
602 CEDAR LN		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
702 CEDAR LN		No	No	1968	1968	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
704 CEDAR LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 CEDAR LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
703 CEDAR LN		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
201 DINAH LN		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
204 DINAH LN		No	No	1986	1986	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
202 DINAH LN		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2003 OLD CREAL SPRINGS RD		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2901 OLD CREAL SPRINGS RD		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
800 MARY LYNN DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2307 SPRING LN		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
907 FAIRLANE DR		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
906 FAIRLANE DR		No	No	1969	1969	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
912 FAIRLANE DR		No	No	1969	1969	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
914 FAIRLANE DR		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1002 OLD CREAL SPRINGS RD		No	No	1987	1987	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1701 OLD CREAL SPRINGS RD		No	No	1976	1976	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
904 FAIRLANE DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
905 FAIRLANE DR		No	No	1969	1969	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 FAIRLANE DR		No	No	1976	1976	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
2400 CARRIAGE LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2801 OLD CREAL SPRINGS RD		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
905 OLD CREAL SPRINGS RD		No	No	1953	1953	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
902 OLD CREAL SPRINGS RD		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
803 OLD CREAL SPRINGS RD		No	No	1969	1969	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
507 OLD CREAL SPRINGS RD		No	No	1948	1948	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
509 OLD CREAL SPRINGS RD		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
600 OLD CREAL SPRINGS RD		No	No	1945	1945	Visual Inspection	Unknown	G	P	NL	N	N/R	No		No		
504 OLD CREAL SPRINGS RD		No	No	2024	1960	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
505 OLD CREAL SPRINGS RD		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
617 VINEWOOD LN		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
707 VINEWOOD LN		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
700 CEDAR LN		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1203 ANDERSON DR		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
613 VINEWOOD LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
614 VINEWOOD LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
703 VINEWOOD LN		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
615 VINEWOOD LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
611 VINEWOOD LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
705 VINEWOOD LN		No	No	1972	1972	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 VINEWOOD LN		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
619 VINEWOOD LN		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1211 ANDERSON DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1207 ANDERSON DR		No	No	1975	1975	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
600 CEDAR LN		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1210 ANDERSON DR		No	No	1976	1976	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1205 ANDERSON DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1206 ANDERSON DR		No	No	2024	2024	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
1202 ANDERSON DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1212 ANDERSON DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1806 E MAIN ST		No	No	1973	1973	Survey Response	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
601 CEDAR LN		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1011 HILLCREST DR		No	No	1967	1967	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1703 E MAIN ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
7671 MOAKE SCHOOL RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2200 OLD CREAL SPRINGS RD		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2202 OLD CREAL SPRINGS RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1800 WREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1809 MULLIGAN DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 COLONIAL DR		No	No	2003	2003	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1605 OLD CREAL SPRINGS RD		No	No	1973	1973	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1817 COLONIAL DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1815 COLONIAL DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1810 COLONIAL DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1812 COLONIAL DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1803 MULLIGAN DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1809 WREN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1804 WREN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1805 WREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 CARDINAL DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 COLONIAL DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1801 MULLIGAN DR		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1800 EAGLE DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2204 OLD CREAL SPRINGS RD		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2408 CARRIAGE LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2509 SADDLE LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2501 SADDLE LN		No	No	2002	2002	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2503 SADDLE LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2301 AUTUMN LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
3911 OLD CREAL SPRINGS RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2406 CARRIAGE LN		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2700 HICKORY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2305 AUTUMN LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2206 AUTUMN LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2304 SPRING LN		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2703 E HICKORY LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2503 RAE ALAN LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2802 E HICKORY LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2809 E HICKORY LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2807 E HICKORY LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2504 SADDLE LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2508 SADDLE LN		No	No	2001	2001	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2506 RAE ALAN LN		No	No	2000	2000	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2508 RAE ALAN LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2505 RAE ALAN LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2510 RAE ALAN LN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
204 VALENTINE LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2402 CARRIAGE LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2403 S CARRIAGE LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2302 AUTUMN LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2501 RAE ALAN LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2705 HICKORY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2707 E HICKORY LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2805 E HICKORY LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2803 E HICKORY LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2600 HICKORY LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2801 HICKORY LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2404 CARRIAGE LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2703 SUMMER LN		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1603 OLD CREAL SPRINGS RD		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 E BOYTON ST #D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2105 E MAIN ST FRONTAGE		No	No	1948	1948	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1803 E BOYTON ST		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
607 OLD CREAL SPRINGS RD #D		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
605 OLD CREAL SPRINGS RD #B		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
607 OLD CREAL SPRINGS RD #C		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
607 OLD CREAL SPRINGS RD #B		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2707 SUMMER LN		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2708 SUMMER LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
605 OLD CREAL SPRINGS RD #D		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
607 OLD CREAL SPRINGS RD #A		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 E BOYTON ST #B		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 E BOYTON ST #D		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2700 OLD CREAL SPRINGS RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1305 CARDINAL DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1005 GOLF COURSE RD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1808 EAGLE DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2200 AUTUMN LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2202 AUTUMN LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2706 SUMMER LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 E BOYTON ST #A		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2704 SUMMER LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1504 E BOYTON ST #C		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
802 MOUNTAINEER LN #D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1700 E BOYTON ST #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
802 MOUNTAINEER LN #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1700 E BOYTON ST #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1702 EASY ST #D		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1702 EASY ST #C		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1703 EASY ST #D		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1703 EASY ST #C		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2701 OLD CREAL SPRINGS RD		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2705 SUMMER LN		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2702 WINTERS LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2703 WINTERS LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 CARDINAL DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2704 WINTERS LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 E BOYTON ST #C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1503 RIDGEVIEW DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 RIDGEVIEW DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 RIDGEVIEW DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2204 AUTUMN LN		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1801 COLONIAL DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 GOLF COURSE RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1405 GOLF COURSE RD		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
705 GOLF COURSE RD		No	No	1943	1943	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2600 OLD CREAL SPRINGS RD #REAR		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1807 EAGLE DR		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1703 OLD CREAL SPRINGS RD		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1801 OLD CREAL SPRINGS RD		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2314 SPRING LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2308 SPRING LN		No	No	1987	1987	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2301 SPRING LN		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2903 OLD CREAL SPRINGS RD		No	No	1977	1977	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
3102 OLD CREAL SPRINGS RD		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2309 SPRING LN		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2303 SPRING LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2302 SPRING LN		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2900 OLD CREAL SPRINGS RD		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2311 SPRING LN		No	No	1981	1981	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2300 SPRING LN		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2305 SPRING LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2313 SPRING LN		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2310 SPRING LN		No	No	1984	1984	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
2203 AUTUMN LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2312 SPRING LN		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2315 SPRING LN		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2201 AUTUMN LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1801 E BOYTON ST		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1204 ANDERSON DR		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2101 OLD CREAL SPRINGS RD		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
902 VINEWOOD LN #E		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
902 VINEWOOD LN #C		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
902 VINEWOOD LN #D		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2606 OLD CREAL SPRINGS RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
902 VINEWOOD LN #B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
902 VINEWOOD LN #A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1804 COLONIAL DR		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1802 WREN DR		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1801 EAGLE DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1803 EAGLE DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
3907 S MARKET ST		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
3703 S MARKET ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1214 ANDERSON DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
703 OLD CREAL SPRINGS RD		No	No	1935	1935	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1705 E MAIN ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1006 KIMBERLY CT A		No	No	1970	1970	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1813 MULLIGAN DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1002 TAMARACK LN		No	No	1967	1967	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1802 E MAIN ST		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 LOREN AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1006 KIMBERLY CT B		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1005 HILLCREST DR		No	No	1964	1964	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
2103 OLD CREAL SPRINGS RD		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1103 OAKWOOD LN		No	No	1991	1991	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1104 TAMARACK LN		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1108 CEDAR LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1001 CEDAR LN		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
2111 E MAIN ST FRONTAGE		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2201 OLD CREAL SPRINGS RD		No	No	1979	1979	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1816 COLONIAL DR		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1815 MULLIGAN DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1105 OAKWOOD LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1101 OAKWOOD LN		No	No	1997	1997	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1104 CEDAR LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1005 LOREN AVE		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1102 TAMARACK LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1701 E MAIN ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1804 MULLIGAN DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2703 OLD CREAL SPRINGS RD		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1818 COLONIAL DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1900 COLONIAL DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3906 S MARKET ST		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
3502 S MARKET ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
201 E TIMBERLINE RD		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3701 S MARKET ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
4005 S MARKET ST		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
4000 S MARKET ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
604 GOLF COURSE RD		No	No	2024	2000	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
504 GOLF COURSE RD		No	No	1998	1998	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1811 MULLIGAN DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1405 CARDINAL DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
807 E BOYTON ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
902 FAIRLANE DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
109 SYCAMORE LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
105 SYCAMORE LN		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3203 S MARKET ST		No	No	1972	1972	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
3604 S MARKET ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2900 S MARKET ST		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2502 RAE ALAN LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2105 OLD CREAL SPRINGS RD		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1803 OLD CREAL SPRINGS RD		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
2605 OLD CREAL SPRINGS RD		No	No	1976	1976	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
2205 OLD CREAL SPRINGS RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2603 OLD CREAL SPRINGS RD		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2601 OLD CREAL SPRINGS RD		No	No	1962	1962	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1402 GOLF COURSE RD		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
110 E TIMBERLINE RD		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1400 GOLF COURSE RD		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1406 GOLF COURSE RD		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
204 E TIMBERLINE RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
602 GOLF COURSE RD		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1301 GOLF COURSE RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2301 OLD CREAL SPRINGS RD		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2501 OLD CREAL SPRINGS RD		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1500 GOLF COURSE RD		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
2303 OLD CREAL SPRINGS RD		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1808 MULLIGAN DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1000 OLD CREAL SPRINGS RD		No	No	1984	1984	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1805 E MAIN ST #REAR		No	No	1950	1950	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1807 E MAIN ST #10		No	No	1953	1953	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1504 E MAIN ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2106 E MAIN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
103 VALENTINE LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1715 E MAIN ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2105 OLD E MAIN ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2101 E MAIN ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1211 LINCOLN DR		No	No	1971	1971	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1212 LINCOLN DR		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1213 LINCOLN DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
805 VINEWOOD LN		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1214 LINCOLN DR		No	No	1971	1971	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1215 LINCOLN DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
802 VINEWOOD LN		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1210 LINCOLN DR		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1209 LINCOLN DR		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1207 LINCOLN DR		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1002 LOREN AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
802 MOUNTAINEER LN #C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1208 LINCOLN DR		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
900 E BOYTON ST		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
201 TIMBERLINE RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1805 E MAIN ST #4		No	No	1953	1953	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
1800 E MAIN ST		No	No	1975	1975	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1706 E MAIN ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1702 E MAIN ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
604 OLD CREAL SPRINGS RD		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1807 E MAIN ST #8		No	No	1953	1953	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1700 E MAIN ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1805 E MAIN ST #1		No	No	1953	1953	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
1805 E MAIN ST #3		No	No	1953	1953	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
1805 E MAIN ST #5		No	No	1953	1953	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
1805 E MAIN ST #2		No	No	1953	1953	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
1004 TAMARACK LN		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
3304 OLD CREAL SPRINGS RD		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3402 OLD CREAL SPRINGS RD		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
803 MARY LYNN DR		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
805 MARY LYNN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
903 RIX DR		No	No	2023	1976	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1509 E BOYTON ST		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
704 MARY LYNN DR		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
705 MARY LYNN DR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
1601 E BOYTON ST		No	No	2023	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
904 RIX DR		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
702 MARY LYNN DR		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
907 RIX DR		No	No	2024	1978	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
2504 RAE ALAN LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 CRANE LN		No	No	1964	1964	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1701 EASY ST #D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2001 OLD CREAL SPRINGS RD		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1903 E BOYTON ST		No	No	1976	1976	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1701 E BOYTON ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1501 E BOYTON ST		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1405 E BOYTON ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1002 KIMBERLY CT A		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
906 RIX DR		No	No	1979	1979	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
909 RIX DR		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
905 RIX DR		No	No	2024	1975	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
912 RIX DR		No	No	1976	1976	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 RIX DR		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1006 TAMARACK LN		No	No	1967	1967	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1003 HILLCREST DR		No	No	1968	1968	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
905 HILLCREST DR		No	No	1969	1969	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1109 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
802 S HADFIELD ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
101 CHASE LN		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
100 CHASE LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1207 S HADFIELD ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
903 E BOYTON ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1804 E MAIN ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1201 S HADFIELD ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
806 E BOYTON ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1006 OAKWOOD LN		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1008 OAKWOOD LN		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1007 OAKWOOD LN		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1109 OAKWOOD LN		No	No	1993	1993	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1004 OAKWOOD LN		No	No	1977	1977	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1005 OAKWOOD LN		No	No	1972	1972	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1200 E HANCOCK CT		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1100 OAKWOOD LN		No	No	1995	1995	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1009 OAKWOOD LN		No	No	1972	1972	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1015 TAMARACK LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1003 OAKWOOD LN		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1709 E MAIN ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1803 WREN DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
111 TREGINA LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
106 TREGINA LN		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
116 TREGINA LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1708 E MAIN ST		No	No	1959	1959	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
1702 WINCHESTER CT		No	No	2001	2001	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
507 CEDAR LN		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1202 LINCOLN DR		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1706 E WINCHESTER CT		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 WINCHESTER CT		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1707 E WINCHESTER CT		No	No	1997	1997	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1713 E MAIN ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
107 CHASE LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2500 SADDLE LN		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
110 CHASE LN		No	No	2007	2007	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
102 CHASE LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1804 ROYE LN		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 E WINCHESTER CT		No	No	2022	1996	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
108 CHASE LN		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
109 CHASE LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
104 CHASE LN		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1700 WINCHESTER CT		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1706 GEORGE SIMS RD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1208 ANDERSON DR		No	No	1974	1974	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
106 CHASE LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
103 TREGINA LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
105 TREGINA LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1801 E MAIN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
104 TREGINA LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
808 E MARSHALL ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
811 E MARSHALL ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
810 E MARSHALL ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
813 E MARSHALL ST		No	No	1992	1992	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1000 HILLCREST DR		No	No	1967	1967	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1101 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1206 S HADFIELD ST		No	No	1991	1991	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1103 S PEMBERTON DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
815 E MARSHALL ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1106 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1807 E MAIN ST		No	No	1953	1953	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1107 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1104 S PEMBERTON DR		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1000 TAMARACK LN	LP1A046	No	No	1967	1967	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
109 TREGINA LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
200 DINAH LN		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
206 DINAH LN		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1007 TAMARACK LN		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
209 DINAH LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	G	NL	N	N/R	No		No		
903 OLD CREAL SPRINGS RD #A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
905 VINEWOOD LN #1-8		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
112 TREGINA LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
113 TREGINA LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1111 S PEMBERTON DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1108 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1110 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 CARDINAL DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1112 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1114 S PEMBERTON DR		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
103 CHASE LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
104 TREGINA LN #SPRIN		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1900 E MAIN ST		No	No	2007	2007	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1710 E MAIN ST		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1001 HILLCREST DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1004 HILLCREST DR		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1014 TAMARACK LN		No	No	1995	1995	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1614 E MAIN ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
901 VINEWOOD LN #1-8		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 E MAIN ST #REAR		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1206 EVERGREEN PL		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1203 EVERGREEN PL		No	No	1963	1963	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
901 S HADFIELD ST	LP1A042	No	No	1960	1960	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
902 S HADFIELD ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
904 S HADFIELD ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
900 S HADFIELD ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1103 S HADFIELD ST		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1203 S HADFIELD ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1102 S HADFIELD ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1003 S HADFIELD ST		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1101 S HADFIELD ST		No	No	1971	1971	Maintenance Records	Copper	C	CLS	NL	N	N/R	No		No		
1005 S HADFIELD ST		No	No	1969	1969	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1200 S HADFIELD ST	LP1A044	No	No	1970	1970	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1202 S HADFIELD ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
807 E MARSHALL ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
809 E MARSHALL ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1002 S PEMBERTON DR		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
OLD CREAL SPRINGS RD MARION MOBILE HOME		No	No	1980	1980	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1008 HILLCREST DR		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1005 TAMARACK LN		No	No	1967	1967	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1007 HILLCREST DR		No	No	1968	1968	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1102 CEDAR LN		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1005 CEDAR LN		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1003 CEDAR LN		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1105 CEDAR LN		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1010 HILLCREST DR		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1107 CEDAR LN		No	No	1994	1994	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1103 CEDAR LN		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1109 CEDAR LN		No	No	2020	1990	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1600 E BOYTON ST		No	No	1964	1964	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1001 S PEMBERTON DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
800 E FORD AVE		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
804 E FORD AVE		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
905 S HADFIELD ST		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
806 E FORD AVE		No	No	1971	1971	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1004 S HADFIELD ST		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L)							
1003 S PEMBERTON DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1008 TAMARACK LN		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1000 LOREN AVE		No	No	1989	1989	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
902 HILLCREST DR		No	No	1967	1967	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1002 HILLCREST DR		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1003 LOREN AVE		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1009 HILLCREST DR		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1101 E BOYTON ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1204 E BOYTON ST		No	No	1966	1966	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1206 E BOYTON ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1202 E BOYTON ST #1-4		No	No	1964	1964	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1013 TAMARACK LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1010 TAMARACK LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
901 CEDAR LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1016 TAMARACK LN		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
107 TREGINA LN		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
903 OLD CREAL SPRINGS RD #D		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
204 VALENTINE LN #SPRINK		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1505 E BOYTON ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
105 CHASE LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2103 E MAIN ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
603 OLD CREAL SPRINGS RD		No	No	1930	1930	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
111 SYCAMORE LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1300 E MAIN ST		No	No	2012	2012	Construction Records	Copper	C	C	NL	N	N/R	No		No		
1002 OAKWOOD LN		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1208 E BOYTON ST		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
207 DINAH LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1805 ROYE LN		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1100 TAMARACK LN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
806 E MARSHALL ST		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
802 E MARSHALL ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
804 E MARSHALL ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
803 E MARSHALL ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
801 E MARSHALL ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
805 E MARSHALL ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1105 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1102 S PEMBERTON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1210 E BOYTON ST		No	No	1967	1967	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1704 E MAIN ST		No	No	1959	1959	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1011 TAMARACK LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2801 E BRIDLE LN		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
913 E BOYTON ST		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
909 E BOYTON ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
907 E BOYTON ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
905 E BOYTON ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
808 E BOYTON ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
805 E BOYTON ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
803 E BOYTON ST		No	No	1964	1964	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1200 EVERGREEN PL		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1202 EVERGREEN PL		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1201 EVERGREEN PL		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
911 E BOYTON ST		No	No	1967	1967	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
207 E UNION ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
106 N MECHANIC ST		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
202 N FAIR ST		No	No	1915	1915	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
110 E GOODALL ST 1-3		No	No	1904	1904	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
721 E UNION ST		No	No	1885	1885	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
111 N MADISON ST		No	No	2017	2017	Construction Records	Plastic	P	C	NL	N	N/R	No		No		
201 N GARFIELD ST 1-4		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
301 N GARFIELD ST		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
403 N WASHINGTON ST		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
611 N MADISON ST		No	No	2016	2016	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
703 E BOULEVARD ST		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
606 N GARFIELD ST A		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
705 E BOULEVARD ST		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
710 N GARFIELD ST		No	No	1915	1915	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
107 E GOODALL ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
703 N WASHINGTON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
112 E JEFFERSON ST A-C		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
808 N WASHINGTON ST		No	No	1901	1901	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
400 E BOULEVARD ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
208 E JACKSON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
108 E MAIN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
303 N GARFIELD ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
107 N LILLIAN ST		No	No	1945	1945	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
104 N BUCHANAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
305 N GARFIELD ST		No	No	1900	1900	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No		
702 N HARPER ST		No	No	1920	1920	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
700 E MAIN ST		No	No	1900	1900	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
606 N GARFIELD ST B		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
809 N GARFIELD ST #C		No	No	1982	1982	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
701 N HARPER ST		No	Yes	2024	2024	Maintenance Records	Copper	C	P	NL	Y	9/4/2024	Yes	9/4/2024	C	No	
110 E MAIN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
703 N MADISON ST		No	No	1955	1955	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
406 N FAIR ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
101 N FAIR ST		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
404 E JACKSON ST 1-2		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
108 E BOULEVARD ST		No	No	1898	1898	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
607 N LOGAN ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
724 N HARPER ST	LP1C003	No	Yes	2024	2024	Maintenance Records	Plastic	P	P	NL	Y	9/4/2024	Yes	9/4/2024	P	No	
725 N HARPER ST		No	Yes	2024	2024	Maintenance Records	Copper	C	P	NL	Y	9/4/2024	Yes	9/4/2024	C	No	
306 E CALVERT ST		No	No	1980	1980	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
900 N LOGAN ST 1		No	No	1983	1983	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
404 N WASHINGTON ST		No	No	1981	1981	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
404 N WASHINGTON ST A REAR		No	No	1981	1981	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
404 N WASHINGTON ST B REAR		No	No	1981	1981	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
802 N LOGAN ST		No	No	2019	1900	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
504 E BOULEVARD ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
718 N LOGAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
809 N GARFIELD ST #B		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
402 N OTIS ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
406 N WASHINGTON ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
406 N WASHINGTON ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
604 E BOULEVARD ST		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
406 E JEFFERSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
502 N GARFIELD ST #REAR		No	No	2022	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
212 E GOODALL ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
103 E CALVERT ST		No	No	2024	1965	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
301 N BUCHANAN ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
704 N WASHINGTON ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
704 N WASHINGTON		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
405 E BOULEVARD ST "Empty Lot"		No	No	1900	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
702 N WASHINGTON ST B		No	No	1982	1982	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
702 N WASHINGTON ST A		No	No	1982	1982	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
414 E MAIN ST		No	No	1953	1953	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
108 E JEFFERSON ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
608 N GARFIELD ST B		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
608 N GARFIELD ST A		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
604 N GARFIELD ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
900 N LOGAN ST #3		No	No	1983	1983	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
505 E BROWNING ST B		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
505 E BROWNING ST A		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
720 N HARPER ST		No	No	1920	1920	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
900 N LOGAN ST 2		No	No	1983	1983	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
900 N LOGAN ST #4		No	No	1983	1983	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
503 E BROWNING ST B		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
503 E BROWNING ST A		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
602 E BOULEVARD ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1701 DEW DROP DR		No	No	2013	2013	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1602 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1801 DEW DROP DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1100 HORIZON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1103 DAYBREAK DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1105 DAYBREAK DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1111 EARLY BIRD LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1102 HORIZON DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1104 HORIZON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1605 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1603 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1600 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1001 HORIZON DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1116 FOLGERS ST		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1104 DAYBREAK DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1102 GLORY LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1108 GLORY LN		No	No	2005	2005	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1109 DAYBREAK DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1100 GLORY LN		No	No	2005	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1102 DAYBREAK DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1117 FOLGERS ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1107 EARLY BIRD LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1110 FOLGERS ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1101 EARLY BIRD LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
911 INDEPENDENCE AVE #B		No	No	2009	2009	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1105 FOLGERS ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1104 FOLGERS ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
910 INDEPENDENCE AVE		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1106 FOLGERS ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1108 FOLGERS ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 KARRIS LN #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
911 INDEPENDENCE AVE #C		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
911 INDEPENDENCE AVE #A		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1304 KARRIS LN #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1304 KARRIS LN #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
810 NEW DAY WAY		No	No	1997	1997	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
908 INDEPENDENCE AVE #A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
909 INDEPENDENCE AVE		No	No	2006	2006	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 KARRIS LN #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 KARRIS LN #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 KARRIS LN #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
810 E DEYOUNG ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1401 GUARDIAN PLACE #C		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1311 E BOULEVARD ST A		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1311 E BOULEVARD ST B		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
907 INDEPENDENCE AVE #C		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
907 INDEPENDENCE AVE #A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
912 INDEPENDENCE AVE #C		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
912 INDEPENDENCE AVE #A		No	No	2006	2006	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1502 E PARHAM ST B		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
907 INDEPENDENCE AVE #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
912 INDEPENDENCE AVE #B		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1502 E PARHAM ST A		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1311 E BOULEVARD ST C		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
908 INDEPENDENCE AVE #C		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
908 INDEPENDENCE AVE #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
914 INDEPENDENCE AVE		No	No	1966	1966	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
913 INDEPENDENCE AVE		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
906 INDEPENDENCE AVE #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
906 INDEPENDENCE AVE A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1502 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1305 KARRIS LN #G		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1109 FOLGERS ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 KARRIS LN #H		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1303 KARRIS LN #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 KARRIS LN #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 FELTS DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1708 FELTS DR		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1813 DEW DROP DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1710 FELTS DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
805 NEW DAY WAY		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
802 N HARTKOPF ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1500 E PARHAM ST E		No	No	2024	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1313 E BOULEVARD ST C		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
803 N TAFT ST A		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1500 E PARHAM ST C		No	No	2024	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1313 E BOULEVARD ST B		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1500 E PARHAM ST B		No	No	2024	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1000 E REEVES ST B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1306 KARRIS LN #B		No	No	1989	1989	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
900 HORIZON DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1000 E REEVES ST A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
706 HORIZON DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
803 N TAFT ST B		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1218 N VAN BUREN ST D		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1703 N DAWN DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1803 N DAWN DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1901 N DAWN DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1218 N VAN BUREN ST C		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1801 N DAWN DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1109 E CARTER ST		No	No	1962	1962	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1503 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
1300 KARRIS LN #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
901 E BOULEVARD ST A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
901 E BOULEVARD ST B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1306 KARRIS LN #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
802 HORIZON DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
806 HORIZON DR		No	No	2002	2002	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
805 HORIZON DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1718 FELTS DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1716 FELTS DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1300 KARRIS LN #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1715 FELTS DR		No	No	2012	2012	Construction Records	Plastic	P	C	NL	N	N/R	No			No	
1302 KARRIS LN #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1304 KARRIS LN #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1302 KARRIS LN #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1302 KARRIS LN #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1304 KARRIS LN #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
803 N TAFT ST C		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
801 E DEYOUNG ST		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1108 EARLY BIRD LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1101 HORIZON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1105 HORIZON DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2002 CANDLESTICK LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1103 EARLY BIRD LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1106 EARLY BIRD LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1103 HORIZON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 GUARDIAN PLACE #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 GUARDIAN PLACE A		No	No	2006	2006	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 GUARDIAN PLACE #A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1313 E BOULEVARD ST A		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
806 NEW DAY WAY		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1507 DEW DROP DR		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
804 N RADCLIFFE ST A		No	No	2024	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1403 N MAGNOLIA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
903 MORNINGSIDE DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
801 MORNINGSIDE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1205 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2203 FIETSAM RD		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
804 N RADCLIFFE ST B		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
804 N RADCLIFFE ST C		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1301 E DEYOUNG ST		Yes	No	1966	1966	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1305 KARRIS LN #F		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
802 N RADCLIFFE ST B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 DEW DROP DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
903 INDEPENDENCE AVE #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
901 INDEPENDENCE AVE		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
905 INDEPENDENCE AVE #B		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
808 NEW DAY WAY		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
903 INDEPENDENCE AVE #A		No	No	2010	2010	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
905 INDEPENDENCE AVE #A		No	No	2006	2006	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 E PARHAM ST A		No	No	2024	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1500 E PARHAM ST F		No	No	2024	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1500 E PARHAM ST G		No	No	2024	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1811 DEW DROP DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 GUARDIAN PLACE #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 GUARDIAN PLACE #C		No	No	2006	2006	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
815 NEW DAY WAY		No	No	2012	2012	Construction Records	Plastic	P	C	NL	N	N/R	No		No		
1408 DEW DROP DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1305 KARRIS LN #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1300 KARRIS LN #A		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 E PARHAM ST D		No	No	2024	2005	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1524 BROEKING RD		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1522 BROEKING RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1512 BROEKING RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1803 DEW DROP DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1805 DEW DROP DR		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
808 HORIZON DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1809 DEW DROP DR		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
802 N RADCLIFFE ST A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
901 E BOULEVARD ST C		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
801 N TAFT ST #A		No	No	2024	2017	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
901 E BOULEVARD ST D		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1300 KARRIS LN #C		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1510 BROEKING RD		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1706 FELTS DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1514 BROEKING RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1014 E PATTON DR		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
902 HORIZON DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1901 DEW DROP DR		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
707 HORIZON DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 KARRIS LN #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
803 NEW DAY WAY		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 KARRIS LN #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 KARRIS LN #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 KARRIS LN #E		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 KARRIS LN #C		No	No	2008	2008	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 KARRIS LN #F		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1008 E PATTON DR		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1009 E PATTON DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1302 E PARHAM ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
1000 E GREGORY AVE		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1010 E PATTON DR		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
1005 E GREGORY AVE		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1109 GLORY LN		No	No	2007	2007	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No	No	
1106 GLORY LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
906 E THOMPSON ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No	No	
1107 E CARTER ST #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
912 E THOMPSON ST		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1303 N MAGNOLIA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1305 N MAGNOLIA DR		No	No	1995	1995	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1302 N FAIR ST D		No	No	2018	2018	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No	No	
1100 E GRIGGS ST B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1902 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
907 E CLARK ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
905 E CLARK ST A		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1203 AURELIA DR		No	No	1971	1971	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
905 E CLARK ST B		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1013 E PATTON DR		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
1001 E CLARK ST		No	No	1974	1974	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
1011 E PATTON DR		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
1003 E CLARK ST		No	No	1974	1974	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1012 E PATTON DR		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1004 N RADCLIFFE ST B		No	No	2013	2013	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1802 N FAIR ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
909 E CARTER ST C		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1210 E REEVES ST A		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
803 MORNINGSIDE DR		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1903 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
705 N FAIR ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1001 E CARTER ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
707 N OTIS ST		No	No	2022	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
800 E BROWNING ST C		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1100 DAYBREAK DR		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1201 N MC LAREN ST C		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1501 ERINBERRY LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
909 E CARTER ST A		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
909 E CARTER ST B		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2004 CALICO RD		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2003 CALICO RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 DAISY LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1400 DAISY LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1812 SPRING GARDEN RD		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1604 E WILLOW DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1516 E WILLOW DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
905 MORNINGSIDE DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
909 E CARTER ST D		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1804 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1004 N RADCLIFFE ST A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1100 E GRIGGS ST A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1210 E REEVES ST B		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1201 N MC LAREN ST E		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 WINDY HILL DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1412 E WILLOW DR		No	No	2003	2003	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1108 N FAIR ST B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
901 MORNINGSIDE DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1410 E WILLOW DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1108 N FAIR ST C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
804 AURORA LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1413 E WILLOW DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
800 MORNINGSIDE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1108 N FAIR ST A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1111 E GRIGGS ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1409 E WILLOW DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1108 N FAIR ST D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1411 E WILLOW DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
802 MORNINGSIDE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1203 E PARHAM ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 N FAIR ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
910 E THOMPSON ST		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1304 ARBICOLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1002 HORIZON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1308 ARBICOLA DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1409 PERSIMMON DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1511 E WILLOW DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1107 DAYBREAK DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1410 PERSIMMON DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1003 HORIZON DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1101 DAYBREAK DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1203 EARLY BIRD LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1304 BROEKING RD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1206 E DEYOUNG ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1214 E DEYOUNG ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1111 FOLGERS ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 N SMITH AVE		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1502 NATHAN DR		No	No	2004	2004	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1518 BROEKING RD		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1108 DAYBREAK DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1202 E DEYOUNG ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
817 NEW DAY WAY		No	No	1996	1996	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1104 GLORY LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1703 SMITH AVE		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1400 IVY DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1709 N SMITH AVE		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1405 PERSIMMON DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1407 PERSIMMON DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
804 NEW DAY WAY		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
903 E REEVES ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1504 E WILLOW DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1509 POSEY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1513 POSEY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1902 CALICO RD		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1602 POSEY ST		No	No	2004	2004	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1711 QUAIL RUN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1400 PERSIMMON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1419 E WILLOW DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1404 PERSIMMON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1406 PERSIMMON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1306 ARBICOLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1416 E WILLOW DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1807 REVELLE RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1417 E WILLOW DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1809 REVELLE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1421 E WILLOW DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
802 AURORA LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1418 E WILLOW DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 MELMAR DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1718 MELMAR DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1005 N WHITMAN DR #A		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1716 MELMAR DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
800 AURORA LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1710 MELMAR DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1300 NORMAN RD		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1504 NATHAN DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
511 MORNINGSIDE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
807 HORIZON DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
801 HORIZON DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
803 HORIZON DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1507 POSEY ST		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
804 HORIZON DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1310 ARBICOLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 ARBICOLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1007 E PATTON DR		No	No	1985	1985	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 N SMITH AVE		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1000 HORIZON DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1514 E WILLOW DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1411 PERSIMMON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1402 PERSIMMON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 SMITH AVE		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1105 EARLY BIRD LN		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1103 GLORY LN		No	No	2017	2017	Construction Records	Plastic	P	C	NL	N	N/R	No		No		
1512 E WILLOW DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1100 GLORY LN # Sprink		No	No	2005	2005	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1107 GLORY LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1105 GLORY LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
800 HORIZON DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1501 NATHAN DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1610 POSEY ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1707 N SMITH AVE		No	No	2002	2002	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1500 POSEY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 POSEY ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 POSEY ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1201 EARLY BIRD LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 N FAIR ST C		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1505 NATHAN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1207 EARLY BIRD LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1101 GLORY LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1105 E REEVES ST		No	No	1920	1920	Survey Response	Unknown	C	G	NL	N	N/R	No		No		
1901 SPRING GARDEN RD		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
708 HORIZON DR		No	No	1999	1999	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1715 MELMAR DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1110 EARLY BIRD LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 NATHAN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1005 N WHITMAN DR #C		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1005 N WHITMAN DR #B		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1107 E CARTER ST #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1510 POSEY ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
811 NEW DAY WAY		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1109 EARLY BIRD LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1112 FOLGERS ST		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1303 ARBICOLA DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 ARBICOLA DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1300 ARBICOLA DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1301 ARBICOLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Lead (L)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)					Copper - Lead Solder (CLS)		
		Yes (Y) or No (N)				Examples:	Lead (L)	Lead (L)	Lead (L)	Non-Lead (NL)				Plastic - PVC, HDPE, PEX (P)			
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead Service Line was replaced.		
							Unknown (U)	Unknown (U)	Unknown (U)								
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
1106 DAYBREAK DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
807 NEW DAY WAY		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
813 NEW DAY WAY		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1703 FELTS DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1306 BROEKING RD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1702 FELTS DR		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1113 FOLGERS ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1700 FELTS DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1114 FOLGERS ST		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1205 EARLY BIRD LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1802 CALICO RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2006 BUCKLEY RD		No	No	1999	1999	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2105 CANDLESTICK LN		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1407 N MAGNOLIA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1500 ERINBERRY LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 POSEY ST		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1506 POSEY ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1502 MATTHEW LN		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2103 CANDLESTICK LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1911 CALICO RD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1420 E WILLOW DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1406 N MAGNOLIA DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2006 CALICO RD		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 N FAIR ST B		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 N FAIR ST A		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1410 BROEKING RD #C		No	No	2011	2011	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1410 BROEKING RD #D		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1416 BROEKING RD #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1405 SUNFLOWER DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1709 OAKSHIRE RD		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1416 BROEKING RD #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2004 NORMAN RD		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1906 CALICO RD		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
804 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1908 CALICO RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1717 TWIN DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1909 CALICO RD		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1905 CALICO RD		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1803 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1901 N FAIR ST		No	No	2002	2002	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1805 N FAIR ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2006 SPRING GARDEN RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2000 GINGHAM CT		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 KARRIS LN #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2000 SPRING GARDEN RD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2004 CANDLESTICK LN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1902 SPRING GARDEN RD		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
900 MISSISSIPPI DR #D		No	No	2016	2016	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
606 N MC LAREN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1818 CALICO RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1612 POSEY ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1415 E WILLOW DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1805 N DAWN DR		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1903 N DAWN DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 E WILLOW DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1904 CALICO RD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1400 N MAGNOLIA DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 N MAGNOLIA DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1309 N MAGNOLIA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 N MAGNOLIA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1713 QUAIL RUN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2102 FIETSAM RD		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1903 CALICO RD		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
900 MISSISSIPPI DR #C		No	No	2016	2016	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2005 FIETSAM RD		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
900 MISSISSIPPI DR #B		No	No	2016	2016	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
900 MISSISSIPPI DR #A		No	No	2016	2016	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
906 E CARTER ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1201 N MC LAREN ST A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1604 DEW DROP DR		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
705 N MC LAREN ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
800 E BROWNING ST B		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
600 N MC LAREN ST		No	No	2022	1940	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1201 N MC LAREN ST B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
800 E BROWNING ST A		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1302 KARRIS LN #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 KARRIS LN #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1001 E GREGORY AVE		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1004 E GREGORY AVE		No	No	1977	1977	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
902 MORNINGSIDE DR		No	No	1991	1991	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1402 MATTHEW LN		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1517 E DEYOUNG ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1003 E GREGORY AVE		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
900 MORNINGSIDE DR		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1002 E GREGORY AVE		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1401 N GOLDENROD DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 IVY DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1609 POSEY ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1308 N MAGNOLIA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1505 E WILLOW DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1606 POSEY ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1614 POSEY ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1613 POSEY		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1615 POSEY		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1307 N MAGNOLIA DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
802 NEW DAY WAY		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
903 HORIZON DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1717 FELTS DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
901 HORIZON DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1713 FELTS DR		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1905 N FAIR ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1902 DEW DROP DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1712 FELTS DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1813 SPRING GARDEN RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2002 N DAWN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1800 SPRING GARDEN RD		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1400 N GOLDENROD DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1400 PRIMROSE LN		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
513 MORNINGSIDE DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1608 POSEY ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1402 PRIMROSE LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1402 IVY DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1200 E DEYOUNG ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
501 MORNINGSIDE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
706 MORNINGSIDE DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1506 BROEKING RD		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1010 E ILLINOIS ST		No	No	1975	1975	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
904 E BROWNING ST #C		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
904 E BROWNING ST D		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2004 GINGHAM CT		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1515 E WILLOW DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2001 CANDLESTICK LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1607 BROEKING RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2008 SPRING GARDEN RD		No	No	1997	1997	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1900 SPRING GARDEN RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1305 KARRIS LN #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1305 KARRIS LN #E		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1904 N FAIR ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2002 EMILY LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1410 BROEKING RD #A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2000 EMILY LN		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 NATHAN DR		No	No	2002	2002	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1608 POSEY ST #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1515 POSEY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1012 E CARTER ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
611 N MC LAREN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1002 N RADCLIFFE ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
505 MORNINGSIDE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1709 E DEYOUNG ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1604 ADAMS DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 E DEYOUNG ST #REAR		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
1503 E DEYOUNG ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1605 ADAMS DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
904 E BROWNING ST A		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1602 E WILLOW DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1406 DEW DROP DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1008 N RADCLIFFE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 N RADCLIFFE ST #C		No	No	2013	2013	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1106 PHEMISTER DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
809 E GREGORY AVE		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
705 N HARTKOPF ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1200 AURELIA DR		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2001 N DAWN DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2003 N DAWN DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1300 N MAGNOLIA DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1414 E WILLOW DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1513 E WILLOW DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1418 BROEKING RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
904 E BROWNING ST B		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1401 N MAGNOLIA DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
610 N MC LAREN ST A		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
701 N TAFT ST		No	No	1943	1943	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1511 POSEY ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 N DAWN DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1605 BROEKING RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2103 NORMAN RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1710 BROEKING RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 BROEKING RD		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1904 SPRING GARDEN RD		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 BROEKING RD		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2105 NORMAN RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1510 E WILLOW DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1905 N DAWN DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
509 MORNINGSIDE DR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
507 MORNINGSIDE DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1002 N RADCLIFFE ST A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1903 FIETSAM RD		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1200 N TAFT ST "Empty Lot"		No	No	1920	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
1202 AURELIA DR		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1610 ADAMS DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1605 POSEY ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1601 POSEY ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1703 DEW DROP DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
909 E DEYOUNG ST		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1702 OAKSHIRE RD		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1700 DEW DROP DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1607 POSEY ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1611 POSEY ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1506 E WILLOW DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1514 POSEY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1600 POSEY ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2107 CANDLESTICK LN		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2003 CANDLESTICK LN		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1704 OAKSHIRE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1706 OAKSHIRE RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1703 OAKSHIRE RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1705 OAKSHIRE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1508 POSEY ST		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1604 POSEY ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1812 DEW DROP DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2000 CANDLESTICK LN		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1806 SPRING GARDEN RD		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1805 SPRING GARDEN RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1803 SPRING GARDEN RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2006 EMILY LN		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2003 EMILY LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1804 DEW DROP DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1903 DEW DROP DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1807 DEW DROP DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1810 DEW DROP DR		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1207 AURELIA DR		No	No	1972	1972	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1505 N SMITH AVE		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1506 MATTHEW LN		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1206 AURELIA DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1205 AURELIA DR		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1399 MATTHEW LN		No	No	1991	1991	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1602 MATTHEW LN		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1600 MATTHEW LN		No	No	1980	1980	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
903 E CLARK ST C		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
904 E CLARK ST		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1104 E DULLE ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1604 MATTHEW LN		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1007 E CLARK ST		No	No	1975	1975	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1605 N SMITH AVE		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1603 N SMITH AVE		No	No	1977	1977	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1019 E PATTON DR		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1015 E PATTON DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1201 AURELIA DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1501 N SMITH AVE		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1502 N SMITH AVE		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1504 MATTHEW LN		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1204 AURELIA DR		No	No	1971	1971	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1020 E PATTON DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1401 MATTHEW LN		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1405 MATTHEW LN		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1017 E PATTON DR		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1501 MATTHEW LN		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1503 MATTHEW LN		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1018 E PATTON DR		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1016 E PATTON DR		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1403 MATTHEW LN		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
903 E CLARK ST A		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1404 MATTHEW LN		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1605 MATTHEW LN		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1601 N SMITH AVE		No	No	1976	1976	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
903 E CLARK ST B		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1006 N RADCLIFFE ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
903 E CLARK ST D		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1701 N SMITH AVE		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
906 E CLARK ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1400 MATTHEW LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1601 MATTHEW LN		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1507 MATTHEW LN		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1500 MATTHEW LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1500 SANDBAR DR		Yes	No	2012	2012	Construction Records	Copper	C	C	NL	N	N/R	No		No		
1501 E DEYOUNG ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
815 MISSISSIPPI DR		Yes	No	2012	2012	Construction Records	Copper	C	C	NL	N	N/R	No		No		
1201 N FAIR ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1515 E DEYOUNG ST		Yes	No	2012	2012	Construction Records	Copper	C	C	NL	N	N/R	No		No		
1501 SANDBAR DR		Yes	No	2012	2012	Construction Records	Copper	C	C	NL	N	N/R	No		No		
2007 GINGHAM CT		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2002 CALICO RD		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2003 GINGHAM CT		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
2009 SPRING GARDEN RD		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1606 E WILLOW DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 N SUNFLOWER DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)					Copper - No Lead Solder (C)		
	Yes (Y) or No (N)					Examples:	Lead (L)	Lead (L)	Lead (L)						Plastic - PVC, HDPE, PEX (P)		
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)						Cast/Ductile Iron or Transite (O)		
							Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)						Leave blank if no Lead Service Line was replaced.		
							Unknown (U)	Unknown (U)	Unknown (U)								
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)								
1401 PRIMROSE LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1403 PRIMROSE LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1711 OAKSHIRE RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 QUAIL RUN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1709 FELTS DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1800 REVEILLE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
807 AURORA LN		No	No	1995	1995	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1704 QUAIL RUN		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1801 N FAIR ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1705 QUAIL RUN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1406 BROEKING RD		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1404 N MAGNOLIA DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
805 AURORA LN		No	No	1994	1994	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1802 REVEILLE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1806 REVEILLE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
800 E GREGORY AVE		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1803 REVEILLE RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1808 REVEILLE RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
901 E DEYOUNG ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2004 EMILY LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1707 OAKSHIRE RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
802 E GREGORY AVE		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
805 N RADCLIFFE ST		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1704 REVELLE RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2007 EMILY LN		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1700 OAKSHIRE RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 REVELLE RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1706 N FAIR ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1405 N MAGNOLIA DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1708 OAKSHIRE RD		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1402 N MAGNOLIA DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1409 BROEKING RD		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1710 OAKSHIRE RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1810 REVELLE RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
806 AURORA LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1402 N GOLDENROD DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
701 E DEYOUNG ST (car wash)		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1102 FOLGERS ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1201 N MC LAREN ST D		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
704 N OTIS ST		No	No	2022	1910	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1405 DEW DROP DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1407 DEW DROP DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
905 E CLARK ST D		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
905 E CLARK ST C		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1804 SPRING GARDEN RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1709 MELMAR DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1810 SPRING GARDEN RD		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1811 SPRING GARDEN RD		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1906 NORMAN RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1802 SPRING GARDEN RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1712 QUAIL RUN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1204 E REEVES ST A		No	No	2019	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1204 E REEVES ST B		No	No	2019	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1006 E DICKINSON DR		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
607 N OTIS ST		No	No	2022	1940	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
805 MORNINGSIDE DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1811 CALICO RD		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1820 CALICO RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1816 CALICO RD		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1814 CALICO RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1813 CALICO RD		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1708 QUAIL RUN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1710 QUAIL RUN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1812 CALICO RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1809 SPRING GARDEN RD		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1810 CALICO RD		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1804 CALICO RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1808 SPRING GARDEN RD		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1806 CALICO RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1808 CALICO RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1809 CALICO RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
811 MORNINGSIDE DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
807 MORNINGSIDE DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
809 MORNINGSIDE DR		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1700 MELMAR DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1708 MELMAR DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1701 MELMAR DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1707 MELMAR DR		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1705 MELMAR DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 MELMAR DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1713 MELMAR DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1401 NATHAN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1407 NATHAN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1400 NATHAN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1405 NATHAN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 DEW DROP DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1409 NATHAN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2003 NORMAN RD		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1807 CALICO RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1805 CALICO RD		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1803 CALICO RD		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
908 E THOMPSON ST		No	No	2018	2018	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1709 QUAIL RUN		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 MELMAR DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1704 MELMAR DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1711 MELMAR DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1712 MELMAR DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2000 FRANCIS DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2003 FRANCIS DR		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1900 FRANCIS DR		No	No	1993	1993	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2007 FRANCIS DR		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1714 MELMAR DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1505 MATTHEW LN		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1003 E ILLINOIS ST		No	No	1977	1977	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1701 BROEKING RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1705 BROEKING RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1000 E DULLE ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1004 E DULLE ST		No	No	1977	1977	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1006 E GRIGGS ST C		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
904 E THOMPSON ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
705 N OTIS ST		No	No	2022	1950	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
902 E THOMPSON ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1300 E FAULKNER ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
800 E THOMPSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
808 E THOMPSON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
804 E THOMPSON ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1200 E FAULKNER ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1703 E DEYOUNG ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1004 E CLARK ST		No	No	1975	1975	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1006 E GRIGGS ST B		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1006 E GRIGGS ST D		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
703 N FAIR ST 2		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
807 E GREGORY AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	G	NL	N	N/R	No			No	
907 E GREGORY AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
908 E GREGORY AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
907 E THOMPSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
805 E THOMPSON ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
803 E THOMPSON ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
909 E GREGORY AVE		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
805 E GREGORY AVE		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	G	NL	N	N/R	No			No	
1202 N MC LAREN ST "Empty Lot"		No	No	1950	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
1204 N MC LAREN ST "Empty Lot"		No	No	1900	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
900 E CLARK ST		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1709 BROEKING RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
901 E GREGORY AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1407 BROEKING RD		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1707 BROEKING RD		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1703 BROEKING RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1109 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1002 E ILLINOIS ST		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
903 E GREGORY AVE		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
806 MORNINGSIDE DR		No	No	1990	1990	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1001 E ILLINOIS ST		No	No	1976	1976	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
904 E GREGORY AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1000 E ILLINOIS ST		No	No	1974	1974	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1006 E ILLINOIS ST		No	No	1974	1974	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
905 E GREGORY AVE		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
902 E GREGORY AVE		No	No	1989	1989	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1001 E DULLE ST		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1212 E CARTER ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1212 E CARTER ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
906 E GREGORY AVE		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1006 E CLARK ST		No	No	1976	1976	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
700 E DEYOUNG ST		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 E DEYOUNG ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1204 N FAIR ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1304 N FAIR ST B		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1206 N FAIR ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
903 E ILLINOIS ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
909 E MCKINLEY ST		No	No	2022	1955	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
803 E GREGORY AVE		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1304 N FAIR ST A		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
904 E MCKINLEY ST		No	No	2022	1972	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1205 N MC LAREN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
703 N FAIR ST 1		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
703 N FAIR ST 4		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1004 E GRIGGS ST 6		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1004 E GRIGGS ST 7		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
810 E GREGORY AVE		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1403 N MC LAREN ST		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
900 E GREGORY AVE		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1405 N MC LAREN ST		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
507 N OTIS ST		No	No	2022	1940	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1401 N MC LAREN ST		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
601 N OTIS ST		No	No	2022	1965	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1306 N FAIR ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
804 E GREGORY AVE		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1004 E GRIGGS ST 5		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
703 N FAIR ST 3		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
704 E DEYOUNG ST		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1407 N MC LAREN ST		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1206 E PARHAM ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1307 N MC LAREN ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
801 E GREGORY AVE		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
904 E ILLINOIS ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1305 N MC LAREN ST		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1706 BROEKING RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1708 BROEKING RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1604 BROEKING RD		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1515 BROEKING RD		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1215 E CARTER ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
905 E BROWNING ST		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
801 N FAIR ST		No	No	1958	1958	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1204 E PARHAM ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1707 E DEYOUNG ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1519 E DEYOUNG ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1606 ADAMS DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1616 ADAMS DR		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 BROEKING RD		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1516 BROEKING RD		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1304 E DEYOUNG ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1300 BROEKING RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
806 E GREGORY AVE		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1704 FELTS DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
905 E ILLINOIS ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1700 N SMITH AVE		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1002 E CLARK ST		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1006 E GRIGGS ST E		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1003 E DULLE ST		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1300 E DEYOUNG ST		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1302 BROEKING RD		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1602 BROEKING RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 E PARHAM ST		No	No	2007	2007	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1006 E GRIGGS ST F		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1005 E DULLE ST		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1602 N SMITH AVE		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 E ILLINOIS ST		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
902 N TAFT ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1115 FOLGERS ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1400 E BOULEVARD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	C	UNL	NL	N	N/R	No		No		
1002 E DULLE ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
804 MORNINGSIDE DR		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1600 N SMITH AVE		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1007 E ILLINOIS ST		No	No	1980	1980	Survey Response	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1006 E GRIGGS ST A		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1005 E ILLINOIS ST		No	No	1976	1976	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1009 E ILLINOIS ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1011 E ILLINOIS ST		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1214 E CARTER ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1102 N RADCLIFFE ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1214 E CARTER ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1102 N RADCLIFFE ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1000 E CLARK ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
1218 N VAN BUREN ST B		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1601 BROEKING RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
905 INDEPENDENCE AVE #C		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
915 N RADCLIFF ST		Yes	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1104 E REEVES ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1107 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1206 E REEVES ST A		No	No	2019	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1505 DEW DROP DR		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1403 PERSIMMON DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1404 NATHAN DR		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1503 NATHAN DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1301 NORMAN RD		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1206 E REEVES ST D		No	No	2019	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Non-Lead (NL) Unknown (U) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
801 E REEVES ST		Yes	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
803 AURORA LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No		
1601 DEW DROP DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1404 DEW DROP DR		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1307 N OTIS ST		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1701 OAKSHIRE RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
702 E BOULEVARD ST		Yes	No	1949	1949	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1202 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1206 E REEVES ST B		No	No	2019	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
1206 E REEVES ST C		No	No	2019	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
1100 N OTIS ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1900 NORMAN RD		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1409 E DEYOUNG ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No		
1106 E CARTER ST		No	No	1960	1960	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No		
1705 E DEYOUNG ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1701 E DEYOUNG ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1603 E DEYOUNG ST		No	No	1985	1985	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
1206 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
501 N MCLAREN ST A		No	No	2022	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
1001 E MCKINLEY ST #B		No	No	2022	1979	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
501 N MC LAREN ST #B		No	No	2022	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
1001 E MCKINLEY ST A		No	No	2022	1979	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
500 N FAIR ST B		No	No	2022	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1001 E MCKINLEY ST B		No	No	2022	1979	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
218 WILD ROSE LN A		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
218 WILD ROSE LN B		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
815 N MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1408 N LOGAN ST		No	No	2020	1921	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
501 E REEVES ST #B		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
501 E REEVES ST #D		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
501 E REEVES ST #C		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
211 WILD ROSE LN B		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
211 WILD ROSE LN A		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
412 N MARKET ST A		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1401 N GLENDALE ST B		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1819 BRIDGE ST		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1401 N GLENDALE ST D		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1401 N GLENDALE ST #A		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1401 N GLENDALE ST C		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
905 N MADISON ST		No	No	1940	1940	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
400 E DEYOUNG ST		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No			No	
1004 N MARKET ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
215 WILD ROSE LN A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
605 E CLARK ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
408 E REICHERT DR		No	No	1987	1987	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1218 N VAN BUREN ST A		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1401 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
308 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
212 RED ROW RD		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1109 N STATE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
314 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
115 E MC DONALD ST D		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1016 N GRANITE ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
216 WILD ROSE LN C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
504 E ILLINOIS ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1304 N LOGAN ST		No	No	2020	1960	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
1105 N MONROE ST A		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1105 N MONROE ST D		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1105 N MONROE ST B		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1302 N LOGAN ST		No	No	2020	1920	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1409 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
310 RED ROW RD		No	No	1966	1966	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
302 E DEYOUNG ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
208 WILD ROSE LN A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
208 WILD ROSE LN B		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
208 WILD ROSE LN C		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1707 N STATE ST A		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1105 N MONROE ST C		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1803 N STATE ST		No	No	1917	1917	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
400 E DEYOUNG ST #SPRIN		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
603 N MARKET ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
206 N MARKET ST		No	No	1961	1961	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
313 RED ROW RD		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
508 E CLARK ST		No	No	1972	1972	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1511 N GARFIELD ST A-D		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1510 N GARFIELD ST 1-4		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1305 N OTIS ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
207 E DEYOUNG ST		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
500 E DEYOUNG ST #BATH		Yes	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
401 E REICHERT DR 2		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
100 E DEYOUNG ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
907 N MARKET ST		No	No	1926	1926	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
400 MORNINGSIDE DR		Yes	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1101 N VAN BUREN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
115 E MC DONALD ST B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
115 E MC DONALD ST A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
115 E MC DONALD ST C		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1705 N STATE ST #A		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
217 RED ROW RD C		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
217 RED ROW RD B		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
318 GATEWAY RD		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1702 N STATE ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
217 RED ROW RD A		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1802 BRIDGE ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1806 BRIDGE ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1812 BRIDGE ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
217 WILD ROSE LN B		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
304 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
209 WILD ROSE LN A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
213 WILD ROSE LN A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
209 WILD ROSE LN B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
213 WILD ROSE LN B		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
215 WILD ROSE LN B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
209 WILD ROSE LN C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1714 N STATE ST A		No	No	2010	2010	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
306 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
180 WILD ROSE LN B		No	No	2015	2015	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
180 WILD ROSE LN A		No	No	2015	2015	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
216 WILD ROSE LN A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
214 WILD ROSE LN C		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
109 E MC DONALD ST D		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
414 E REICHERT DR		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
405 E REICHERT DR		No	No	2020	1977	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
406 E REICHERT DR		No	No	2020	1994	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
410 E REICHERT DR		No	No	2020	1978	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
181 WILD ROSE LN C		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
181 WILD ROSE LN A		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
183 WILD ROSE LN		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
203 WILD ROSE LN D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
412 E REICHERT DR		No	No	2020	1973	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
180 WILD ROSE LN C		No	No	2015	2015	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
206 WILD ROSE LN C		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
181 WILD ROSE LN B		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
203 WILD ROSE LN C		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
409 E REICHERT DR		No	No	2020	1976	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1811 BRIDGE ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1810 BRIDGE ST		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
109 E MC DONALD ST C		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
109 E MC DONALD ST B		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
214 WILD ROSE LN B		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
216 WILD ROSE LN B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
214 WILD ROSE LN A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1908 N STATE ST		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
109 E MC DONALD ST A		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
201 RED ROW RD		No	No	1924	1924	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
206 RED ROW RD		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1800 BRIDGE ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
207 RED ROW RD		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
415 E REICHERT DR		No	No	1979	1979	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
310 WHITNEY LN		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
217 WILD ROSE LN A		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
418 E REICHERT DR		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1714 N STATE ST B		No	No	2010	2010	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
318 RED ROW RD		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
309 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
105 W BOULEVARD ST		No	No	2019	1925	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1212 N LOGAN ST		No	No	2020	1940	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
204 WILD ROSE LN C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1304 N MARKET ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
204 WILD ROSE LN B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
107 W BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
217 RED ROW RD D		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1208 N LOGAN ST		No	No	2020	1929	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples:	Examples:	Examples:	Examples:							
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
		Examples:					Lead (L)	Lead (L)									
		Cast/Ductile Iron or Transite (O)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
		Plastic - PVC, HDPE, PEX (P)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
	Yes (Y) or No (N)					Unknown (U)	Unknown (U)	Unknown (U)						Plastic - PVC, HDPE, PEX (P)			
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						Cast/Ductile Iron or Transite (O)		
							Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						Leave blank if no Lead Service Line was replaced.		
218 RED ROW RD		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
215 RED ROW RD B		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
215 RED ROW RD D		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
215 RED ROW RD A		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1808 BRIDGE ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1804 BRIDGE ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
205 WILD ROSE LN C		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
419 E REICHERT DR		No	No	1978	1978	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1212 N MADISON ST A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
304 E CLARK ST		No	No	2019	1950	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
305 RED ROW RD		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
311 RED ROW RD		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1901 N JETER ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
318 WHITNEY LN		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1907 N JETER ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
302 RED ROW RD		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
304 RED ROW RD		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
213 WILD ROSE LN C		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
217 WILD ROSE LN C		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
215 WILD ROSE LN C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1311 N VAN BUREN ST		No	No	Unknown	Unknown	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1006 N STATE ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1209 N VAN BUREN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1403 N GARFIELD ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
504 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
303 E THOMPSON ST		No	No	1960	1960	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1400 N VAN BUREN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
201 W DEYOUNG ST		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
907 N GRANITE ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 N LOGAN ST #B		No	No	2020	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1307 N LOGAN ST #A		No	No	2020	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1902 N STATE ST		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2011 N STATE ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
107 E FINUCANE ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1010 N MARKET ST		No	No	1890	1890	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1311 N COURTNEY ST		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
207 WILD ROSE LN B		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
206 WILD ROSE LN A		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
204 WILD ROSE LN A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
207 WILD ROSE LN C		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
205 WILD ROSE LN A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
206 WILD ROSE LN B		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
205 WILD ROSE LN #B		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
207 WILD ROSE LN A		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1817 BRIDGE ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1806 N STATE ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1805 N STATE ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
301 RED ROW RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1804 N STATE ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1811 N STATE ST		No	No	1956	1956	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
220 RED ROW RD		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1813 N STATE ST		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
211 RED ROW RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1710 N STATE ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1708 N STATE ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
309 RED ROW RD		No	No	1990	1990	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1700 N STATE ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
310 GATEWAY RD		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1709 N STATE ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
302 GATEWAY RD		No	No	2012	2012	Construction Records	Plastic	P	C	NL	N	N/R	No			No	
300 GATEWAY RD		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
308 GATEWAY RD		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1607 N STATE ST		No	No	1954	1954	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
907 N STATE ST		No	No	1950	1950	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1604 N STATE ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
306 GATEWAY RD		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1608 N STATE ST		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1713 N STATE ST		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1606 N STATE ST		No	No	1919	2023	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
311 GATEWAY RD		No	No	1986	1986	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
309 GATEWAY RD		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
313 GATEWAY RD		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1706 N STATE ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
314 GATEWAY RD		No	No	1976	1976	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
316 GATEWAY RD		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1704 N STATE ST		No	No	1953	1953	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
312 GATEWAY RD		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
315 GATEWAY RD		No	No	2019	1978	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
304 GATEWAY RD		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1101 N MADISON ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
303 RED ROW RD		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1210 N MADISON ST B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1403 N GLENDALE ST A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1503 COLIN BRADLEY DR C		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1011 N STATE ST #B		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
216 RED ROW RD		No	No	2000	2000	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
209 RED ROW RD		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
215 RED ROW RD C		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
200 RED ROW RD		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1007 N GARFIELD ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1500 COLIN BRADLEY DR A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1500 COLIN BRADLEY DR B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 COLIN BRADLEY DR B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 COLIN BRADLEY DR A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
208 RED ROW RD		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
210 RED ROW RD		No	No	1969	1969	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1210 N MADISON ST A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
212 WILD ROSE LN A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1706 N STATE ST 1B		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 N STATE ST 1A		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 N STATE ST 2B		No	No	2003	2003	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 N STATE ST 3A		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1809 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
210 WILD ROSE LN B		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
212 WILD ROSE LN C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
512 VILLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1609 N STATE ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1808 N STATE ST B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1808 N STATE ST C		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1810 N STATE ST A		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Non-Lead (NL)	Galvanized Requiring Replacement (GRR) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1808 N STATE ST A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1212 N MADISON ST B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1810 N STATE ST B		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1902 SPILLERTOWN RD		No	No	1961	1961	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1808 N STATE ST D		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1610 N STATE ST		No	No	1924	1924	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1011 N STATE ST #A		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
506 VILLA DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1204 N GARFIELD ST #B		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
103 E MC DONALD ST		No	No	2013	2013	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
514 VILLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
508 VILLA DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
510 VILLA DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No		
1204 N GARFIELD ST #E		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1501 COLIN BRADLEY DR C		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1501 COLIN BRADLEY DR #D		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1204 N GARFIELD ST C		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1204 N GARFIELD ST #D		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1204 N GARFIELD ST #A		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
603 E CARTER ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
504 VILLA DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1508 CORNERSTONE CT B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1503 COLIN BRADLEY DR B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1508 CORNERSTONE CT A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1502 COLIN BRADLEY DR D		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1502 COLIN BRADLEY DR C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1503 COLIN BRADLEY DR A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 N STATE ST 3B		No	No	2003	2003	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
307 GATEWAY RD		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
212 WILD ROSE LN B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
210 WILD ROSE LN A		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1707 N STATE ST B		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
210 WILD ROSE LN C		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1706 N STATE ST 2A		No	No	2003	2003	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
305 GATEWAY RD		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1403 N GLENDALE ST D		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1403 N GLENDALE ST C		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1403 N GLENDALE ST B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1403 N GLENDALE ST E		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
202 CHESAPEAKE DR D		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1502 COLIN BRADLEY DR #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1502 COLIN BRADLEY DR #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1503 COLIN BRADLEY DR D		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
202 CHESAPEAKE DR E		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L)							
202 CHESAPEAKE DR G		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
202 CHESAPEAKE DR B		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1500 COLIN BRADLEY DR D		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
N MC LAREN ST/E CLARK		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
309 N MARKET ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
200 E PATRICK ST		No	No	1965	1965	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
501 N MARKET ST 2		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
200 N MARKET ST		No	Yes	2023	1935	Maintenance Records	Copper	C	P	NL	N	11/7/2023	Yes	11/8/2023	C	No	
2000 N STATE ST		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1705 N STATE ST B		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
400 E REICHERT DR #A-B		No	No	2020	1999	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
300 W LONGSTREET RD		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
319 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
416 E REICHERT DR		No	No	1990	1990	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
100 LONGSTREET RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
307 RED ROW RD		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
321 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
201 W LONGSTREET RD		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
215 RED ROW RD E		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1508 N GARFIELD ST #1-4		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1807 BRIDGE ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
500 VILLA DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
206 CHESAPEAKE DR D		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
204 E DEYOUNG ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1502 CORNERSTONE CT A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
206 CHESAPEAKE DR #G		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
206 CHESAPEAKE DR H		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1502 CORNERSTONE CT B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
206 CHESAPEAKE DR E		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
202 WILD ROSE LN C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
202 WILD ROSE LN B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
203 WILD ROSE LN B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
202 WILD ROSE LN D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
303 GATEWAY RD		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1809 BRIDGE ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1812 N STATE ST A		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1812 N STATE ST C		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1810 N STATE ST C		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1812 N STATE ST B		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
206 CHESAPEAKE DR C		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
206 CHESAPEAKE DR A		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
206 CHESAPEAKE DR F		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
204 CHESAPEAKE DR G		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
206 CHESAPEAKE DR B		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
202 CHESAPEAKE DR A		No	No	1995	1995	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
204 CHESAPEAKE DR F		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1500 COLIN BRADLEY DR C		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
204 CHESAPEAKE DR A		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
204 CHESAPEAKE DR E		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
204 CHESAPEAKE DR B		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
202 CHESAPEAKE DR H		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
204 CHESAPEAKE DR C		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
202 WILD ROSE LN A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
203 WILD ROSE LN A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
311 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No	No	
502 VILLA DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
204 CHESAPEAKE DR H		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1711 N STATE ST A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
316 RED ROW RD		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
312 RED ROW RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1810 N STATE ST D		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
308 RED ROW RD		No	No	1963	1963	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
314 RED ROW RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
306 RED ROW RD		No	No	1961	1961	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
319 RED ROW RD		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1812 N STATE ST D		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1506 CORNERSTONE CT B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1504 CORNERSTONE CT B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1500 CORNERSTONE CT A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
202 CHESAPEAKE DR C		No	No	1995	1995	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1504 CORNERSTONE CT A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1506 CORNERSTONE CT A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1500 CORNERSTONE CT B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1711 N STATE ST B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
202 CHESAPEAKE DR F		No	No	1995	1995	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
204 CHESAPEAKE DR D		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
317 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
315 WHITNEY LN		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
1504 N LOGAN ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
1207 N GLENDALE ST		No	No	1942	1942	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No	No	
902 N LOGAN ST #2		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
902 N LOGAN ST #1		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
902 N LOGAN ST #3		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
211 E CHARLES ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
902 N LOGAN ST #4		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
1514 N STATE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
1515 N STATE ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
1510 N STATE ST		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
201 W STOCKTON ST #C		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
108 E STOCKTON ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
201 W STOCKTON ST #B		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
904 N HIGHLAND ST #A-C		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
312 W BOULEVARD ST		No	No	1936	1936	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
904 SCORCHEE RD		No	No	1982	1982	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
311 W BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
707 W BOULEVARD ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
705 N VAN BUREN ST		No	No	1955	1955	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
606 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
909 N COURT ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1015 N COURT ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1008 N JOHNSON ST #B		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
801 W WHITE ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1011 N COURT ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
905 N COURT ST		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
907 N COURT ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
910 N BENTLEY ST C		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1104 N COURT ST		No	No	1900	1900	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1110 N COURT ST		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1001 N COURT ST		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1009 N COURT ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1009 N RAILROAD ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
703 W BELCHER ST		No	No	1965	1965	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1008 N JOHNSON ST #A		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1108 N COURT ST		No	No	1906	1906	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1020 N COURT ST		No	No	1925	1925	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
701 W BELCHER ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1105 W DEYOUNG ST		No	No	1953	1953	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
923 N BENTLEY ST #REAR		No	No	1976	1976	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
911 N COURT ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
708 N VAN BUREN ST		No	No	1968	1968	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
907 N VICKSBURG ST		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1000 N COURT ST		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
804 N COURT ST		No	No	2013	2013	Construction Records	Copper	C	P	NL	N	N/R	No		No		
700 N COURT ST #SPRINK		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1100 N COURT ST		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
601 W BELCHER ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
109 W WHITE ST		No	No	1900	1900	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
902 W BOULEVARD ST		No	No	1920	1920	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
1005 N VICKSBURG ST		No	No	1961	1961	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
903 N COURT ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
206 W GOODALL ST C		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
801 W BOULEVARD ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
807 N COURT ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L)							
1113 N COURT ST		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
708 N GRANITE ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
400 W GOODALL ST A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
709 N GRANITE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
400 W GOODALL ST B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
209 W WHITE ST		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
908 N BENTLEY ST I		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1001 W DEYOUNG ST #POLICE		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
908 N BENTLEY ST G		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
910 N BENTLEY ST G		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
914 N BENTLEY ST D		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST C		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST #E		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST #F		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST N		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST I		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
918 N BENTLEY ST REAR		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST J		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST H		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST G		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
914 N BENTLEY ST M		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
910 N BENTLEY ST E		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
900 W STOCKTON ST		No	No	1958	1958	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
910 N BENTLEY ST B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
914 N BENTLEY ST K		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
910 N BENTLEY ST D		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
914 N BENTLEY ST L		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
910 N BENTLEY ST A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
802 N COURT ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
910 N BENTLEY ST F		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1105 W STOCKTON ST		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
205 W BOULEVARD ST		No	No	1930	1930	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
1200 W STOCKTON ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
203 W BOULEVARD ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
910 N BENTLEY ST H		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
300 W GOODALL ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1008 N HIGHLAND ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
208 W BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1110 N JOHNSON ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
902 SCORCHEE RD		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
801 N COURT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
603 N COURT ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1100 W STOCKTON ST		No	No	1955	1955	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1010 N VICKSBURG ST		No	No	2019	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1003 N VICKSBURG ST		No	No	2019	1980	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1002 W STOCKTON ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
906 N VICKSBURG ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1101 W DEYOUNG ST #A		No	No	2019	1980	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
910 N COURT ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1109 N RAILROAD ST		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
810 N COURT ST		No	No	1954	1954	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
915 N BENTLEY ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 N BENTLEY ST C		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
908 N BENTLEY ST N		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
917 N BENTLEY ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 N BENTLEY ST E		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
908 N BENTLEY ST L		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
907 N BENTLEY ST		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
908 N BENTLEY ST M		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
908 N BENTLEY ST K		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
908 N BENTLEY ST J		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1107 W DEYOUNG ST 10-80		Yes	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
918 N BENTLEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
923 N BENTLEY ST		No	No	1976	1976	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
920 N BENTLEY ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1007 N HIGHLAND ST		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
900 W STOCKTON ST #REAR		No	No	1958	1958	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1009 N HIGHLAND ST		No	No	1980	1980	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
1010 N HIGHLAND ST		No	No	1960	1960	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
902 N VICKSBURG ST		No	No	1982	1982	Visual Inspection	Unknown	G	CLS	NL	N	N/R	No		No		
1011 N HIGHLAND ST		No	No	2021	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
901 N BENTLEY ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1202 W STOCKTON ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1107 W STOCKTON ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
908 N BENTLEY ST D		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
908 N BENTLEY ST A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
903 N BENTLEY ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
912 N BENTLEY ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
908 N BENTLEY ST B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
916 N BENTLEY ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 N BENTLEY ST F		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
908 N BENTLEY ST H		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1101 N COURT ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
706 N GRANITE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
307 W GOODALL ST		No	No	2024	1943	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
707 N GRANITE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
802 W BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
309 W GOODALL ST		No	No	2024	1924	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
801 N GRANITE ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
602 N COURT ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1100 N JOHNSON ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1000 W UNION ST #C		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
204 N COURT ST #REAR		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1001 ELM ST C		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1001 ELM ST D		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1001 ELM ST A		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
103 N BENTLEY ST #A		No	No	2024	2003	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1000 W UNION ST #B		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
300 N BENTLEY ST		No	No	2024	1920	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1206 W LEE AVE		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
301 N VAN BUREN ST		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
301 N HAMLET ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1000 W UNION ST #D		No	No	2018	2018	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1004 W MAIN ST 1-6		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1000 W UNION ST #A		No	No	2018	2018	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1102 W MAIN ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
207 N BENTLEY ST A-E		No	No	2024	1985	Maintenance Records	Plastic	C	P	NL	N	N/R	No		No		
206 N LEAR ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
304 N VICKSBURG ST #B		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
304 N VICKSBURG ST #A		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
304 N VICKSBURG ST #C		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1007 W UNION ST #B		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
600 W JACKSON ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
410 N COURT ST		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1007 W UNION ST #A		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
304 N HOLLAND ST		No	No	1915	1915	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
504 W JACKSON ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
411 1/2 N COURT ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 ELM ST B		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
923 W UNION ST		No	No	2005	2005	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
208 W UNION ST #5		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
504 TOWER SQUARE PLAZA		No	Yes	2023	1913	Maintenance Records	Copper	C	CLS	NL	N	10/30/2023	Yes	10/30/2023	C	No	
208 W UNION ST #2		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
200 W JEFFERSON ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
401 W UNION ST #FRONT		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
401 W UNION ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
407 N MONROE ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
404 N VAN BUREN ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
105 N LEAR ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
100 N COURT ST		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
350 TOWER SQUARE PLAZA	LP1C001	No	Yes	2023	2023	Maintenance Records	Copper	C	C	NL	N	11/2/2023	Yes	11/2/2023	C	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
303 N HOLLAND ST		No	No	1915	1915	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1505 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1505 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1505 W CENTRAL ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1505 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1502 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1711 W FAUST ST		No	No	1967	1967	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
712 N CARBON ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
103 N CARBON ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1506 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1506 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1500 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1503 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1503 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1503 W CENTRAL ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1503 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1502 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1501 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1501 W CENTRAL ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1706 W DEWEY ST		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1103 W GOODALL ST		No	No	1974	1974	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1105 W GOODALL ST		No	No	1960	1960	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1502 W CENTRAL ST #B		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1502 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1502 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1504 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1411 W MAIN ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1504 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1506 W CENTRAL ST #F		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1500 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1504 W CENTRAL ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1504 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1506 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1506 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1506 W CENTRAL ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1507 W CENTRAL ST #E		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1504 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1507 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1507 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1507 W CENTRAL ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1505 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1507 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1500 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1500 W CENTRAL ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2315 W MAIN ST		No	No	2016	2016	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2100 W ORCHARD ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1609 W FAUST ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2100 W BRADY AVE		No	No	1965	1965	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
306 N 4TH ST		No	No	1961	1961	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1615 W FAUST ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1611 W FAUST ST		No	No	2016	2016	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1614 W FAUST ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
211 N PINE ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1701 W FAUST ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1706 W FAUST ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1705 W FAUST ST		No	No	1930	1930	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
1703 W FAUST ST		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1618 W FAUST ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1500 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1503 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1501 W CENTRAL ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1501 W CENTRAL ST #A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1501 W CENTRAL ST #D		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1000 N CARBON ST M		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
107 N RUSSELL ST #1-4		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
110 N FIFTH ST #C		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
108 N FIFTH ST C		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
303 N FIFTH ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1720 W DEWEY ST		No	No	1970	1970	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
1108 N CARBON ST C		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1203 ENTERPRISE WAY #100		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1115-1 N CARBON ST		No	No	1923	1923	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1507 RENDLEMAN ST #MGH		No	No	2023	2023	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1700 W MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2210 JENNIFER LN		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
900 W WHITE ST		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
808 W WHITE ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1800 W MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1604 MARCELLA DR		No	No	1976	1976	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1700 MARCELLA DR		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
2216 JENNIFER LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1120 N CARBON ST #1		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1120 N CARBON ST 6		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1203 W WHITE ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
600 N RUSSELL ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1131 N CARBON ST #A-C		No	No	2017	2017	Construction Records	Copper	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
602 N STEWART DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1601 W DEWEY ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
604 N STEWART DR		No	No	2024	1972	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
2210 DARREN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1207 N RUSSELL ST		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1412 W BOULEVARD ST #1		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1135 N CARBON ST		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2000 RENDLEMAN ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1119 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1106 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1600 W DEWEY ST		No	No	1953	1953	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1010 W CENTRAL ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1701 MARCELLA DR		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1603 MARCELLA DR		No	No	1969	1969	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2108 MELANIE LN #3		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
108 S EWAN ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
110 S EWAN ST #B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
110 S EWAN ST #C		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1123 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
110 S EWAN ST #A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2219 JENNIFER LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2218 JENNIFER LN		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
2215 JENNIFER LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2201 DARREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2202 DARREN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2200 DARREN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2203 DARREN DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
205 N FIFTH ST #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2208 DARREN DR		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2204 DARREN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
716 N CARBON ST		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1709 W DEWEY ST		No	No	1890	1890	Visual Inspection	Unknown	P	G	NL	N	N/R	No			No	
1713 W DEWEY ST		No	No	1890	1890	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2205 DARREN DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1610 W DEWEY ST #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1706 W FAUST ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1121 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
2206 DARREN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
205 N FIFTH ST #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2207 DARREN DR		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2209 DARREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1113 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1307 W CENTRAL ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2217 JENNIFER LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2213 JENNIFER LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2212 JENNIFER LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1114 N CARBON ST #A "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1137 N CARBON ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
109 N SEVENTH ST		No	No	1952	1952	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
601 N STEWART DR		No	No	1973	1973	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2201 MELANIE LN B		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2201 MELANIE LN A		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2208 JENNIFER LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
205 N FOZZARD ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1502 MARCELLA DR		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1601 MARCELLA DR		No	No	1968	1968	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1600 MARCELLA DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
603 N STEWART DR		No	No	1973	1973	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
301 N 4TH ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
2108 MELANIE LN #2		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
600 N CARBON ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
801 N CARBON ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
801 N CARBON ST #SPRINK		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
2215 MELANIE LN		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2205 MICHELLE DR		No	No	1967	1967	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
601 STEVEN DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
604 STEVEN DR		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1708 MARCELLA DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1703 MARCELLA DR		No	No	1972	1972	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
602 STEVEN DR		No	No	1976	1976	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
603 STEVEN DR		No	No	1971	1971	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 MARCELLA DR		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
606 STEVEN DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1704 MARCELLA DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1905 W RENDLEMAN ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
404 N WALKER ST		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1911 RENDLEMAN ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
206 N WALKER ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2204 MICHELLE DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2205 MELANIE LN		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2202 MELANIE LN		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2206 MICHELLE DR		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2202 MICHELLE DR		No	No	1971	1971	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2206 MELANIE LN		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2203 MELANIE LN		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2208 MELANIE LN		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2203 MICHELLE DR		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2210 MICHELLE DR		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2201 MICHELLE DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2208 MICHELLE DR		No	No	1969	1969	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2207 MICHELLE DR		No	No	1967	1967	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
407 N WALKER ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1000 N CARBON ST T		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1111 ANKER ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
405 N WALKER ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
129 N SEVENTH ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2207 MELANIE LN		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2204 MELANIE LN		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1112 N CARBON ST #A		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
603 N CARBON ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
806 N TREAS ST		No	No	1984	1984	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1602 KIMMELL ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1600 KIMMELL ST		No	No	1976	1976	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1203 ENTERPRISE WAY		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
119 N SEVENTH ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1106 N CARBON ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
204 N CARBON ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 W MAIN ST #GARV		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1501 W FAUST ST #C		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1412 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
2200 W MAIN ST		No	No	1965	1965	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
2203 NICHOLE LN #A-F		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2205 NICHOLE LN #G-L		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2201 NICHOLE LN #A-D		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2216 MICHELLE DR		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2217 MELANIE LN B		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 W BOULEVARD ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1408 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1410 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1409 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1901 W DEYOUNG ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1126 N CARBON ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
1407 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1118 N CARBON ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1128 N CARBON ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
2200 JENNIFER LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2217 NICHOLE LN #A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2214 NICHOLE LN #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2216 NICHOLE LN #A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
112 N FIFTH ST #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
114 N FIFTH ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
112 N FIFTH ST #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
209 N FIFTH ST #A		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2218 MELANIE LN		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2100 W ORCHARD ST #C		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
307 N 4TH ST		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1108 N CARBON ST E		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1108 N CARBON ST F		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1108 N CARBON ST H		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
209 N FIFTH ST #C		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
209 N FIFTH ST #B		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1602 MARCELLA DR		No	No	1982	1982	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1105 W WHITE ST		No	No	1935	1935	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
403 N WALKER ST		No	No	1982	1982	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
209 N PINE ST #A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
209 N PINE ST #C		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
209 N PINE ST #D		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2206 JENNIFER LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2211 JENNIFER LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2214 JENNIFER LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2209 JENNIFER LN		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1512 W DEWEY ST		No	No	1964	1964	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1110 N CARBON ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
209 N PINE ST #B		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2201 JENNIFER LN		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2202 JENNIFER LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
110 N FIFTH ST #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1105 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1419 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
1906 W COOLIDGE AVE		No	No	1977	1977	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No		
1306 W BOULEVARD ST #2		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1417 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
1425 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
1415 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
1421 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
1423 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
302 N RUSSELL ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
1909 W COOLIDGE AVE		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1302 W BOULEVARD ST #2		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
2110 MELANIE LN 2		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1306 W BOULEVARD ST #1		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1300 W BOULEVARD ST #1		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1303 ENTERPRISE WAY #F		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1412 W BOULEVARD ST #2		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1408 W BOULEVARD ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1404 W BOULEVARD ST 2		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
204 N WALKER ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No		
2214 NICHOLE LN #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2215 NICHOLE LN #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2215 NICHOLE LN #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
918 W UNION ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2001 INDUSTRIAL PARK RD #D		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2003 INDUSTRIAL PARK RD		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1301 ENTERPRISE WAY ##80		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1427 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
2204 JENNIFER LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1203 ENTERPRISE WAY A		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2203 JENNIFER LN		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1302 W BOULEVARD ST #1		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1304 W BOULEVARD ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1101 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1414 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1413 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1405 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1009 N CARBON ST		No	No	1973	1973	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1601 W WHITE ST		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1303 ENTERPRISE WAY		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1300 W BOULEVARD ST #2		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1133 N CARBON ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2215 MICHELLE DR		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1608 W DEWEY ST #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2213 MICHELLE DR		No	No	1977	1977	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)					Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)		
2211 MICHELLE DR		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2112 MELANIE LN C		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2214 MICHELLE DR		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2112 MELANIE LN A		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2212 MICHELLE DR		No	No	1973	1973	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
2209 MICHELLE DR		No	No	1972	1972	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2212 MELANIE LN A		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2211 MELANIE LN		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2213 MELANIE LN		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2108 MELANIE LN A		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2108 MELANIE LN B		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1714 W DEWEY ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	G	NL	N	N/R	No		No		
205 N PINE ST #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2110 MELANIE LN E		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2212 MELANIE LN B		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2214 MELANIE LN		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
700 N RUSSELL ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1608 W DEWEY ST #C		No	No	1990	1990	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1608 W DEWEY ST #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2112 MELANIE LN B		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2216 MELANIE LN		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2108 MELANIE LN F		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2210 MELANIE LN		No	No	1968	1968	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Galvanized Requiring Replacement (GRR) Unknown (U) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
302 N 4TH ST #B		No	No	1928	1928	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
2110 MELANIE LN C		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
304 N 4TH ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
2110 MELANIE LN D		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
302 N 4TH ST #A		No	No	1928	1928	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
2108 MELANIE LN D		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2108 MELANIE LN C		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2200 MICHELLE DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
2112 MELANIE LN D		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
2108 MELANIE LN E		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1301 ENTERPRISE WAY #20		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1702 W DEWEY ST		No	No	1935	1935	Survey Response	Unknown	C	P	NL	N	N/R	No			No		
1129 N CARBON ST #C		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
1610 W DEWEY ST #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
1703 W DEWEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
127 N SEVENTH ST		No	No	1955	1955	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
125 N SEVENTH ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
2110 MELANIE LN B		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2110 MELANIE LN F		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2110 MELANIE LN A		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
603 JOHN ALLEN CT		No	No	1974	1974	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
604 JOHN ALLEN CT		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
601 JOHN ALLEN CT		No	No	1974	1974	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
602 JOHN ALLEN CT		No	No	1974	1974	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
201 N 4TH ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2219 MICHELLE DR		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1509 KIMMELL ST		No	No	1984	1984	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1103 N CARBON ST A		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1701 W DEWEY ST		No	No	1926	1926	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1603 KIMMELL ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
804 N RUSSELL ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1301 ENTERPRISE WAY #80 sprink		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
505 N FIFTH ST #A-N		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2200 NICHOLE LN #A-F		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2202 NICHOLE LN #G-L		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2207 NICHOLE LN #A-F		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2206 NICHOLE LN #G-L		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2204 NICHOLE LN #A-F		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1120 N CARBON ST 3		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1120 N CARBON ST 2		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1120 N CARBON ST 4		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1708 W FAUST ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
1709 W FAUST ST		No	No	1966	1966	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2200 MELANIE LN		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
107 N CARBON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1129 N CARBON ST #A		No	No	1978	1978	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
205 N PINE ST #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1603 W DEWEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1607 W DEWEY ST		No	No	1926	1926	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1610 W DEWEY ST #D		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1610 W DEWEY ST #C		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2207 JENNIFER LN		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2205 JENNIFER LN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1605 W FAUST ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1608 W FAUST ST		No	No	1955	1955	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
206 N FOZZARD ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
203 N FOZZARD ST		No	No	1968	1968	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1606 W FAUST ST		No	No	1972	1972	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1207 ENTERPRISE WAY		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1501 MARCELLA DR		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2218 MICHELLE DR		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 ENTERPRISE WAY #10		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
704 N RUSSELL ST		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
708 N RUSSELL ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2217 MELANIE LN A		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2217 MICHELLE DR		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1700 W DEWEY ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1103 N CARBON ST B		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1131 N CARBON ST D		No	No	1978	1978	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1800 W BOULEVARD ST A		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1800 W BOULEVARD ST B		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
901 N CARBON ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1406 W BOULEVARD ST #1		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1410 W BOULEVARD ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1411 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1406 W BOULEVARD ST 2		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1402 W BOULEVARD ST 1		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
507 N FIFTH ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1416 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1418 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1420 SHAWNEE DR		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1501 W DEYOUNG ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1301 ENTERPRISE WAY		No	No	1966	1966	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
709 N CARBON ST		No	No	1977	1977	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1400 W BOULEVARD ST #2		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
605 N CARBON ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1308 W BOULEVARD ST #1		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2218 DARREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2215 DARREN DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2216 DARREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1913 RENDLEMAN ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
1810 INDUSTRIAL PARK RD		No	No	1966	1966	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1803 INDUSTRIAL PARK RD		No	No	1974	1974	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
800 N CARBON ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
2216 NICHOLE LN #B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2211 DARREN DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2212 DARREN DR		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2217 DARREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2218 NICHOLE LN #A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2217 NICHOLE LN #B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2213 DARREN DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2219 DARREN DR		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2214 DARREN DR		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2218 NICHOLE LN #B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2219 NICHOLE LN #A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2219 NICHOLE LN #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
2100 W ORCHARD ST #B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1604 W DEWEY ST		No	No	1905	1905	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
105 N FOZZARD ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1503 W DEWEY ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1501 W FAUST ST #A		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1606 W DEWEY ST		No	No	1905	1905	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1501 W FAUST ST #B		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1501 W FAUST ST #D		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1505 W FAUST ST #B		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1505 W FAUST ST #A		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
110 N FIFTH ST #D		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
112 N FIFTH ST #D		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
108 N FIFTH ST A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
112 N FIFTH ST #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
110 N FIFTH ST #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
108 N FIFTH ST B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
705 N CARBON ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1402 W BOULEVARD ST 2		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1308 W BOULEVARD ST #2		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1400 W BOULEVARD ST #1		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1404 W BOULEVARD ST 1		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
802 N RUSSELL ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
201 N WALKER ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
102 S EWAN ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1000 N CARBON ST W		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1910 RENDLEMAN ST #A		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2305 W MAIN ST		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1909 RENDLEMAN ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
104 S EWAN ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
2209 MELANIE LN		No	No	1977	1977	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified?	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1104 W GOODALL ST		No	No	1980	1980	Survey Response	Unknown	C	G	NL	N	N/R	No		No		
1301 W CENTRAL ST		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
9526 ROUTE 148		No	No	1918	1918	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
9472 ROUTE 148		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
507 S MADISON ST		No	No	2020	1930	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
505 S MADISON ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1406 N LOGAN ST	LP1C008	No	No	Unknown	Unknown	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
1404 N LOGAN ST		No	No	2020	1910	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1405 N LOGAN ST		No	No	2020	1925	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1402 N LOGAN ST		No	No	2020	1940	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1403 N LOGAN ST		No	No	1924	1924	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
310 E ILLINOIS ST		No	No	2020	1940	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1306 N LOGAN ST		No	No	2020	1910	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1305 N LOGAN ST		No	No	2020	1939	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1300 N LOGAN ST		No	No	2020	1910	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1209 N LOGAN ST		No	No	2020	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1207 N LOGAN ST		No	No	2020	1920	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
1210 N LOGAN ST		No	No	2020	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1204 N LOGAN ST		No	No	2020	1900	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1303 N LOGAN ST		No	No	2020	1920	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1409 N LOGAN ST		No	No	2020	1920	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
105 S MARKET ST		No	Yes	2023	1964	Maintenance Records	Plastic	P	CLS	NL	N	11/5/2023	Yes	11/6/2023	P	No	
503 S MARKET ST		No	No	2017	1880	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1200 S BUCHANAN ST	LP1C019	No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
1007 S MADISON ST		No	No	1974	1974	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1008 S MADISON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1006 S MADISON ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
502 S MECHANIC ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
504 S MECHANIC ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
506 S MECHANIC ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
508 S MECHANIC ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
701 S BUCHANAN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
513 S MADISON ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
703 S MADISON ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
607 S MECHANIC ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
200 ALLEN AVE		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
201 ALLEN AVE		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
203 ALLEN AVE		No	No	1915	1915	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
301 ALLEN AVE		No	No	1890	1890	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
410 ALLEN AVE		No	No	1921	1921	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1301 S BUCHANAN ST	LP1C020	No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
1300 S BUCHANAN ST		No	No	2020	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1015 S BUCHANAN ST		No	No	1947	1947	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
514 S MADISON ST		No	No	2020	1950	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
509 S MADISON ST	LP1C017	No	No	Unknown	Unknown	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
101 E WARDER ST		No	No	2022	1930	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
510 S MADISON ST #1		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
510 S MADISON ST #3		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
510 S MADISON ST #4		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
510 S MADISON ST #5		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
510 S MADISON ST #8		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
510 S MADISON ST #2		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
510 S MADISON ST #7		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1408 S MECHANIC ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
510 S MADISON ST #6		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
907 S VIRGINIA AVE		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
519 PARISH AVE		No	No	Unknown	Unknown	Maintenance Records	Unknown	C	CLS	NL	N	N/R	No		No		
512 PARISH AVE		No	No	1942	1942	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
415 E MARION ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
303 S VIRGINIA AVE		No	No	1930	1930	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
805 S VIRGINIA AVE		No	No	2021	1936	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
304 S VIRGINIA AVE		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
416 E THORN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
500 E THORN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
504 PARISH AVE		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
400 S VIRGINIA AVE		No	No	1880	1880	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
402 S VIRGINIA AVE		No	No	1960	1960	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
502 PARISH AVE		No	No	1905	1905	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
404 S VIRGINIA AVE		No	No	1910	1910	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
809 S VIRGINIA AVE		No	No	1890	1890	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
400 E WARDER ST		No	No	2019	1924	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
405 E WARDER ST		No	No	1890	1890	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
501 S BUCHANAN ST		No	No	2019	1899	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
307 E WARDER ST		No	No	2019	1900	Maintenance Records	Copper	C	CLS	NL	N	N/R	No		No		
408 S BUCHANAN ST		No	No	2019	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
801 S VIRGINIA AVE		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
508 S BUCHANAN ST		No	No	1940	1940	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
507 S BUCHANAN ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
509 S BUCHANAN ST		No	No	1890	1890	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
512 S VIRGINIA AVE		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
700 S VIRGINIA AVE		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
711 S VIRGINIA AVE		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
604 VIRGINIA AVE		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
202 E THORN ST #A		No	No	1920	1920	Maintenance Records	Unknown	G	G	NL	N	N/R	No		No		
200 E THORN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
406 E THORN ST #A-B		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
701 S HADFIELD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
702 S HADFIELD ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No		
608 S HADFIELD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
501 S CALUMET ST		No	No	2021	2021	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
708 S CALUMET ST		No	No	2020	1935	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
502 S CALUMET ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
411 S CALUMET ST		No	No	2021	1943	Maintenance Records	Plastic	P	G	NL	N	N/R	No			No		
531 E EVERETT ST		No	No	2021	1943	Maintenance Records	Copper	C	P	NL	N	N/R	No			No		
609 S VIRGINIA AVE		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
604 Pleasant Ct		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
511 S CALUMET ST		No	No	1943	1943	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
527 E EVERETT ST		No	No	2021	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No			No		
502 E EVERETT ST		No	No	1920	1920	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
705 CIRCLE DR		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
710 CIRCLE DR		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No		
707 CIRCLE DR		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
406 E WARDER ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
409 E EVERETT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
601 S CALUMET ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
507 S CALUMET ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1111 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
1104 E MAIN ST		Yes	No	1983	1983	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1105 E MAIN ST		No	No	1920	1920	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
1100 E MAIN ST		No	No	1890	1890	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
104 N MCLAREN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	P	UNL	NL	N	N/R	No		No		
1006 E MAIN ST		No	No	1982	1982	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
1005 E MAIN ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
912 E MAIN ST		No	Yes	2024	2024	Maintenance Records	Plastic	P	P	NL	Y	9/4/2024	Yes	9/17/2024	P	No	
904 E MAIN ST		No	No	1906	1906	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
907 E. BEECH		No	No	1910	1910	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
902 E MAIN ST		No	No	1900	1900	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
816 E MAIN ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
817 E MAIN ST		No	No	1886	1886	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
809 E MAIN ST		No	No	1925	1925	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
812 E MAIN ST		No	No	1900	1900	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
806 E MAIN ST		No	No	1920	1920	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
807 E MAIN ST		No	No	2021	1983	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
804 E MAIN ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
202 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
206 S FUTURE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
717 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
716 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
715 E MAIN ST #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
715 E MAIN ST #B		No	No	1990	1990	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
715 E MAIN ST #C		No	No	1990	1990	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
715 E MAIN ST #D		No	No	1990	1990	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
621 E MAIN ST		No	No	1986	1986	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
617 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
613 E MAIN ST		No	No	1982	1982	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
511 E MAIN ST		No	No	1985	1985	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
509 E MAIN ST #A-D		No	No	1915	1915	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
420 E MAIN ST		Yes	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
505 E MAIN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	P	UNL	NL	N	N/R	No		No		
501 E MAIN ST		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
105 S VIRGINIA AVE		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
417 E Main St		No	No	1940	1940	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
407 E MAIN ST		No	No	1940	1940	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
403 E MAIN ST		No	No	1930	1930	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
201 E COLLEGE ST		No	No	1940	1940	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
105 S MECHANIC ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
309 E COLLEGE ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
404 E COLLEGE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
110 S VIRGINIA AVE		Yes	No	1993	1993	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
513 E COLLEGE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
507 E COLLEGE ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
511 E MARION ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
505 E MARION ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
506 E MARION ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
301 S VIRGINIA AVE		No	No	1925	1925	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
536 E THORN ST		No	No	1900	1900	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
611 E THORN ST		No	No	2020	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
605 E THORN ST		No	No	1910	1910	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
524 E THORN ST		No	No	1905	1905	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
601 E THORN ST		No	No	1907	1907	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
516 E THORN ST		No	No	1935	1935	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
512 E THORN ST		No	No	1935	1935	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
508 E THORN ST		No	No	1935	1935	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
504 E THORN ST		No	No	1935	1935	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
521 E COLLEGE ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
509 E THORN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1904 E PICKETT LN		No	No	1981	1981	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
206 S FAIR ST		No	No	1920	1920	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No		
1101 E COLLEGE ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1001 E COLLEGE ST		No	No	2021	1900	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
912 E COLLEGE ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
207 S BURR ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
203 S BURR ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
901 E COLLEGE ST "Empty Lot"		No	No	1900	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
206 S BURR ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
202 S BURR ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
901 E BEECH ST		No	No	1915	1915	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1117 E MAIN ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1119 E MAIN ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
106 S CHAMP ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1505 E MAIN ST		No	No	1946	1946	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
903 OLD CREAL SPRINGS RD #C		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
903 OLD CREAL SPRINGS RD #B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1501 E MAIN ST		No	No	1964	1964	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1209 ANDERSON DR		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
904 VINEWOOD LN #A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
904 VINEWOOD LN #B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
904 VINEWOOD LN #C		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
904 VINEWOOD LN #D		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
904 VINEWOOD LN #E		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1100 E BOYTON ST #D		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
800 E MARSHALL ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1006 HILLCREST DR		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
900 E BOYTON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
1705 OLD CREAL SPRINGS RD "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1802 COLONIAL DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1823 COLONIAL DR		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1503 CARDINAL DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1402 CARDINAL DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1806 MULLIGAN DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1802 MULLIGAN DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1400 CARDINAL DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1400 CARDINAL DR SPRINK		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1300 RIDGEVIEW DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1301 RIDGEVIEW DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
3201 S MARKET ST		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3003 S MARKET ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
2405 CARRIAGE LN		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1159 GOLF COURSE RD		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2803 E BRIDLE LN		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1501 E PARHAM ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
106 SYCAMORE LN		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2602 S MARKET ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
2002 E MAIN ST		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2800 S MARKET ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1606 E MAIN ST		No	No	2019	2006	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
108 N FAIR ST		No	No	1885	1885	Survey Response	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
302 N FAIR ST		No	No	1900	1900	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
310 N FAIR ST #A		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
310 N FAIR ST #B		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
310 N FAIR ST #C		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
310 N FAIR ST #D		No	No	2012	2012	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1003 E JACKSON ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
401 N MCLAREN ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
403 S MCLAREN ST		No	No	1940	1940	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
405 N MCLAREN ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
404 N MCLAREN ST		No	No	1985	1985	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
402 N MCLAREN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
400 N MCLAREN ST		No	No	1985	1985	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
1105 E UNION ST		No	No	2020	2020	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1103 E UNION ST		No	No	2020	2020	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
203 N MCLAREN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
301 N MCLAREN ST		No	No	1900	1900	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
303 N MCLAREN ST		No	No	1920	1920	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
307 N MCLAREN ST		No	Yes	2024	2024	Maintenance Records	Copper	C	P	NL	Y	9/4/2024	Yes	10/3/2024	C	No	
904 E JACKSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
903 E JACKSON ST		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
301 N OTIS ST		No	No	1957	1957	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
903 N OTIS ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified?	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	Examples: Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
305 N OTIS ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
309 N OTIS ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
312 N OTIS ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
804 E JACKSON ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
112 N OTIS ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
723 E UNION ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
720 E UNION ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
719 E UNION ST		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
718 E UNION ST		No	No	1964	1964	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
715 E UNION ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
716 E UNION ST		No	No	1916	1916	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
713 E UNION ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
712 E UNION ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
711 E UNION ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
615 E UNION ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
614 E UNION ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
706 E MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
400 N MADISON ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
612 E UNION ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
608 E UNION ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
309 N MADISON ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
205 E CALVERT ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
708 E MAIN ST		No	No	2012	2012	Construction Records	Copper	C	C	NL	N	N/R	No			No	
208 E JEFFERSON ST		No	No	1920	1920	Maintenance Records	Unknown	G	G	NL	N	N/R	No			No	
304 N MECHANIC ST		No	No	1900	1900	Maintenance Records	Unknown	G	P	NL	N	N/R	No			No	
210 E JEFFERSON ST		No	No	1940	1940	Maintenance Records	Unknown	G	P	NL	N	N/R	No			No	
712 E JEFFERSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
210 E UNION ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
301 E JEFFERSON ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
205 N GARFIELD ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
208 N GARFIELD ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
300 E UNION ST		No	No	1947	1947	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
704 E UNION ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
406 N BUCHANAN ST		No	No	1930	1930	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
407 N BUCHANAN ST		No	Yes	2024	2024	Maintenance Records	Plastic	P	P	NL	Y	9/4/2024	Yes	10/22/2024	P	No	
408 E JEFFERSON ST		No	No	1898	1898	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
405 N BUCHANAN ST		No	No	1926	1926	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
404 E JEFFERSON ST		No	No	1920	1920	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
401 N BUCHANAN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
406 E JACKSON ST #1-5		No	No	1929	1929	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
400 N BUCHANAN ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
405 E JACKSON ST		No	No	2024	1915	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
403 E JACKSON ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
307 N BUCHANAN ST		No	No	1880	1880	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
402 E JACKSON ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
304 N BUCHANAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	P	UNL	NL	N	N/R	No		No		
305 N BUCHANAN ST		No	No	1930	1930	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
309 N MCLAREN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
308 N MCLAREN ST A		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
400 N FAIR ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
307 N OTIS ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
304 N OTIS ST		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No		
302 N MCLAREN ST #A		No	No	2001	2001	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
302 N MCLAREN ST #B		No	No	2001	2001	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
301 N LOGAN ST		No	No	2023	1964	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
416 E JEFFERSON ST		No	No	2021	2021	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
412 E Jefferson St		No	No	2022	2022	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
204 N GARFIELD ST #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
106 N FAIR ST		No	No	1885	1885	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1302 E MAIN ST		No	No	2010	2010	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1400 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
404 N FAIR ST		No	No	1973	1973	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
206 E JACKSON ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
608 N MADISON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	C	UNL	NL	N	N/R	No		No		
619 N MADISON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	P	UNL	NL	N	N/R	No		No		
108 E GOODALL ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
202 E BOULEVARD ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
305 E BOULEVARD ST		No	No	1918	1918	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
721 N HARPER ST		No	No	1930	1930	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
710 N HARPER ST		No	No	1910	1910	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
708 N Harper		No	No	1910	1910	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
704 N HARPER ST		No	No	2022	1910	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
702 N LOGAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
707 N LOGAN ST		No	No	1920	1920	Survey Response	Unknown	C	G	NL	N	N/R	No		No		
801 N LOGAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
412 E BOULEVARD ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
701 E MCKINLEY ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
403 N OTIS ST #B "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
708 N OTIS ST		No	No	2022	1925	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
802 N OTIS ST		No	No	2022	1960	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
106 E BOULEVARD ST		No	No	1915	1915	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
903 N MARKET ST		No	No	1953	1953	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
200 E BOULEVARD ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
109 E BOULEVARD ST		No	No	2019	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
201 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
203 E BOULEVARD ST "Empty Lot"		No	No	2019	Unknown	Maintenance Records	Copper	C	UNL	NL	N	N/R	No		No		
206 E BOULEVARD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
208 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
212 E BOULEVARD ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
214 E BOULEVARD ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
211 E BOULEVARD ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
222 E BOULEVARD ST		No	No	1930	1930	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
900 N STATE ST		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
905 N STATE ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
302 E BOULEVARD ST #A		No	No	1986	1986	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
302 E BOULEVARD ST #B		No	No	1986	1986	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
308 E BOULEVARD ST		No	No	1983	1983	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
404 E BOULEVARD ST #A		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
408 E BOULEVARD ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
901 N GARFIELD ST A		No	No	1997	1997	Visual Inspection	Lead	C	C	NL	N	N/R	No		No		
508 E BOULEVARD ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
510 E BOULEVARD ST		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
600 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
606 E BOULEVARD ST		No	No	1928	1928	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
701 E BOULEVARD ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
615 E BOULEVARD ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
611 E BOULEVARD ST	LP1C004	No	No	1930	1930	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
607 E BOULEVARD ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
809 N GARFIELD ST #A		No	No	1982	1982	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
809 N GARFIELD ST #D		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
509 E BOULEVARD ST #A		No	No	1940	1940	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
509 E BOULEVARD ST #B		No	No	1940	1940	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
507 E BOULEVARD ST		No	No	1982	1982	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
505 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
503 E BOULEVARD ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
409 E BOULEVARD ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
303 E BOULEVARD ST		No	No	1910	1910	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
301 E BOULEVARD ST		No	No	1920	1920	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
403 N OTIS ST A		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
405 N WASHINGTON ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
401 N WASHINGTON ST		No	No	1945	1945	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
801 E JACKSON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
803 E JACKSON ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
404 N OTIS ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
406 N OTIS ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
405 N OTIS ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
505 N OTIS ST		No	No	1986	1986	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
712 N MADISON ST		No	No	1930	1930	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
807 E MCKINLEY ST		No	No	2021	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
805 E MCKINLEY ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
508 N WASHINGTON ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
600 N WASHINGTON ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
802 E MCKINLEY ST		No	No	1970	1970	Survey Response	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
623 N MADISON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	P	UNL	NL	N	N/R	No			No		
806 E MCKINLEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
620 N MADISON ST		No	No	1984	1984	Visual Inspection	Lead	P	CLS	NL	N	N/R	No			No		
702 E MCKINLEY ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
618 N MADISON ST		No	No	1930	1930	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		
602 N OTIS ST		No	No	2022	1975	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
612 N MADISON ST		No	No	1950	1950	Visual Inspection	Lead	P	CLS	NL	N	N/R	No			No		
617 N MADISON ST		No	No	1947	1947	Visual Inspection	Lead	P	CLS	NL	N	N/R	No			No		
603 N OTIS ST #A		No	No	2022	1980	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
608 N OTIS ST		No	No	2022	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
610 N OTIS ST		No	No	2022	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
903 E BROWNING ST		No	No	2022	1980	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No		
700 N OTIS ST		No	No	2022	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
403 E WHITE ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
401 E WHITE ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
709 N OTIS ST		No	No	2022	1980	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
700 N HARPER ST		No	No	2021	1910	Maintenance Records	Plastic	P	G	NL	N	N/R	No			No		
703 E PARHAM ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
807 N OTIS ST		No	No	2022	1960	Visual Inspection	Plastic	P	CLS	NL	N	N/R	No			No		
703 N HARPER ST		No	No	1945	1945	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No		
702 E PARHAM ST		No	No	2022	1960	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No		
706 N HARPER ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
707 E BOULEVARD ST		No	No	2022	1982	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
810 N WASHINGTON ST		No	No	1900	1900	Visual Inspection	Unknown	G	P	NL	N	N/R	No		No		
707 N HARPER ST		No	No	1920	1920	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
807 N WASHINGTON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
712 N HARPER ST		No	No	1920	1920	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
805 N WASHINGTON ST A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
714 N HARPER ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
715 N HARPER ST		No	No	1930	1930	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
707 N WASHINGTON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
719 N HARPER ST		No	No	1930	1930	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
705 N WASHINGTON ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
723 N HARPER ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
705 N WASHINGTON		No	No	1942	1942	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
613 E BROWNING ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
614 E BROWNING ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
607 N WASHINGTON ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
700 E MCKINLEY ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
808 N LOGAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
600 N GARFIELD ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
603 N GARFIELD ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
607 N GARFIELD ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
609 N GARFIELD ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
711 N LOGAN ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
710 N LOGAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
708 N LOGAN ST		No	No	2019	2019	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
706 N LOGAN ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
605 N LOGAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
603 N LOGAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
606 N GARFIELD ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
601 N LOGAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
602 N LOGAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
700 N GARFIELD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
701 N GARFIELD ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
705 N GARFIELD ST		No	No	1936	1936	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
709 N GARFIELD ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
708 N GARFIELD ST		No	No	1920	1920	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
507 E MCKINLEY ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
508 E PARHAM ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
806 N GARFIELD ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
808 N GARFIELD ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
801 N GARFIELD ST #A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
801 N GARFIELD ST #B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
801 N GARFIELD ST #C		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
810 N GARFIELD ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
505 N MADISON ST		No	No	1990	1990	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
701 N MADISON ST		No	No	1992	1992	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
407 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		
709 N MADISON ST		No	No	1930	1930	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
803 E MCKINLEY ST		No	No	1910	1910	Survey Response	Unknown	C	P	NL	N	N/R	No			No		
604 N OTIS ST		No	No	2022	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
405 E WHITE ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
800 N OTIS ST		No	No	2022	1960	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No		
705 N HARPER ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
608 E PARHAM ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No		
718 N HARPER ST		No	No	1910	1910	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		
727 N HARPER ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No		
728 N HARPER ST		No	No	1910	1910	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No		
703 N LOGAN ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
503 E MCKINLEY ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
603 E PARHAM ST #A		No	No	1980	1980	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No		
605 E PARHAM ST		No	No	2021	1900	Maintenance Records	Copper	C	P	NL	N	N/R	No			No		
708 N MADISON ST #1-4		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No		
608 N HARPER ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
801 N WASHINGTON ST		No	No	1925	1925	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No		
609 N WASHINGTON ST B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
611 E BROWNING ST		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
804 N LOGAN ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
511 N LOGAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
603 E PARHAM ST #B		No	No	1980	1980	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
707 N TAFT ST		No	No	2023	1961	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
709 N TAFT ST		No	No	1948	1948	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1403 E PARHAM ST		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1408 E PARHAM ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1406 E PARHAM ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
808 N MCLAREN ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
805 N MCLAREN ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
803 N HARTKOPF ST		No	No	1937	1937	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
803 N MCLAREN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
800 N MCLAREN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
801 N HARTKOPF ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
805 E PARHAM ST		No	No	1919	1919	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
709 N MCLAREN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
707 N HARTKOPF ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
707.5 N MCLAREN ST		No	No	1930	1930	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
703 N HARTKOPF ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
707 N MCLAREN ST		No	No	2019	1920	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
702 N MCLAREN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1106 E GRIGGS ST		No	No	1973	1973	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
703 N MCLAREN ST		No	No	1900	1900	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
609 N HARTKOPF ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1113 E GRIGGS ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1104 E GRIGGS ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1102 E GRIGGS ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1001 E BROWNING ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
607 N MCLAREN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
605 N MCLAREN ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1007 E GRIGGS ST 1		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 E MCKINLEY ST A		No	No	2022	1932	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1007 E GRIGGS ST 7		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 E MCKINLEY ST #B		No	No	2022	1932	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
600 N FAIR ST		No	No	2022	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1007 E GRIGGS ST 3		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1007 E GRIGGS ST 6		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1007 E GRIGGS ST 2		No	No	2024	1970	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1007 E GRIGGS ST 8		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
512 N FAIR ST		No	No	2022	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
601 N FAIR ST		No	No	2022	1978	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
604 N FAIR ST		No	No	1975	1975	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
605 N FAIR ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
606 N FAIR ST		No	No	1918	1918	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
607 N FAIR ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
610 N FAIR ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
609 N FAIR ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 E PARHAM ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
611 N FAIR ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
704 N FAIR ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1305 E PARHAM ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1304 E PARHAM ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1300 E PARHAM ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1207 E PARHAM ST		No	No	2022	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
1301 E PARHAM ST		No	No	1940	1940	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
708 N FAIR ST		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1205 E PARHAM ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1201 E PARHAM ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
804 N FAIR ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
812 N FAIR ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
810 N FAIR ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
808 N FAIR ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1007 E GRIGGS ST 4		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
805 N FAIR ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1007 E GRIGGS ST 5		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
609 N WASHINGTON ST A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL) Unknown (U) Unknown (U) Unknown (U) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
800 E PARHAM ST		No	No	2022	1977	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
805 N WASHINGTON ST B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
404 E BOULEVARD ST #B		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No			No	
1205 E BOYTON ST #1-4		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1203 E BOYTON ST		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1207 E BOYTON ST #1-4		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1105 E BOYTON ST #1-4		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1209 E BOYTON ST #1-4		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1103 E BOYTON ST #1-4		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1201 E BOYTON ST #1-4		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
505 E REEVES ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
908 N WASHINGTON ST		No	No	2022	1960	Maintenance Records	Copper	C	CLS	NL	N	N/R	No			No	
902 N WASHINGTON ST		No	No	2021	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
905 E Reeves St		No	No	1928	1928	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
903 N RADCLIFF ST A		No	No	1980	1980	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
903 N RADCLIFF ST D		No	No	1980	1980	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
901 N RADCLIFF ST A		No	No	1980	1980	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
901 N RADCLIFF ST B		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
901 N RADCLIFF ST C		No	No	1980	1980	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
901 N RADCLIFF ST D		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
904 N RADCLIFFE ST		No	No	1960	1960	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
908 N RADCLIFFE ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1314 E BOULEVARD ST		No	No	1979	1979	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1310 E BOULEVARD ST		No	No	1921	1921	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
1308 E BOULEVARD ST		No	No	1910	1910	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1305 E BOULEVARD ST #REAR		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 E BOULEVARD ST		No	No	1970	1970	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1301 E BOULEVARD ST #REAR		No	No	1973	1973	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1210 E BOULEVARD ST		No	No	1949	1949	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
805 N HARTKOPF ST #B		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
805 N HARTKOPF ST #A		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
806 N HARTKOPF ST		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1205 E BOULEVARD ST		No	No	1924	1924	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
901 ROOSEVELT AVE		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1203 E BOULEVARD ST		No	No	1924	1924	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
602 E REEVES ST A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
602 E REEVES ST B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1201 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
604 E REEVES ST		No	No	2019	1945	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
909 N WASHINGTON ST		No	No	1959	1959	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
605 E REEVES ST		No	No	1914	1914	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
906 N RADCLIFFE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1000 N WHITMAN DR		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1107 E BOULEVARD ST		No	No	2022	1920	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1105 E BOULEVARD ST		No	No	1985	1985	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
1002 N WHITMAN DR		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1102 E BOULEVARD ST		No	No	1982	1982	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1003 N WHITMAN DR		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1008 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1001 N WHITMAN DR		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1004 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
702 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1001 E BOULEVARD ST		No	No	2009	2009	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
706 E REEVES ST B		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
904 E BOULEVARD ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
706 E REEVES ST A		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1002 N OTIS ST B		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1002 N OTIS ST A		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1004 N OTIS ST A		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1004 N OTIS ST B		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
900 E BOULEVARD ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
808 E BOULEVARD ST		No	No	1920	1920	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
809 E BOULEVARD ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
800 E REEVES ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
802 E REEVES ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
804 E REEVES ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
806 E REEVES ST		No	No	1906	1906	Survey Response	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
900 E REEVES ST		No	No	2013	1922	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
807 E REEVES ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
901 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
902 E REEVES ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1309 E REEVES ST		No	No	1936	1936	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
904 E REEVES ST		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1208 E REEVES ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
906 E REEVES ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 E REEVES ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
907 E REEVES ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
909 E REEVES ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
1207 E REEVES ST		No	No	1977	1977	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1003 N TAFT ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1111 E REEVES ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1112 E REEVES ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1106 E REEVES ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1102 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1100 E REEVES ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1011 E REEVES ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1006 E REEVES ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1004 E REEVES ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1002 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
903 N RADCLIFF ST B		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
903 N RADCLIFF ST C		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
910 N WASHINGTON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
603 E REEVES ST	LP1C006	No	No	Unknown	1900	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
607 E REEVES ST		No	No	1914	1914	Maintenance Records	Unknown	P	CLS	NL	N	N/R	No		No		
801 E BOULEVARD ST		No	No	1961	1961	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
510 E REEVES ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
910 N RADCLIFFE ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1003 N MCLAREN ST		No	No	1962	1962	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
801 E CARTER ST		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1005 N OTIS ST		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
805 E CARTER ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
800 E CARTER ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
802 E CARTER ST		No	No	1920	1920	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
807 E CARTER ST		No	No	1905	1905	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
808 E CARTER ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1005 N MCLAREN ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
900 E CARTER ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
904 E CARTER ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
903 E CARTER ST		No	No	1935	1935	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
905 E CARTER ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
907 E CARTER ST		No	No	1975	1975	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1000 E CARTER ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1002 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1003 E CARTER ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1004 E CARTER ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1006 E CARTER ST		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1005 E CARTER ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1007 E CARTER ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1008 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1013 E CARTER ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1101 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1100 E CARTER ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1105 E CARTER ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1102 E CARTER ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1104 E CARTER ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1111 E CARTER ST		No	No	1930	1930	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1110 E CARTER ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1200 E CARTER ST		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1201 E CARTER ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1204 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1207 E CARTER ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1209 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1211 E CARTER ST		No	No	1955	1955	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
906 E ILLINOIS ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1009 N TAFT ST		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
805 E DEYOUNG ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
803 E DEYOUNG ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1403 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1401 DEW DROP DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1305 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
808 E DEYOUNG ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
900 E DEYOUNG ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
906 E DEYOUNG ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
810 E THOMPSON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
811 E CARTER ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
807 E DE YOUNG ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1102 N OTIS ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1009 E CARTER ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1103 E CARTER ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1601 E DE YOUNG ST		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1104 PHEMISTER DR		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1103 FOLGERS ST		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1711 N SMITH AVE		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1707 N FAIR ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1113 GLORY LN		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2007 DEW DROP DR		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2004 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2002 DEW DROP DR		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1906 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1908 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1801 NORMAN RD		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1722 NORMAN RD		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1714 FELTS DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1508 E WILLOW DR		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1711 FELTS DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
501 E REEVES ST #A		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No			No	
908 N GARFIELD ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
909 N GARFIELD ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
907 N GARFIELD ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
912 N GARFIELD ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
413 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
405 E REEVES ST		No	No	2022	2022	Construction Records	Copper	C	P	NL	N	N/R	No			No	
1000 N GARFIELD ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1003 N GARFIELD ST		No	No	1957	1957	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1005 N GARFIELD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1006 N GARFIELD ST		No	No	1957	1957	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
1008 N GARFIELD ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1009 N GARFIELD ST	LP1A070	No	No	1940	1940	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
1012 N GARFIELD ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
403 E CARTER ST		No	No	1975	1975	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
416 E CARTER ST		No	No	2021	1900	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
406 E CARTER ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
404 E CARTER ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
511 E DEYOUNG ST		No	No	1993	1993	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
509 E DEYOUNG ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1114 N WASHINGTON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
508 E CARTER ST		No	No	1949	1949	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
510 E CARTER ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1105 N WASHINGTON ST #A		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1105 N WASHINGTON ST #B		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1105 N WASHINGTON ST #C		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1105 N WASHINGTON ST #D		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1010 N WASHINGTON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1008 N WASHINGTON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1006 N WASHINGTON ST		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
910 N GARFIELD ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
412 E REEVES ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
1212 N GARFIELD ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)							
506 E CARTER ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1008 N OTIS ST #A		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
705 E CARTER ST		No	No	1913	1913	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
705 E CARTER ST #REAR		No	No	1913	1913	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
607 E CARTER ST	LP1C011	No	No	Unknown	Unknown	Visual Inspection	Lead	P	P	NL	N	N/R	No			No	
503 E CARTER ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
401 E DEYOUNG ST		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1105 N LOGAN ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
309 E DEYOUNG ST		No	No	1971	1971	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1104 N LOGAN ST		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1103 N LOGAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1012 N LOGAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1006 N LOGAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1003 N LOGAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1004 N LOGAN ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1000 N LOGAN ST		No	No	1920	1920	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1001 N LOGAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
909 N LOGAN ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
908 N LOGAN ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
906 N LOGAN ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
910 N LOGAN ST		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
311 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
307 E REEVES ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
306 E REEVES ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
304 E REEVES ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
303 E REEVES ST #A		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
303 E REEVES ST #B		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
914 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
916 N STATE ST		No	No	2005	2005	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1001 N STATE ST		No	No	1900	1900	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1005 N STATE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1009 N STATE ST		No	No	Unknown	Unknown	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
1010 N STATE ST		No	No	1965	1965	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1015 N STATE ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1103 N STATE ST		No	No	1940	1940	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1105 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1104 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1107 N STATE ST		No	No	1900	1900	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
222 E CARTER ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
224 E CARTER ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1108 N STATE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
918 N STATE ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1007 N STATE ST		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1112 N STATE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
902 N MADISON ST		No	No	1982	1982	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Galvanized Requiring Replacement (GRR) Unknown (U) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
903 N MADISON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	C	UNL	NL	N	N/R	No			No		
906 N MADISON ST		No	No	1987	1987	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		
106 E STOCKTON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1001 N MARKET ST		No	No	1907	1907	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
110 E STOKTON ST		No	No	1935	1935	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
1002 N MADISON ST		No	No	1957	1957	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
215 E CHARLES ST #A		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
215 E CHARLES ST #B		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
215 E CHARLES ST #C		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
214 E CHARLES ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
212 E CHARLES ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
210 E CHARLES ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
206 E CHARLES ST		No	No	1928	1928	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No		
200 E CHARLES ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1004 N MADISON ST		No	No	1920	1920	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		
1006 N MADISON ST		No	No	1920	1920	Visual Inspection	Lead	P	P	NL	N	N/R	No			No		
1008 N MADISON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Lead	P	UNL	NL	N	N/R	No			No		
406 E DEYOUNG ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1304 N GARFIELD ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No		
1306 N GARFIELD ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
1308 N GARFIELD ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1310 N GARFIELD ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1402 N GARFIELD ST		No	No	1966	1966	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1404 N GARFIELD ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
506 E ILLINOIS ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
500 E ILLINOIS ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1513 N GARFIELD ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1515 N GARFIELD ST		No	No	1970	1970	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
502 E CLARK ST		No	No	1980	1980	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
504 E CLARK ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
600 E CLARK ST		No	No	1974	1974	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
602 E CLARK ST		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
604 E CLARK ST		No	No	1978	1978	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
904 N MADISON ST		No	No	1987	1987	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
1606 N GARFIELD ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1604 N GARFIELD ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1602 N GARFIELD ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
408 E CLARK ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
406 E CLARK ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
405 E CLARK ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
403 E CLARK ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
402 E CLARK ST		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
402 E ILLINOIS ST		No	No	1940	1940	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1506 N LOGAN ST		No	No	1945	1945	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1505 N LOGAN ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
306 E CLARK ST		No	No	1940	1940	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1309 N LOGAN ST		No	No	1940	1940	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
400 E ILLINOIS ST		No	No	1920	1920	Maintenance Records	Unknown	P	CLS	NL	N	N/R	No		No		
401 E ILLINOIS ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1308 N LOGAN ST		No	No	1910	1910	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No		
308 E ILLINOIS ST		No	No	1950	1950	Survey Response	Unknown	C	G	NL	N	N/R	No		No		
306 E ILLINOIS ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
302 E CLARK ST #A		No	No	2019	2010	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
302 E CLARK ST #B		No	No	2019	2010	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
301 E CLARK ST		No	No	1940	1940	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
210 E DEYOUNG ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1207 N STATE ST		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1204 N STATE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1211 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1213 N STATE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1210 N STATE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 N STATE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1212 N STATE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1311 N STATE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
203 E MCDONALD ST A		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
203 E MCDONALD ST B		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1313 N STATE ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1315 N STATE ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1402 N STATE ST #A		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1402 N STATE ST #B		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1402 N STATE ST #D		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1404 N STATE ST		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1505 N STATE ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1406 N STATE ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1509 N STATE ST		No	No	1920	1920	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
207 E PATRICK ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
206 E PATRICK ST		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
208 E PATRICK ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1502 N STATE ST		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1504 N STATE ST		No	No	1959	1959	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1508 N STATE ST		No	No	1940	1940	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
1502 N LOGAN ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1407 N LOGAN ST		No	No	2020	1910	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
1308 N STATE ST		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1208 N STATE ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1402 N STATE ST #C		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1904 N STATE ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1815 BRIDGE ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1813 BRIDGE ST "Empty Lot"		No	No	2019	Unknown	Construction Records	Plastic	P	UNL	NL	N	N/R	No		No		
401 E REICHERT DR		Yes	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1507 N GLENDALE ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1505 N GLENDALE ST #B		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
202 E PATRICK ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1411 N GLENDALE ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1409 N GLENDALE ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1410 N GLENDALE ST		No	No	1976	1976	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1400 N GLENDALE ST		No	No	1948	1948	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
109 E FINUCANE ST		No	No	2024	1993	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1311 N GLENDALE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 N GLENDALE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1305 N GLENDALE ST		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1302 N GLENDALE ST		No	No	1951	1951	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1301 N GLENDALE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
201 E MCDONALD ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1215 N GLENDALE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1213 N GLENDALE ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1210 N GLENDALE ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1208 N GLENDALE ST "Empty Lot"		No	No	1906	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1211 N GLENDALE ST #C		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1211 N GLENDALE ST #D		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1209 N GLENDALE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1206 N GLENDALE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
202 E DEYOUNG ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
203 E DEYOUNG ST		No	No	1980	1980	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
201 E DEYOUNG ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
208 W DEYOUNG ST		No	No	2004	2004	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
110 E DEYOUNG ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
108 E DEYOUNG ST		No	No	1942	1942	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
108 E MCDONALD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
104 E MCDONALD ST		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
102 E FINUCANE ST		No	No	1917	1917	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
106 E FINUCANE ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
105 E PATRICK ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1413 N COURTNEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1405 N COURTNEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1403 N COURTNEY ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
1400 N COURTNEY ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
101 E FINUCANE ST A		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
101 E FINUCANE ST B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
101 E FINUCANE ST C		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
101 E FINUCANE ST D		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1310 N COURTNEY ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1309 N COURTNEY ST		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1303 N COURTNEY ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1216 N COURTNEY ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1300 N COURTNEY ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1214 N COURTNEY ST		No	No	1973	1973	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1211 N COURTNEY ST		No	No	2008	2008	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
102 E DEYOUNG ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1200 N MARKET ST		No	No	1963	1963	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1201 N MARKET ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1207 N MARKET ST #A-B		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1216 N MARKET ST		No	No	1912	1912	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
101 W PATRICK ST		No	No	1903	1903	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
100 W PATRICK ST		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
205 W PATRICK ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1409 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1407 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1406 N VAN BUREN ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1405 N VAN BUREN ST		No	No	1910	1910	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1314 N VAN BUREN ST #A		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1314 N VAN BUREN ST #B		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1308 N VAN BUREN ST #B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1308 N VAN BUREN ST #A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1309 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1306 N VAN BUREN ST		No	No	1920	1920	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
1305 N VAN BUREN ST		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1304 N VAN BUREN ST		No	No	2014	2014	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1303 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1217 N VAN BUREN ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1215 N VAN BUREN ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1216 N VAN BUREN ST #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1216 N VAN BUREN ST #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1216 N VAN BUREN ST #C		No	No	2007	2007	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1210 N VAN BUREN ST #A		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1210 N VAN BUREN ST #B		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1210 N VAN BUREN ST #C		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1206 N VAN BUREN ST		No	No	1910	1910	Visual Inspection	Unknown	P	G	NL	N	N/R	No			No	
1205 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1203 N VAN BUREN ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1204 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
200 W DEYOUNG ST		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1205 N MONROE ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
213 W MCDONALD ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
212 W MCDONALD ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
211 W MCDONALD ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
208 W MCDONALD ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1505 N GLENDALE ST #A		No	No	1974	1974	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
204 E PATRICK ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1402 N GLENDALE ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1211 N GLENDALE ST #B		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1214 N MARKET ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
205 E PATRICK ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1303 N GLENDALE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1211 N GLENDALE ST #A		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
206 W DEYOUNG ST		No	No	1920	1920	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1408 N MARKET ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
204 TOWER SQ PL #F		No	Yes	2023	2022	Maintenance Records	Plastic	P	P	NL	N	11/15/2023	Yes	11/15/2023	P	No	
111 N MARKET ST		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	11/7/2023	Yes	11/8/2023	P	No	
107 E UNION ST		No	Yes	2023	1915	Maintenance Records	Plastic	P	CLS	NL	N	11/14/2023	Yes	11/15/2023	P	No	
115 W UNION ST		No	No	1912	1912	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
310 N MARKET ST		No	No	Unknown	Unknown	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
401 N MARKET ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
413 N MARKET ST		No	No	1905	1905	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
411 N MARKET ST		No	No	1905	1905	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
500 N MARKET ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
104 W CALVERT ST		No	No	2001	2001	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
612 N MARKET ST		No	No	1914	1914	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
801 N MARKET ST		No	No	1966	1966	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Non-Lead (NL)	Galvanized Requiring Replacement (GRR) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
803 N MARKET ST		No	No	1942	1942	Visual Inspection	Unknown	P	G	NL	N	N/R	No			No		
800 N MARKET ST		No	No	1960	1960	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No		
812 N MARKET ST		No	No	1901	1901	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No		
904 N MARKET ST		No	No	1890	1890	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
908 N MARKET ST		No	No	1982	1982	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No		
909 N MARKET ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
207 W DEYOUNG ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
700 N MARKET ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No		
906 N MARKET ST		No	No	1950	1950	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No		
911 N MARKET ST		No	No	1949	1949	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
1114 N MONROE ST		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No		
1109 N MONROE ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
1110 N MONROE ST		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No		
1104 N MONROE ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No		
1100 N MONROE ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No		
1103 N MONROE ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
1022 N GRANITE ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
1101 N GRANITE ST		No	No	1982	1982	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No		
1014 N MONROE ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1015 N MONROE ST "Empty Lot"		No	No	1920	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1009 N MONROE ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1010 N MONROE ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1008 N MONROE ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1005 N MONROE ST		No	No	1935	1935	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1014 N GRANITE ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1010 N GRANITE ST A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1010 N GRANITE ST B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1012 N GRANITE ST A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1012 N GRANITE ST B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1008 N GRANITE ST A		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1008 N GRANITE ST B		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
304 W STOCKTON ST		No	No	1983	1983	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1003 N MONROE ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1000 N MONROE ST		No	No	1983	1983	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
306 W STOCKTON ST #A		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
306 W STOCKTON ST #B		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
309 W STOCKTON ST		No	No	2024	1983	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
307 W STOCKTON ST #A		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
307 W STOCKTON ST #B		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
305 W STOCKTON ST		No	No	1982	1982	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
400 N MARKET ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
503 N VAN BUREN ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
506 N MARKET ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
514 N MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
207 W STOCKTON ST #A		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
207 W STOCKTON ST #B		No	No	1983	1983	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
910 N MONROE ST		No	No	2024	1982	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
905 N MONROE ST #A		No	No	1985	1985	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
905 N MONROE ST #B		No	No	1985	1985	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
903 N MONROE ST #A		No	No	2005	2005	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
110 W BOULEVARD ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
903 N MONROE ST #B		No	No	2005	2005	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
108 W BOULEVARD ST		No	No	1898	1898	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
908 N GRANITE ST		No	No	1925	1925	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
900 N MARKET ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
905 N GRANITE ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1000 N MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
904 N GRANITE ST #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
910 N MARKET ST		No	No	1908	1908	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
904 N GRANITE ST #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
903 N GRANITE ST		No	No	1938	1938	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1003 N MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
902 N GRANITE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
400 W BOULEVARD ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1006 N MARKET ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
308 W BOULEVARD ST		No	No	1922	1922	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1007 N MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1011 N MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
401 W BOULEVARD ST #A		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1013 N MARKET ST		No	No	2023	1920	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
401 W BOULEVARD ST #B		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1014 N MARKET ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1015 N MARKET ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
309 W BOULEVARD ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1016 N MARKET ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
303 W BOULEVARD ST		No	No	1903	1903	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
300 W BOULEVARD ST		No	No	1952	1952	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1018 N MARKET ST		No	No	1929	1929	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1017 N MARKET ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1020 N MARKET ST		No	No	1900	1900	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
207 W BOULEVARD ST #B		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1022 N MARKET ST		No	No	1920	1920	Maintenance Records	Unknown	C	CLS	NL	N	N/R	No		No		
206 W BOULEVARD ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
200 W BOULEVARD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
810 N GRANITE ST		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
809 N GRANITE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1114 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
808 N GRANITE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
807 N GRANITE ST		No	No	1982	1982	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1111 N VAN BUREN ST		No	No	1970	1970	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
803 N GRANITE ST		No	No	2017	2017	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1104 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
302 W GOODALL ST		No	No	2024	1970	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1100 N VAN BUREN ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1016 N VAN BUREN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
208 W GOODALL ST #B		No	No	1984	1984	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
208 W GOODALL ST #D		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
208 W GOODALL ST #C		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
804 N MONROE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
805 N MONROE ST #A		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1008 N VAN BUREN ST		No	No	2019	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
805 N MONROE ST #B		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
206 W GOODALL ST B		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
807 N MONROE ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
809 N MONROE ST		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1005 N VAN BUREN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
200 W STOCKTON ST A		No	No	1985	1985	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
200 W STOCKTON ST		No	No	1985	1985	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
110 W STOCKTON ST		No	No	1982	1982	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)							
400 W WHITE ST		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
204 W STOCKTON ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
404 W WHITE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
314 W WHITE ST		No	No	2024	2024	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
312 W WHITE ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
205 W STOCKTON ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
201 W STOCKTON ST #A		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
306 W WHITE ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
309 W WHITE ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
905 N VAN BUREN ST		No	No	1954	1954	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
908 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
704 N MONROE ST #A		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
906 N VAN BUREN ST		No	No	1928	1928	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
704 N MONROE ST #B		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
904 N VAN BUREN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
210 W WHITE ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
707 N MONROE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
706 N MONROE ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
301 W GOODALL ST		No	No	2024	1910	Maintenance Records	Copper	C	G	NL	N	N/R	No			No	
201 W BOULEVARD ST		No	No	1920	1920	Visual Inspection	Lead	P	CLS	NL	N	N/R	No			No	
209 W GOODALL ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
204 W GOODALL ST #A		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
		Examples:					Lead (L)	Lead (L)									
		Cast/Ductile Iron or Transite (O)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
		Plastic - PVC, HDPE, PEX (P)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
	Yes (Y) or No (N)					Unknown (U)	Unknown (U)	Unknown (U)									
						Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)						Leave blank if no Lead Service Line was replaced.		
204 W GOODALL ST #B		No	No	Unknown	Unknown	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
206 W WHITE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
811 N VAN BUREN ST		No	No	1915	1915	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
809 N VAN BUREN ST		No	No	2024	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
808 N VAN BUREN ST		No	No	1930	1930	Visual Inspection	Lead	P	P	NL	N	N/R	No			No	
805 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Lead	P	CLS	NL	N	N/R	No			No	
807 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
802 N VAN BUREN ST		No	No	1960	1960	Visual Inspection	Lead	P	P	NL	N	N/R	No			No	
709 N VAN BUREN ST		No	No	1955	1955	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
710 N VAN BUREN ST		No	No	1920	1920	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
707 N VAN BUREN ST		No	No	1948	1948	Visual Inspection	Lead	P	P	NL	N	N/R	No			No	
704 N VAN BUREN ST #A		No	No	1994	1994	Visual Inspection	Lead	P	C	NL	N	N/R	No			No	
704 N VAN BUREN ST #B		No	No	1994	1994	Visual Inspection	Lead	P	C	NL	N	N/R	No			No	
704 N VAN BUREN ST #C		No	No	1994	1994	Visual Inspection	Lead	C	C	NL	N	N/R	No			No	
704 N VAN BUREN ST #D		No	No	1994	1994	Visual Inspection	Lead	P	C	NL	N	N/R	No			No	
809 N COURT ST		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
803 W BOULEVARD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
807 W BOULEVARD ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
809 W BOULEVARD ST		No	No	1953	1953	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
901 W BOULEVARD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
905 W BOULEVARD ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
904 W BOULEVARD ST		No	No	2023	2023	Maintenance Records	Copper	C	C	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
907 W BOULEVARD ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
811 N VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
806 N JOHNSON ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
805 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
800 W GOODALL ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
701 N COURT ST #SPRIN		No	No	1986	1986	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
701 N COURT ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
704 N JOHNSON ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
702 N JOHNSON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
603 N GRANITE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
611 N COURT ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
607 N COURT ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
600 N COURT ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
603 N COURT ST ICE MACHINE		No	No	1980	1980	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
601 N JOHNSON ST		No	No	1951	1951	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
600 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
602 N JOHNSON ST		No	No	1925	1925	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
603 N JOHNSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
608 N JOHNSON ST		No	No	1948	1948	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
607 N JOHNSON ST		No	No	2023	2023	Construction Records	Copper	C	P	NL	N	N/R	No		No		
705 W WHITE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
802 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
804 W WHITE ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
903 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
901 W WHITE ST		No	No	1935	1935	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
809 W WHITE ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
608 N HIGHLAND ST		No	No	2024	1920	Maintenance Records	Plastic	C	P	NL	N	N/R	No		No		
604 N HIGHLAND ST		No	No	1920	1920	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
600 N HIGHLAND ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
501 N WALKER ST		No	No	1988	1988	Survey Response	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
305 W GOODALL ST		No	No	2024	1920	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
814 N MARKET ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
501 W DEYOUNG ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
503 W DEYOUNG ST		No	No	2012	2012	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1107 N COURT ST		No	No	1924	1924	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
904 N JOHNSON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
906 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
908 N JOHNSON ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
912 N JOHNSON ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
706 W STOCKTON ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1000 N JOHNSON ST		No	No	2022	1920	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
1002 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1006 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1003 N JOHNSON ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1007 N JOHNSON ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1010 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1014 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1015 N JOHNSON ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1013 N JOHNSON ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1101 N JOHNSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1104 N JOHNSON ST		No	No	2023	1930	Maintenance Records	Copper	C	CLS	NL	N	N/R	No		No		
805 W DEYOUNG ST #A		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
805 W DEYOUNG ST #B		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
805 W DEYOUNG ST #C		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
805 W DEYOUNG ST #D		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
805 W DEYOUNG ST #E		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
805 W DEYOUNG ST #F		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1103 N JOHNSON ST		No	No	1901	1901	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1107 N JOHNSON ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1109 N JOHNSON ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
903 N HIGHLAND ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
909 N HIGHLAND ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
908 N HIGHLAND ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1000 N HIGHLAND ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
905 W DEYOUNG ST		No	No	2014	2014	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1012 N VICKSBURG ST #A		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1012 N VICKSBURG ST #B		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1012 N VICKSBURG ST #C		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1012 N VICKSBURG ST #D		No	No	2019	2019	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1012 N VICKSBURG ST #E		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
904 W STOCKTON ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1000 W BOULEVARD ST		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1102 W BOULEVARD ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1003 W BOULEVARD ST		No	No	1945	1945	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1008 W BOULEVARD ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1007 W BOULEVARD ST		No	No	1963	1963	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1009 W BOULEVARD ST		No	No	1971	1971	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1103 W BOULEVARD ST #B		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1103 W BOULEVARD ST #A		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1100 W BOULEVARD ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
905 N BENTLEY ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
911 N BENTLEY ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
804 SCORCHEE RD		No	No	2004	2004	Survey Response	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
904 N MONROE ST		No	No	1924	1924	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1021 N MARKET ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
209 W BOULEVARD ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
804 N GRANITE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1012 N VAN BUREN ST		No	No	1929	1929	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1007 N VAN BUREN ST		No	No	2019	1929	Maintenance Records	Copper	C	G	NL	N	N/R	No			No	
206 W GOODALL ST A		No	No	1984	1984	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
810 N MONROE ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
305 W WHITE ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
806 W WHITE ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1105 N Highland st		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1010 N MARKET ST #SPRIN		No	No	1890	1890	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
305 W BOULEVARD ST		No	No	1950	1950	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
207 W BOULEVARD ST #A "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
1110 N VAN BUREN ST		No	No	2014	2014	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1106 N VAN BUREN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1103 N VAN BUREN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
208 W GOODALL ST #A		No	No	1984	1984	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
310 W WHITE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
705 N MONROE ST		No	No	2024	1920	Maintenance Records	Copper	C	CLS	NL	N	N/R	No			No	
207 W GOODALL ST		No	No	1924	1924	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
204 W WHITE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
806 N MONROE ST "Empty Lot"		No	No	1930	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
610 N MONROE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
903 N VAN BUREN ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
208 W WHITE ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
710 W GOODALL ST		No	No	2024	1900	Maintenance Records	Copper	C	G	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
906 N HIGHLAND ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1308 W MAIN ST		No	No	1935	1935	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1310 W MAIN ST		No	No	2019	1905	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
208 W MAIN ST		No	Yes	2023	1967	Maintenance Records	Copper	C	CLS	NL	N	10/30/2023	Yes	10/30/2023	C	No	
102 W MAIN ST		No	Yes	2023	1970	Maintenance Records	Plastic	P	CLS	NL	N	10/30/2023	Yes	10/30/2023	P	No	
307 N VAN BUREN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
305 N VAN BUREN ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
300 N MONROE ST		No	No	1980	1980	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
304 N MONROE ST		No	No	1925	1925	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
502 W JEFFERSON ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
506 W JEFFERSON ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
504 W JEFFERSON ST		No	No	2024	1900	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
302 N GRANITE ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
601 W JACKSON ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
503 W JACKSON ST		No	No	1945	1945	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
500 N HOLLAND ST		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
406 N MONROE ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
404 N MONROE ST		No	No	2024	1977	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
411 N COURT ST		No	No	2024	1990	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
403 N COURT ST		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
201 N COURT ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
103 N COURT ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
102 N COURT ST		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
818 W MAIN ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
922 W MAIN ST		No	No	1987	1987	Maintenance Records	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
928 W MAIN ST spare tap "Empty Lot"		No	No	2021	Unknown	Construction Records	Copper	C	UNL	NL	N	N/R	No		No		
109 N VICKSBURG ST		No	No	1910	1910	Survey Response	Unknown	C	G	NL	N	N/R	No		No		
922 W UNION ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
924 W UNION ST		No	No	1934	1934	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
914 W MAIN ST		No	No	Unknown	Unknown	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
906 W UNION ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
204 N COURT ST		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
302 N COURT ST		No	No	2024	2010	Maintenance Records	Copper	C	C	NL	N	N/R	No		No		
1003 ELM ST B		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
206 N VICKSBURG ST		No	No	1966	1966	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
300 N VICKSBURG ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1004 ELM ST A		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1004 ELM ST B REA		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1004 ELM ST C		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1004 W LEE AVE		No	No	1977	1977	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
305 N VICKSBURG ST		No	No	1925	1925	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
302 N VICKSBURG ST #A-B		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
403 N VICKSBURG ST		No	No	2024	1930	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
405 N VICKSBURG ST		No	No	1926	1926	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/Pigtail	PWS-Owned Service Line Material Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Customer Side Service Line Material Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Classification for Entire Service Line Examples: Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL)	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
306 N VICKSBURG ST		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
409 N VICKSBURG ST		No	No	1913	1913	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1012 W MAIN ST		No	No	1915	1915	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
1018 W MAIN ST		No	No	2017	2017	Construction Records	Copper	C	C	NL	N	N/R	No			No	
200 N BENTLEY ST		No	No	2024	1897	Maintenance Records	Plastic	P	G	NL	N	N/R	No			No	
202 N BENTLEY ST		No	No	2024	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
203 N BENTLEY ST		No	No	2024	1945	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
204 N BENTLEY ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
206 N BENTLEY ST		No	No	2024	1930	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
1009 W LEE AVE A		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1009 W LEE AVE C		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
210 N BENTLEY ST		No	No	2024	1940	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1012 W LEE AVE #A		No	No	2024	1995	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1010 W LEE AVE #A		No	No	2024	1995	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1010 W LEE AVE #B		No	No	2024	1995	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1103 W LEE AVE		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
303 N BENTLEY ST		No	No	2024	1963	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
304 N BENTLEY ST #A		No	No	2024	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
304 N BENTLEY ST #B		No	No	2024	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
304 N BENTLEY ST #C		No	No	2024	2014	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
313 N BENTLEY ST		No	No	2024	1910	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
308 N BENTLEY ST		No	No	2024	1920	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
308 N HAMLET ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
309 N HAMLET ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
307 N HAMELET ST		No	No	1910	1910	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
304 N HAMLET ST		No	No	1947	1947	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
305 N HAMLET ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1201 W LEE AVE		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
209 N HAMLET ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
205 N HAMLET ST		No	No	1918	1918	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
200 N HAMLET ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
203 N HAMLET ST #A		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
203 N HAMELET ST #B		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
203 N HAMLET ST #C		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
203 N HAMLET ST #D		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
105 N HAMLET ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
103 N HAMLET ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1304 W MAIN ST		No	No	1938	1938	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1200 W MAIN ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
102 N LEAR ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
104 N LEAR ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
107 N LEAR ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
202 N LEAR ST		No	No	1926	1926	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
204 N LEAR ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1212 W LEE AVE		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
301 N LEAR ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 W LEE AVE #A		No	No	2014	2014	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
300 N LEAR ST #A		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1306 W LEE AVE		No	No	1941	1941	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1308 W LEE AVE		No	No	1941	1941	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1414 W MAIN ST		No	No	1906	1906	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1408 W MAIN ST #A-B		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1406 W MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1400 W MAIN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
405 N COURT ST		No	No	2024	1968	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
408 N COURT ST		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
102 N VICKSBURG ST		No	No	2020	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
104 N VICKSBURG ST #A-B		No	No	1940	1940	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
201 N VICKSBURG ST #A		No	No	1940	1940	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1003 ELM ST A		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
201 N VICKSBURG ST #B		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1003 W LEE AVE		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
205 N VICKSBURG ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1010 W MAIN ST		No	No	1945	1945	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1002 ELM ST		No	No	2024	1996	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1104 W LEE AVE		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
316 N BENTLEY ST		No	No	2024	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
302 N HAMLET ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
103 N LEAR ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1208 W LEE AVE		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 W LEE AVE #B		No	No	2014	2014	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
300 N LEAR ST #B		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1304 W LEE AVE		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
302 N BENTLEY ST		No	No	2024	1959	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1009 W LEE AVE B		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1012 W LEE AVE #B		No	No	2024	1995	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
805 N VICKSBURG ST		No	No	1905	1905	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 W GOODALL ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
710 N VICKSBURG ST		No	No	2024	1920	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1101 W WHITE ST		No	No	2024	1917	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
601 N LEAR ST		No	No	2024	1950	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1125 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
714 N CARBON ST		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1000 N CARBON ST L		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1000 N CARBON ST X		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2003 INDUSTRIAL PARK DR		No	No	1981	1981	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1607 W FAUST ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1707 W FAUST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
303 N CARBON ST		No	No	1973	1973	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No		
1712 W DEWEY ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
1715 W DEWEY ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
1702 W MAIN ST		No	No	2022	1910	Maintenance Records	Copper	C	G	NL	N	N/R	No			No		
101 N 5TH ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
123 N SEVENTH ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
311 S 4TH ST		No	No	2023	2023	Construction Records	Copper	C	P	NL	N	N/R	No			No		
406 S CARBON ST		No	No	1945	1945	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
1901 W CHERRY ST		No	No	1950	1950	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No		
901 S CARBON ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No		
1701 W HENDRICKSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
402 N WALKER ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
406 N WALKER ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
607 N VICKSBURG ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No		
602 HALFWAY RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
1133 N CARBON ST SPRINK		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1116 N CARBON ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1904 W RENDLEMAN ST		No	No	1983	1983	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
1706 MARCELLA DR		No	No	1972	1972	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No		
1108 N CARBON ST #A & B		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
1000 N CARBON ST		No	No	1979	1979	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
907 W CENTRAL ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1001 W CENTRAL ST		No	No	1965	1965	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
810 N HIGHLAND ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
808 N HIGHLAND ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
807 N HIGHLAND ST		No	No	1930	1930	Maintenance Records	Copper	C	CLS	NL	N	N/R	No		No		
804 N HIGHLAND ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
800 N HIGHLAND ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
710 N HIGHLAND ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
708 N HIGHLAND ST		No	No	1977	1977	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
909 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
906 W WHITE ST		No	No	1965	1965	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
701 N VICKSBURG ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
709 N VICKSBURG ST		No	No	1920	1920	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
711 N VICKSBURG ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
708 N VICKSBURG ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
800 N VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
804 N VICKSBURG ST		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
807 N VICKSBURG ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
810 N VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1008 W GOODALL ST		No	No	2024	1900	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No		No		
1005 W GOODALL ST		No	No	1902	1902	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1011 W GOODALL ST		No	No	1962	1962	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1012 W GOODALL ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1100 W GOODALL ST		No	No	1900	1900	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
1106 W GOODALL ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1108 W GOODALL ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1107 W GOODALL ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1110 W GOODALL ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1109 W GOODALL ST		No	No	1968	1968	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1200 W WHITE ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
702 N HAMLET ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
704 N HAMLET ST		No	No	1964	1964	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1201 W GOODALL ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1200 W GOODALL ST		No	No	2019	1945	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1204 W GOODALL ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1203 W GOODALL ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1205 W GOODALL ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1208 W GOODALL ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1207 W GOODALL ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1210 W GOODALL ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1209 W GOODALL ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1212 W GOODALL ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1214 W GOODALL ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1211 W GOODALL ST		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1408 W GOODALL ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1410 W GOODALL ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1409 W GOODALL ST		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
403 N RUSSELL ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
605 N RUSSELL ST		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1307 W WHITE ST #B		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 W WHITE ST #A		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 W WHITE ST #C		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1307 W WHITE ST #D		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1305 W WHITE ST		No	No	1970	1970	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1304 W WHITE ST		No	No	1956	1956	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1302 W WHITE ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1303 W WHITE ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1301 W WHITE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1300 W WHITE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1204 W WHITE ST		No	No	1956	1956	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1211 W WHITE ST		No	No	2024	1940	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1209 W WHITE ST		No	No	2024	1935	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1202 W WHITE ST		No	No	1956	1956	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1201 W WHITE ST #A		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1201 W WHITE ST #B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1111 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
602 N HAMLET ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
600 N HAMLET ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
510 N HAMLET ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1112 W WHITE ST		No	No	1966	1966	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1110 W WHITE ST		No	No	1940	1940	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1108 W WHITE ST		No	No	1921	1921	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1104 W WHITE ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1103 W WHITE ST		No	No	1940	1940	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1102 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1100 W WHITE ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1015 W WHITE ST		No	No	1952	1952	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1012 W WHITE ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1011 W WHITE ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1010 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1008 W WHITE ST #A		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1008 W WHITE ST #B		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1008 W WHITE ST #C		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1007 W WHITE ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1004 W WHITE ST		No	No	1952	1952	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1005 W WHITE ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1002 W WHITE ST		No	No	1901	1901	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
608 N VICKSBURG ST		No	No	2019	2019	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
606 N VICKSBURG ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
604 N VICKSBURG ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
603 N VICKSBURG ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1004 W CENTRAL ST		No	No	1980	1980	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
1008 W CENTRAL ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1005 W CENTRAL ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
1012 W CENTRAL ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1014 W CENTRAL ST		No	No	2021	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
401 N BENTLEY ST		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1100 W CENTRAL ST		No	No	1974	1974	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
1102 W CENTRAL ST		No	No	1967	1967	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1106 W CENTRAL ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1108 W CENTRAL ST		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1110 W CENTRAL ST		No	No	1996	1996	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1204 W CENTRAL ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1300 W CENTRAL ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1302 W CENTRAL ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1303 W CENTRAL ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1306 W CENTRAL ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1308 W CENTRAL ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1310 W CENTRAL ST		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1201 W MAIN ST		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1205 W MAIN ST #EHS		No	No	1907	1907	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1305 W MAIN ST		No	No	2024	1910	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1315 W MAIN ST		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1407 W MAIN ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
131 N 7TH ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
2300 W MAIN ST		No	No	1995	1995	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
102 N 5TH ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
109 N 5TH ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
111 N FIFTH ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
113 N 5TH ST		No	No	1930	1930	Visual Inspection	Unknown	G	G	NL	N	N/R	No		No		
201 N 5TH ST		No	No	2020	1940	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
2204 W MAIN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
106 N 4TH ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
108 N 4TH ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
112 N 4TH ST		No	No	1945	1945	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
204 N 4TH ST		No	No	1965	1965	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
301 N CARBON ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
205 N CARBON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1710 W FAUST ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1702 W FAUST ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
304 N PINE ST		No	No	1960	1960	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
2103 W MAIN ST		No	No	1956	1956	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2101 W MAIN ST		No	No	1919	1919	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
107 N RUSSELL ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
105 N RUSSELL ST #1-4		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
103 N RUSSELL ST #1-4		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
204 N RUSSELL ST #B		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
204 N RUSSELL ST #A		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
200 N RUSSELL ST		No	No	1964	1964	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
106 N RUSSELL ST		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
101 N RUSSELL ST #A-B		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
104 N RUSSELL ST		No	No	1925	1925	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
2007 W MAIN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2005 W MAIN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1905 W MAIN ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1907 W MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1903 W MAIN ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1901 W MAIN ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1825 W MAIN ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1823 W MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1712 W MAIN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1711 W MAIN ST		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1616 W MAIN ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
1608 W MAIN ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1602 W MAIN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1600 W MAIN ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	C	CLS	NL	N	N/R	No		No		
1508 W MAIN ST		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
106 N 5TH ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
510 S CARBON ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
508 S CARBON ST		No	No	1955	1955	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
506 S CARBON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
505 S CARBON ST "Empty Lot"		No	No	1937	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
504 S CARBON ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
503 S CARBON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
410 S CARBON ST		No	No	1945	1945	Survey Response	Unknown	C	G	NL	N	N/R	No		No		
408 S CARBON ST		No	No	1945	1945	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
404 S CARBON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
401 S CARBON ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
402 S CARBON ST		No	No	1921	1921	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
312 S CARBON ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
309 S CARBON ST		No	No	1980	1980	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
310 S CARBON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
102 S CARBON ST #5		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
102 S CARBON ST		No	No	1952	1952	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
903 S CARBON ST		No	No	1970	1970	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1001 S CARBON ST		No	No	1959	1959	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1005 S CARBON ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1006 S CARBON ST		No	No	1955	1955	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1007 S CARBON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1702 W HENDRICKSON ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1704 W HENDRICKSON ST		No	No	1970	1970	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1703 W HENDRICKSON ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
305 S 3RD ST		No	No	1943	1943	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
303 S 3RD ST		No	No	1943	1943	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1716 W MAIN ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
605 N VICKSBURG ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
806 N VICKSBURG ST		No	No	1976	1976	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
907 W WHITE ST "Empty Lot"		No	No	1910	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
302 S 2ND ST		No	No	1941	1941	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2100 W CHERRY ST		No	No	1940	1940	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
705 S CARBON ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
703 S CARBON ST		No	No	1965	1965	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
616 S CARBON ST		No	No	1951	1951	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
614 S CARBON ST		No	No	1951	1951	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
612 S CARBON ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
610 S CARBON ST		No	No	1952	1952	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
608 S CARBON ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
606 S CARBON ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
605 S CARBON ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
604 S CARBON ST		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
603 S CARBON ST #B		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
603 S CARBON ST #C		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
603 S CARBON ST #D		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
603 S CARBON ST #E		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
603 S CARBON ST #F		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1710 W WALNUT ST		No	No	1956	1956	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1711 W CHESTNUT ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1704 W CHESTNUT ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1609 W CHESTNUT ST		No	No	2024	2024	Construction Records	Copper	C	P	NL	N	N/R	No			No	
403 S FOZZARD ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1605 W CHERRY ST		No	No	1978	1978	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
107 S CARBON ST		No	No	1932	1932	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1609 W CHERRY ST		No	No	1940	2021	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
1607 W CHERRY ST		No	No	1940	1940	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
300 S RUSSELL ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
1406 W CHERRY ST		No	No	2021	1930	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
105 S RUSSEL ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1314 W CHERRY ST		No	No	2021	1926	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1110 W CHERRY ST		No	No	2021	2021	Construction Records	Copper	C	P	NL	N	N/R	No			No	
203 S BENTLEY ST		No	No	1885	1885	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
202 S BENTLEY ST		No	No	2019	2019	Construction Records	Copper	C	P	NL	N	N/R	No			No	
111 S BENTLEY ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
110 S BENTLEY ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
106 S BENTLEY ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
103 S BENTLEY ST		No	No	1952	1952	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
810 DOGWOOD LN		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
702 DOGWOOD LN		No	No	1965	1965	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
707 S RUSSELL ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
705 S RUSSELL ST		No	No	2021	1945	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
1705 W COPELAND ST		No	No	2023	1920	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
506 DOGWOOD LN		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
505 DOGWOOD LN		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
503 DOGWOOD LN		No	No	1950	1950	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1610 W COPELAND ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1606 W COPELAND ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
505 S DAYTON ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
506 S DAYTON ST		No	No	1962	1962	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
502 S DAYTON ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
503 S DAYTON ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1600 W WALNUT ST		No	No	1961	1961	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
512 S RUSSELL ST		No	No	1907	1907	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
601 S RUSSELL ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
505 S RUSSELL ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
501 N RUSSELL ST #A-C		No	No	1975	1975	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
508 S RUSSELL ST		No	No	1910	1910	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1414 W WALNUT ST		No	No	1940	1940	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
405 S RUSSELL ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
412 S RUSSELL ST		No	No	1895	1895	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
401 S RUSSELL ST		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
408 S RUSSELL ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1404 W MAPLEWOOD ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1413 W CHESTNUT ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1411 W CHESTNUT ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1409 W CHESTNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1406 W CHESTNUT ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1402 W CHESTNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1400 W CHESTNUT ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1302 W CHESTNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1301 W CHESTNUT ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1208 W CHESTNUT ST		No	No	1914	1914	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
312 S BENTLEY ST		No	No	1920	1920	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
311 S BENTLEY ST		No	No	1950	1950	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
308 S BENTLEY ST #A		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
308 S BENTLEY ST #B		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
308 S BENTLEY ST #C		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
308 S BENTLEY ST #D		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
308 S BENTLEY ST #E		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)									
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
	Unknown (U)	Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)														
	Unknown Not Lead (UNL)	Unknown (U)	Unknown (U)														
		Unknown Not Lead (UNL)	Unknown Not Lead (UNL)														
308 S BENTLEY ST #F		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
307 S BENTLEY ST		No	No	1923	1923	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1110 W CHESTNUT ST		No	No	1950	2024	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1104 W CHESTNUT ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1109 W CHESTNUT ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
602 S AIKMAN ST		No	No	1986	1986	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
600 S AIKMAN ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
601 S AIKMAN ST		No	No	1941	1941	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
507 S AIKMAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
506 S AIKMAN ST		No	No	1990	1990	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
505 S AIKMAN ST		No	No	2022	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1203 S AKIMAN ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1412 W WALNUT ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1411 W WALNUT ST		No	No	1904	1904	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1410 W WALNUT ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1409 W WALNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1405 W WALNUT ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1400 W WALNUT ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1403 W WALNUT ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1309 W WALNUT ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1308 W WALNUT ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
404 S EISENHOWER DR		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1403 W CHESTNUT ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
401 S EISENHOWER DR #A		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
401 S EISENHOWER DR #C		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
401 S EISENHOWER DR #B		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1204 W WALNUT ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1206 W WALNUT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1208 W WALNUT ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
410 S AIKMAN ST		No	No	1977	1977	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
411 S AIKMAN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 S AIKMAN ST		No	No	1960	1960	Visual Inspection	Unknown	G	CLS	NL	N	N/R	No		No		
408 S AIKMAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
406 S AIKMAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
403 S AIKMAN ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1209 W CHESTNUT ST		No	No	1910	1910	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
602 S CARBON ST		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1613 W CHESTNUT ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
603 S CARBON ST #A		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1617 W CHESTNUT ST		No	No	2022	1930	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
1309 W CHERRY ST		No	No	2023	2023	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1200 W CHERRY ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
703 S RUSSELL ST		No	No	1940	1940	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
510 S RUSSELL ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1311 RITCHEY DR		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1300 LAURA LN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1212 LAURA LN		No	No	1952	1952	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1425 JULIANNE DR #30		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1504 W HENDRICKSON ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1502 W HENDRICKSON ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1500 W HENDRICKSON ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
1501 W HENDRICKSON ST	LP1A048	No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
1409 W HENDRICKSON ST		No	No	1965	1965	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1407 W HENDRICKSON ST		No	No	1962	1962	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1405 W HENDRICKSON ST		No	No	1965	1965	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1403 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1125 S MIDWAY CT		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1123 MIDWAY CT "Empty Lot"		No	No	1942	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1113 W CHESTNUT ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
405 S BENTLEY ST		No	No	2021	1920	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
416 S BENTLEY ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
415 S BENTLEY ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
502 S BENTLEY ST		No	No	2014	2014	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
501 S BENTLEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
505 S BENTLEY ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
509 S BENTLEY ST		No	No	2024	1960	Maintenance Records	Copper	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples:	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified?	Examples:	Examples:	Examples:	Examples:	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples:	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities		Copper - No Lead Solder (C)					Copper - No Lead Solder (C)	Copper - No Lead Solder (C)	Lead (L)	Copper - No Lead Solder (C)							
		Copper - Lead Solder (CLS)					Copper - Lead Solder (CLS)	Copper - Lead Solder (CLS)	Galvanized Requiring Replacement (GRR)								
		Galvanized (G)					Galvanized (G)	Galvanized (G)	Unknown (U)								
		Lead (L)					Galvanized Requiring Replacement (GRR)	Galvanized Requiring Replacement (GRR)	Non-Lead (NL)								
		Cast/Ductile Iron or Transite (O)					Lead (L)	Lead (L)									
		Plastic - PVC, HDPE, PEX (P)					Cast/Ductile Iron or Transite (O)	Cast/Ductile Iron or Transite (O)									
		Unknown (U)					Plastic - PVC, HDPE, PEX (P)	Plastic - PVC, HDPE, PEX (P)									
	Yes (Y) or No (N)		Unknown (U)	Unknown (U)	Unknown (U)												
			Unknown Not Lead (UNL)	Unknown Not Lead (UNL)	Unknown Not Lead (UNL)										Leave blank if no Lead Service Line was replaced.		
510 S BENTLEY ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
600 S BENTLEY ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
701 S BENTLEY ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1201 W PRAIRIE ST		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
703 S BENTLEY ST "Empty Lot"		No	No	1940	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
704 S BENTLEY ST		No	No	1930	1930	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
705 S BENTLEY ST #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
705 S BENTLEY ST #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
805 S BENTLEY ST #A		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
805 S BENTLEY ST #B		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
805 S BENTLEY ST #C		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
807 S BENTLEY ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
809 S BENTLEY ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
808 S BENTLEY ST #A		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
808 S BENTLEY ST #B		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
811 S BENTLEY ST		No	No	1950	1950	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
810 S BENTLEY ST		No	No	1936	1936	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1201 W MALDEN ST		No	No	1960	1960	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
904 S BENTLEY ST		No	No	1943	1943	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
906 S BENTLEY ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1322 W HENDRICKSON ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
701 S AIKMAN ST		No	No	1938	1938	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
704 S AIKMAN ST		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
903 S RUSSELL ST		No	No	1960	1960	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
809 S RUSSELL ST		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2202 KINGSPONTE DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1801 WOLFF DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1609 EUGENE LN		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1621 EUGENE LN		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1107 W CONCORD ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1203 W CONCORD ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1105 S VICKSBURG ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1102 S VICKSBURG ST "Empty Lot"		No	No	1950	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1104 S VICKSBURG ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1004 S DUNCAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1101 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1006 S DUNCAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1113 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1214 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1213 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1010 S DUNCAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1014 S DUNCAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
1008 W HENDRICKSON ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
906 S DUNCAN ST		No	No	2021	1936	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
907 S DUNCAN ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
904 S DUNCAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
900 S DUNCAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1008 W MALDEN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1100 W MALDEN ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
807 S DUNCAN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
804 S DUNCAN ST		No	No	1963	1963	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
805 S DUNCAN ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
803 S DUNCAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
712 S DUNCAN ST #A-B		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
709 S DUNCAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
707 S DUNCAN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
706 S DUNCAN ST		No	No	1968	1968	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
703 S DUNCAN ST		No	No	2022	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
702 S DUNCAN ST		No	No	1950	1950	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
700 S DUNCAN ST		No	No	1925	1925	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1005 W PRARIE ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
605 S DUNCAN ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
604 S DUNCAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
601 S DUNCAN ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
600 S DUNCAN ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
507 S DUNCAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
506 S DUNCAN ST		No	No	1940	1940	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
504 S DUNCAN ST		No	No	1950	1950	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
505 S DUNCAN ST		No	No	1959	1959	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
1101 W WALNUT ST A		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1101 W WALNUT ST B		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
501 S DUNCAN ST		No	No	1959	1959	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
415 S DUNCAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
408 S DUNCAN ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
409 S DUNCAN ST		No	No	1910	1910	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
404 S DUNCAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
405 S DUNCAN ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
402 S DUNCAN ST		No	No	1900	1900	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
1009 W CHESTNUT ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1100 W CHESTNUT ST		No	No	1970	1970	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
311 S DUNCAN ST		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
306 S DUNCAN ST		No	No	1960	1960	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
305 S DUNCAN ST		No	No	1945	1945	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1008 W CHERRY ST		No	No	2014	2014	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
1009 W CHERRY ST		No	No	1978	1978	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1005 W CHERRY ST A		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1005 W CHERRY ST B		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1005 W CHERRY ST C		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No			No	
1005 W CHERRY ST D		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1005 W CHERRY ST E		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1005 W CHERRY ST #F		No	No	1988	1988	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1105 W MAIN ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1017 W MAIN ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1009 W MAIN ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1007 W MAIN ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
705 W COLLEGE ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
200 S COURT ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
213 S COURT ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
302 S COURT ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
807 W CHERRY ST "Empty Lot"		No	No	1955	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
919 W CHERRY ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
921 W CHERRY ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
931 W CHERRY ST		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
411 S BENTLEY ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
602 S BENTLEY ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
707 S BENTLEY ST		No	No	1965	1965	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
708 S BENTLEY ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
907 S BENTLEY ST		No	No	1938	1938	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
707 S AIKMAN ST		No	No	1975	1975	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
702 S EISENHOWER DR		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
604 S EISENHOWER DR		No	No	1925	1925	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
1510 W MALDEN ST		No	No	1958	1958	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
402 S BENTLEY ST		No	No	1900	1900	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No	No	
702 S BENTLEY ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
705 S BENTLEY ST #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
805 S AIKMAN ST		No	No	1948	1948	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
804 S EISENHOWER DR		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
404 S BENTLEY ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
1105 W PRAIRIE ST		No	No	Unknown	Unknown	Survey Response	Unknown	P	P	NL	N	N/R	No		No	No	
803 S BENTLEY ST		No	No	2021	1930	Maintenance Records	Copper	C	P	NL	N	N/R	No		No	No	
802 S BENTLEY ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
901 S BENTLEY ST		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
806 EISENHOWER DR		No	No	1946	1946	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
803 S EISENHOWER DR		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No	No	
900 S AIKMAN ST #B		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
1305 W COPELAND ST #A		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No	No	
1303 W PRAIRIE ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
602 S EISENHOWER DR		No	No	1950	1950	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
907 S RUSSELL ST		No	No	1920	1920	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No	No	
1407 W MALDEN ST		No	No	1970	1970	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
1106 S VICKSBURG ST		No	No	1940	1940	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
1008 S DUNCAN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No	No	
1216 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No	No	
1011 MIDWAY CT "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
309 S DUNCAN ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
908 W CHERRY ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1215 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
905 S DUNCAN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
603 S DUNCAN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
901 W CHERRY ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
905 W CHERRY ST		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
908 W MALDEN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
509 S VICKSBURG ST		No	No	1944	1944	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
712 S VICKSBURG ST		No	No	2021	1925	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
508 S VICKSBURG ST		No	No	1915	1915	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
305 S VICKSBURG ST		No	No	2019	1930	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
506 S HILL ST		No	No	1920	1920	Visual Inspection	Unknown	P	G	NL	N	N/R	No		No		
812 W CHESTNUT ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
808 W PRAIRIE ST		No	No	2014	2014	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1005 W CHESTNUT ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
402 S VICKSBURG ST		No	No	1910	1910	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
424 S COURT ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
418 S COURT ST		No	No	2019	1930	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
402 S COURT ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
418 S VICKSBURG ST		No	No	2022	1920	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
401 S COURT ST		No	No	1924	1924	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
912 W CHESTNUT ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
909 W CHESTNUT ST		No	No	1920	1920	Maintenance Records	Copper	C	CLS	NL	N	N/R	No			No	
313 S COURT ST		No	No	1940	1940	Survey Response	Unknown	C	G	NL	N	N/R	No			No	
507 S SPILLMAN ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
511 S HILL ST		No	No	1924	1924	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
802 W CHESTNUT ST		No	No	1915	1915	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
509 S HILL ST		No	No	1924	1924	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
804 W CHESTNUT ST		No	No	1936	1936	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
505 S HILL ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
502 S HILL ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
501 S HILL ST		No	No	1930	1930	Maintenance Records	Copper	C	CLS	NL	N	N/R	No			No	
413 S HILL ST		No	No	1902	1902	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
805 W CHESTNUT ST #A		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
411 S HILL ST		No	No	Unknown	Unknown	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
805 W CHESTNUT ST #B		No	No	2015	2015	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
410 S HILL ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
405 S HILL ST		No	No	1910	1910	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
408 S HILL ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
807 W CHESTNUT ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
809 W CHESTNUT ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
904 W CHESTNUT ST		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
808 W CHESTNUT ST		No	No	1920	1920	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
901 W CHESTNUT ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
815 W CHESTNUT ST		No	No	1950	1950	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
814 W CHESTNUT ST		No	No	1980	1980	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
902 W CHESTNUT ST		No	No	1905	1905	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
410 S COURT ST		No	No	1920	1920	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
504 S HILL ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
816 W CHESTNUT ST		No	No	1905	1905	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
505 S COURT ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No		No		
812 W MAPLEWOOD ST #A		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
812 W MAPLEWOOD ST #B		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
502 S COURT ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
810 W PRAIRIE ST #A		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
810 W PRAIRIE ST #B		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
810 W PRAIRIE ST #C		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
811 W PRAIRIE ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
817 W PRAIRIE ST		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
901 W PRAIRIE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
903 W PRAIRIE ST		No	No	1942	1942	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
905 W PRAIRIE ST		No	No	1939	1939	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
907 W PRAIRIE ST		No	No	2021	1920	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
500 S COURT ST		No	No	1882	1882	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
501 S COURT ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area? Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Service Line Newly Identified Since Last Submitted Inventory Yes (Y) or No (N)	Year PWS-Owned Service Line was Installed What year was the PWS-Owned service line installed, if known?	Year Customer Side Service Line was Installed What year was the customer side service line installed, if known?	Source of Information Used for Service Line Identification Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead? If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Date Customer Notified of Lead Service Line Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Was a lead service line previously replaced at this location? Yes (Y) or No (N)	Date Lead Service Line Replaced If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Material of Service Line Replacement	Has the customer refused access to the property? Yes (Y) or No (N)	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property) IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
							Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)					Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.		
813 W PRAIRIE ST #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
813 W PRAIRIE ST #B		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
813 W PRAIRIE ST #C		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
813 W PRAIRIE ST #D		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
813 W PRAIRIE ST #E		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
814 W PRAIRIE ST #B		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
814 W PRAIRIE ST #A		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
3300 W LAKEVIEW RD #SPRINK		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
517 S COURT ST		No	No	2021	1890	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
905 W MAPLEWOOD ST		No	No	1880	1880	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
606 S COURT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
610 S COURT ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
603 S COURT ST		No	No	1978	1978	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
614 S COURT ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
703 S COURT ST "Empty Lot"		No	No	1951	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
805 S COURT ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
901 S COURT ST		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
908 S COURT ST		No	No	1979	1979	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
812 W MAPLEWOOD ST #C		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
812 W MAPLEWOOD ST #D		No	No	1979	1979	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
804 W MAPLEWOOD ST		No	No	1920	1920	Visual Inspection	Unknown	G	P	NL	N	N/R	No		No		
820 W MAPLEWOOD ST		No	No	2023	2023	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
809 W MAPLEWOOD ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
815 W MAPLEWOOD ST		No	No	2021	1920	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
819 W MAPLEWOOD ST		No	No	1910	1910	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
822 W MAPLEWOOD ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
821 W MAPLEWOOD ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
810 W MALDEN ST		No	No	2021	1940	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
814 W MALDEN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
811 W MALDEN ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
815 W MALDEN ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
817 W MALDEN ST "Empty Lot"		No	No	1950	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
818 W MALDEN ST		No	No	1953	1953	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
819 W MALDEN ST		No	No	1935	1935	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
823 W MALDEN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
901 W MALDEN ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
902 W MALDEN ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
907 W MALDEN ST		No	No	1950	1950	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
909 W MALDEN ST		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
906 W MALDEN ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
903 W HENDRICKSON ST "Empty Lot"		No	No	1950	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
813 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
820 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
703 S HILL ST		No	No	1987	1987	Survey Response	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1407 S COURT ST "Empty Lot"		No	No	1934	Unknown	Visual Inspection	Unknown	G	UNL	NL	N	N/R	No		No		
1207 S COURT ST		No	No	2021	1920	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
1203 S COURT ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
201 W BOYTON ST		No	No	2021	1925	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
403 W SIMMONS ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
635 LAKE HARBOR DR		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1000 S MONROE ST		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1306 S MONROE ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1204 S MONROE ST		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
902 S MONROE ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
423 S COURT ST		No	No	1983	1983	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
709 S HOLLAND ST		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
706 S HOLLAND ST		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
704 S MONROE ST		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
305 W CLINE ST		No	No	2019	2015	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
407 W CLINE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
304 W CLINE ST		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
315 S GRANITE ST		No	No	2019	1915	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
506 S VAN BUREN ST		No	No	2020	1930	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
409 S VAN BUREN ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
307 S MONROE ST		No	No	1900	1900	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
305 S MONROE ST "Empty Lot"		No	No	1960	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
210 S HOLLAND ST		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
208 S HOLLAND ST		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
301 S VAN BUREN ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
206 S VAN BUREN ST		No	No	1900	1900	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
505 W COLLEGE ST		No	No	1972	1972	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
206 S HOLLAND ST		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
601 W MAIN ST		No	No	1900	1900	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
521 W MAIN ST #1		No	Yes	2024	1910	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No	
521 W MAIN ST #2		No	Yes	2024	1910	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No	
700 S MARKET ST		No	No	1940	1940	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
606 S MARKET ST		No	No	1900	1900	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
524 S MARKET ST		No	No	2017	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
307 W BOYTON ST "Empty Lot"		No	No	1980	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
508 W DAVIS ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
403 W CLINE ST		No	No	1960	1960	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
208 S LIBERTY ST		No	No	2023	1980	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
202 S VAN BUREN ST		No	No	1915	1915	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
202 S LIBERTY ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
600 S MARKET ST		No	No	2017	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
307 W SIMMONS ST		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
1303 S MONROE ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
506 S MARKET ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
302 S VAN BUREN ST		No	No	1890	1890	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
205 S LIBERTY ST		No	No	1915	1915	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
402 W COLLEGE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
201 S MONROE ST #A		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
201 S MONROE ST B		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
303 W COLLEGE ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
602 TOWER SQ		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	10/29/2023	Yes	10/30/2023	P	No	
111 W MAIN ST		No	Yes	2023	1950	Maintenance Records	Plastic	P	CLS	NL	N	10/29/2023	Yes	10/30/2023	P	No	
201 W MAIN ST #A-D		No	Yes	2023	1950	Maintenance Records	Plastic	P	CLS	NL	N	10/30/2023	Yes	10/30/2023	P	No	
205 W COLLEGE ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
104 S VAN BUREN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
808 S MARKET ST		No	No	1950	1950	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
1834 N COURT ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
903 SCOTSBORO RD "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1010 W DEYOUNG ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
1000 W DEYOUNG ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1008 W DEYOUNG ST		No	No	1984	1984	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1300 SCOTSBORO RD #A		No	No	2024	1970	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1300 SCOTSBORO RD #B		No	No	2024	1970	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
1310 SCOTSBORO RD		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1209 MORGAN AVE		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1212 MORGAN AVE		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Unknown (U) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1505 N RUSSELL ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No		
1905 PRINCETON AVE		No	No	1977	1977	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
CARBON/MORGAN ROUNDAABOUT #SPRINK		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1707 MORGAN AVE #SPRINK		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
1512 MAUREEN DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1630 N PEABODY ST		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1508 MAUREEN DR		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1522 MAUREEN DR		No	No	1979	1979	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1808 BITTLE PLACE		No	No	1980	1980	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No		
1506 CHAMPIONS DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
3117 CIVIC CIRCLE BLVD		No	No	Unknown	Unknown	Survey Response	Unknown	P	P	NL	N	N/R	No			No		
2703 SEVENTEENTH ST #B		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2703 SEVENTEENTH ST #C		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2703 SEVENTEENTH ST #D		No	No	2019	2019	Maintenance Records	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1303 N MARATHON DR		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2406 WILLIAMSON CO PKWY #5-F		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
2902 W DEYOUNG ST #SPRIN		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
2902 W DEYOUNG ST		No	No	2013	2013	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
2741 KOKOPELLI DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1535 SIOUX DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
1800 N SKYLINE DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
3402 HEARTLAND ST #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
2401 W MAIN ST		Yes	No	1940	1940	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
2703 WALTON WAY		No	No	2019	2019	Construction Records	Copper	C	P	NL	N	N/R	No			No	
3200 W COMMERCIAL RD "Empty Lot"		No	No	1987	Unknown	Visual Inspection	Unknown/Not Lead	P	UNL	NL	N	N/R	No			No	
10033 OLD BAINBRIDGE TRAIL		No	No	2021	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9537 PENTECOST RD		No	No	1970	1970	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9390 PENTECOST RD		No	No	1973	1973	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
9342 PENTECOST RD		No	No	1963	1963	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
9268 OLD ROUTE 13		No	No	1966	1966	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
9092 OLD ROUTE 13		No	No	2021	1959	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9058 OLD ROUTE 13		No	No	2021	1965	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9024 OLD ROUTE 13		No	No	1965	1965	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
9000 OLD ROUTE 13		No	No	1961	1961	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
8804 OLD ROUTE 13		No	No	1970	1970	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
8730 OLD ROUTE 13		No	No	1947	1947	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
8602 OLD ROUTE 13		No	No	1954	1954	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
8576 OLD ROUTE 13		No	No	1979	1979	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
9375 SITTER LN		No	No	2020	1987	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9395 SITTER LN		No	No	2005	2005	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
8504 OLD ROUTE 13		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
8494 OLD ROUTE 13		No	No	1940	1940	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
9453 STANLEY LN		No	No	1965	1965	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
9375 STANLEY LN		No	No	1970	1970	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
8386 OLD ROUTE 13		No	No	1950	1950	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
9448 MULLANS LN		No	No	2020	1930	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9433 JOHNS LN		No	No	1994	1994	Survey Response	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
8208 OLD ROUTE 13		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9539 ROUTE 148		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
9669 ROUTE 148		No	No	1945	1945	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
9731 ROUTE 148		No	No	1959	1959	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
7580 GUNNERS LN		No	No	1940	1940	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
10202 BRIGGS RD		No	No	1966	1966	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
10097 BRIGGS RD		No	No	1955	1955	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
10077 BRIGGS RD		No	No	1961	1961	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
7606 OLD ROUTE 13		No	No	1960	1960	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
7626 OLD ROUTE 13		No	No	1935	1935	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
7744 OLD ROUTE 13		No	No	1950	1950	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
7682 OLD ROUTE 13		No	No	1935	1935	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
2802 W DEYOUNG ST		No	No	2020	2020	Construction Records	Copper	C	P	NL	N	N/R	No			No	
302 E CLARK ST #C		No	No	2019	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
900 S COURT ST #B		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
909 S MADISON ST		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1010 E REEVES ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
617 E MERIDIAN ST		No	No	1952	1952	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
204 E ALLEN AVE		No	Yes	2024	2024	Maintenance Records	Copper	C	P	NL	Y	9/4/2024	Yes	9/25/2024	C	No	
9340 JOHNS LN		No	No	1960	1960	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
100 E WARDER ST A B		No	No	2020	1910	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9335 SITTER LN		No	No	2020	1996	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
9397 SITTER LN		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
407 S MADISON ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1711 CASTLEBERRY DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1310 E MAIN ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1312 E MAIN ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1314 E MAIN ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1316 E MAIN ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2002 W MAPLE ST		No	No	1960	1960	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
2006 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
9569 ROUTE 148		No	No	1971	1971	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
7784 OLD ROUTE 13		No	No	1945	1945	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
2903 S MARKET ST #A		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2903 S MARKET ST #B		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2909 S MARKET ST #B		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1303 N OTIS ST #SPRINK		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1303 N OTIS ST		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
403 N GARFIELD ST		No	No	2020	1969	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
405 N GARFIELD ST		No	No	1969	1969	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
2208 OLD CREAL SPRINGS RD		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
508 E MARION ST #A		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
508 E MARION ST #B		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1413 N STATE ST		No	No	2020	1940	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
300 E CLARK ST		No	No	2020	1970	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
1806 HOLMES DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
208 E CHARLES ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1205 N OTIS ST #A		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1205 N OTIS ST #B		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1205 N OTIS ST #C		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2008 W MAIN ST A		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2008 W MAIN ST B		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
909 N MADISON ST		No	No	1940	1940	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
913 N MADISON ST		No	No	1948	1948	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1503 CHAMPIONS DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
412 S COURT ST		No	No	1958	1958	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1408 PERSIMMON DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1505 CHAMPIONS DR		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2400 BLUE HERON DR		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1306 N MARKET ST		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1209 N COURTNEY ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1606 WINDY HILL DR		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1106 S MECHANIC ST		No	No	1920	1920	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
920 W UNION ST #A-B		No	No	1935	1935	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
704 N GARFIELD ST		No	No	2019	2019	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
405 E DENNISON ST		No	No	1927	1927	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1205 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1303 DEW DROP DR		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
506 E BROWNING ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
9336 OLD ROUTE 13		No	No	1969	1969	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
812 W MALDEN ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
208 E GOODALL ST		No	No	1910	1910	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
540 E THORN ST		No	No	1940	1940	Maintenance Records	Unknown	G	P	NL	N	N/R	No			No	
532 E THORN ST		No	No	1935	1935	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
405 E ALLEN AVE		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
904 W PRAIRIE ST		No	No	1942	1942	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
1405 S COURT ST		No	No	1925	1925	Maintenance Records	Unknown	G	G	NL	N	N/R	No			No	
1301 S HOLLAND ST		No	No	1970	1970	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
801 W DEYOUNG ST #A-B		No	No	1980	1980	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
1703 N STATE ST		No	No	1880	1880	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
900 S COURT ST #A		No	No	2019	2019	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2909 S MARKET ST #A		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1902 N SKYLINE DR		No	No	1950	1950	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
2408 N SKYLINE DR		No	No	2011	2011	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2611 BLUE HERON DR #SPRINK		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
205 E THORN ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
307 S MARKET ST		No	No	1904	1904	Maintenance Records	Unknown	P	G	NL	N	N/R	No		No		
2795 S MARKET ST #A		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2891 S MARKET ST #A		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1007 S MECHANIC ST		No	No	1910	1910	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
807 S BUCHANAN ST		No	No	1930	1930	Survey Response	Unknown	P	P	NL	N	N/R	No		No		
523 S MARKET ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
606 S MADISON ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
604 S MADISON ST		No	No	1930	1930	Survey Response	Unknown	C	P	NL	N	N/R	No		No		
211 W GOODALL ST		No	No	1910	1910	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
705 N HIGHLAND ST		No	No	2021	1910	Maintenance Records	Copper	C	G	NL	N	N/R	No		No		
1110 DAYBREAK DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1114 GLORY LN		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1612 N GARFIELD ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1610 N GARFIELD ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1608 N GARFIELD ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1411 N STATE ST		No	No	1920	1920	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
1304 N STATE ST		No	No	1911	1911	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1300 N STATE ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
301 E THORN ST		No	No	1930	1930	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
300 E MAIN ST		No	No	1985	1985	Maintenance Records	Unknown	P	CLS	NL	N	N/R	No			No	
1007 S MARKET ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
2795 S MARKET ST #B		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2891 S MARKET ST #B		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
707 N HIGHLAND ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
2001 DEW DROP DR		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
605 E CARTER ST		No	No	1970	1970	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
604 E CARTER ST		No	No	1920	1920	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
1014 N STATE ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1012 N STATE ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1206 N STATE ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
105 E FINUCANE ST		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1301 DEW DROP DR		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1102 N MCLAREN ST		No	No	1969	1969	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1614 EUGENE LN		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1209 W CHERRY ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1315 W CHERRY ST		No	No	1938	1938	Survey Response	Unknown	C	G	NL	N	N/R	No			No	
909 N STATE ST		No	No	1950	1950	Survey Response	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
101 W DEYOUNG ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
900 S MADISON ST		No	No	1940	1940	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
1306 LAURA LN		No	No	2021	2003	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
2810 JOSEPH CANNON WAY		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
906 S VIRGINIA AVE		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
500 ALLEN AVE		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
415 S CALUMET ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
713 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
1916 E PICKETT LN #A		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1916 E PICKETT LN #B		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1916 E PICKETT LN #C		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1916 E PICKETT LN #D		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1916 E PICKETT LN #E		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1203 DEW DROP DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1207 N VAN BUREN ST		No	No	1950	1950	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
800 S VIRGINIA AVE		No	No	1926	1926	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
603 PLEASANT CT		No	No	1923	1923	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
404 E MARION ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
401 E MARION ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
306 E MARION ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
107 S BUCHANAN ST		No	No	1930	1930	Maintenance Records	Unknown	G	G	NL	N	N/R	No			No	
303 E MAIN ST		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2720 W MAIN ST D		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2720 W MAIN ST E		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2720 W MAIN ST F		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2720 W MAIN ST G		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2720 W MAIN ST #H		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2720 W MAIN ST I		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
9452 JOHNS LN		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
9384 JOHNS LN		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
612 S VIRGINIA AVE		No	No	1932	1932	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1111 GLORY LN		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1802 DEW DROP DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
614 S CALUMET ST		No	No	1936	1936	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
608 PLEASANT CT		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
600 PLEASANT CT		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
611 S VIRGINIA AVE		No	No	1945	1945	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
709 S VIRGINIA AVE		No	No	1920	1920	Survey Response	Unknown	P	CLS	NL	N	N/R	No		No		
402 S MADISON ST		No	No	1920	1920	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
307 E MAIN ST	LP1C012	No	No	1900	1900	Visual Inspection	Lead	P	CLS	NL	N	N/R	No		No		
1910 W COOLIDGE AVE		No	No	1997	1997	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
3781 S MARKET ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
708 CIRCLE DR		No	No	1925	1925	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1517 CHAMPIONS DR		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
301 N MARKET ST SPRINK		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1513 N STATE ST		No	No	1852	1852	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1708 W MAIN ST #DOG		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1708 W MAIN ST		No	No	2004	2004	Survey Response	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
1106 N GRANITE ST		No	No	1960	1960	Visual Inspection	Unknown	P	G	NL	N	N/R	No			No	
506 E BOULEVARD		No	No	1930	1930	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
928 W MAIN ST		No	No	2021	2021	Construction Records	Copper	C	P	NL	N	N/R	No			No	
400 S CALUMET ST		No	No	1930	1930	Survey Response	Unknown	P	CLS	NL	N	N/R	No			No	
904 S VIRGINIA AVE		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
501 S VIRGINIA AVE		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
303 S VAN BUREN ST		No	No	2022	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
503 N MADISON ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
305 S BENTLEY ST		No	No	1925	1925	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1014 W WHITE ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1904 DEW DROP DR		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1930 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1932 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1928 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1920 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1918 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
408 E DEYOUNG ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
310 E DEYOUNG ST		No	No	2020	1960	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
308 E DEYOUNG ST		No	No	1953	1953	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
720 E MAIN ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
708 E UNION ST		No	No	1945	1945	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
108 N LILLIAN ST	LP1C026	No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
915 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
304 N MCLAREN ST		No	No	2022	1900	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
306 N MCLAREN ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No		No		
308 N MCLAREN ST B		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
108 S CHAMP ST		No	No	1920	1920	Maintenance Records	Unknown	C	P	NL	N	N/R	No		No		
1006 S MECHANIC ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
113 S FIRST ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
2004 W MAPLE ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1013 W WHITE ST		No	No	1910	1910	Maintenance Records	Unknown	C	G	NL	N	N/R	No		No		
1009 W WHITE ST		No	No	2022	2023	Maintenance Records	Copper	C	P	NL	N	N/R	No		No		
810 N VAN BUREN ST		No	No	1930	1930	Survey Response	Unknown	C	CLS	NL	N	N/R	No		No		
1505 N GLENDALE ST B		No	No	1974	1974	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1407 N GLENDALE ST #B		No	No	1912	1912	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1407 N GLENDALE ST #A		No	No	1912	1912	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		
1407 N GLENDALE ST #C		No	No	1912	1912	Maintenance Records	Unknown	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1407 N GLENDALE ST #D		No	No	1912	1912	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
208 S BURR ST		No	No	1930	1930	Survey Response	Unknown	P	P	NL	N	N/R	No			No	
3306 W LAKEVIEW RD		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
4650 MEADOWLAND PKWY		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
713 N MADISON ST B		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
713 N MADISON ST C		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
713 N MADISON ST D		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
2604 OLD CREAL SPRINGS RD		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1808 RAMSEY DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
713 N MADISON ST A		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
710 E UNION ST		No	No	1900	1900	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
200 TOWER SQUARE PLAZA		No	Yes	2023	2011	Maintenance Records	Plastic	P	C	NL	N	11/15/2023	Yes	11/15/2023	P	No	
200 N 5TH ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
3304 W COMMERCIAL RD		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1306 E BOULEVARD ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
801 N TAFT ST #B		No	No	2017	2017	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2716 Carnoustie Dr #SPRINK		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
807 DOGWOOD LN		No	No	1967	1967	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
600 N LOGAN ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1308 LAURA LN "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1603 N BRUCE ST		No	No	1970	1970	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1520 BROEKING RD		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
412 S DUNCAN ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1302 W LEE AVE		No	No	2024	1930	Maintenance Records	Copper	C	G	NL	N	N/R	No			No	
204 N GARFIELD ST #A		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1107 W BOULEVARD ST		No	No	1989	1989	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1909 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1907 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1201 E MAIN ST		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
701 E DEYOUNG ST		No	No	1975	1975	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
103 E GOODALL ST A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
103 E GOODALL ST B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
103 E GOODALL ST C		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
103 E GOODALL ST D		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
103 E GOODALL ST E		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
103 E GOODALL ST F		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
705 N MARKET ST #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
705 N MARKET ST #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
705 N MARKET ST #D		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
705 N MARKET ST #E		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
705 N MARKET ST #F		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
703 N MARKET ST #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
703 N MARKET ST #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
703 N MARKET ST #C		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
703 N MARKET ST #D		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
703 N MARKET ST #E		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
100 CAMPBELL ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
102 CAMPBELL ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
104 CAMPBELL ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
106 CAMPBELL ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
108 CAMPBELL ST		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
204 TOWER SQ #A		No	Yes	2023	2022	Maintenance Records	Plastic	P	P	NL	N	11/15/2023	Yes	11/15/2023	P	No	
204 TOWER SQ PL #B		No	Yes	2023	2022	Maintenance Records	Plastic	P	P	NL	N	11/15/2023	Yes	11/15/2023	P	No	
204 TOWER SQ PL #C		No	Yes	2022	2022	Maintenance Records	Plastic	P	P	NL	N	11/15/2023	Yes	11/15/2023	P	No	
204 TOWER SQ PL #D		No	Yes	2023	2022	Maintenance Records	Plastic	P	P	NL	N	11/15/2023	Yes	11/15/2023	P	No	
204 TOWER SQ PL #E		No	Yes	2023	2022	Maintenance Records	Plastic	P	P	NL	N	11/15/2023	Yes	11/15/2023	P	No	
TOWER SQUARE PLAZA #SPRINK		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
407 E JACKSON ST		No	No	2022	2022	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
403 E BOULEVARD ST		No	No	1915	1915	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	
803 E Browning St		No	No	1940	1940	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
900 E BROWNING ST		No	No	2022	2022	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
902 E BOULEVARD ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
705 N MARKET ST #C		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
806 E BOULEVARD St		No	No	2022	1920	Maintenance Records	Plastic	P	CLS	NL	N	N/R	No			No	
1401 N COURTNEY ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1406 N GLENDALE ST		No	No	1940	1940	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1310 N GLENDALE ST		No	No	1920	1920	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1308 N GLENDALE ST		No	No	1940	1940	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1403 N STATE ST		No	No	1950	1950	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
716 N Harper St		No	No	1910	1910	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
717 N Harper St		No	No	2020	2020	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
800 N GARFIELD ST		No	No	2022	1925	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1001 N Garfield St		No	No	1968	1968	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
600 E Reeves St		No	No	1900	1900	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
700 N Fair St		No	No	2022	1910	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
604 N McLaren St		No	No	1930	1930	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
605 S Bentley St		No	No	1940	1940	Maintenance Records	Unknown	C	G	NL	N	N/R	No			No	
2707 S MARKET ST #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2707 S MARKET ST #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2709 S MARKET ST #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2709 S MARKET ST #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2725 S Market St A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2725 S Market St B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2755 S MARKET ST #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2755 S MARKET ST #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1110 Horizon Dr		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1109 Horizon Dr		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1112 DAYBREAK DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1112 DAYBREAK DR #SPRIN		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1400 RIDGEVIEW DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1203 WHITWORTH DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
221 E CARTER ST		No	No	1900	1900	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1617 N PEABODY ST		No	No	2023	1980	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1700 N RUSSELL ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1402 MORGAN AVE		No	No	1935	1935	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1003 E MCKINLEY ST #A		No	No	2022	1979	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
400 TOWER SQUARE PLAZA		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	11/7/2023	Yes	11/8/2023	P	No	
1079 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1081 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1077 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1075 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1073 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1071 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1063 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1061 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1051 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1053 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1035 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1037 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1031 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1033 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1027 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1029 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1025 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1023 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
ROLLING ACRES DR LAUNDRY ROOM		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1204 W HENDRICKSON ST #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1204 W HENDRICKSON ST #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1106 W HENDRICKSON ST A		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1106 W HENDRICKSON ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1106 W HENDRICKSON ST C		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1106 W HENDRICKSON ST D		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3213 MARK TWAIN AVE #A		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1912 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1910 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1914 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1916 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1911 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1913 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1915 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1917 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1924 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1919 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1921 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1923 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1925 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1926 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1927 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1929 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1931 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1933 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1934 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1936 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1905 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1903 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1908 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1906 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1904 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1902 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1922 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
905 S COURT ST		No	No	1958	1958	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1404 W PRAIRIE ST #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
118 E UNION ST		No	No	1960	1960	Visual Inspection	Lead	C	CLS	NL	N	N/R	No			No	
950 PENTECOST RD		No	No	2022	2022	Construction Records	Copper	C	P	NL	N	N/R	No			No	
1011 N GARFIELD ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
2801 CIVIC CIRCLE BLVD #6		No	No	2009	2009	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1403 W MALDEN ST		No	No	1960	1960	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1500 CARDINAL DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1306 E MAIN ST		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1301 N VAN BUREN ST "Empty Lot"		No	No	2022	Unknown	Maintenance Records	Copper	C	UNL	NL	N	N/R	No			No	
3119 CIVIC CIRCLE BLVD #A		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3119 CIVIC CIRCLE BLVD #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1404 W PRAIRIE ST #C		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1404 W PRAIRIE ST #B		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1702 CAESER LN		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1415 N Courtney st		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1413 AUGUSTA DR #SPRIN		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1413 AUGUSTA DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
3002 W DEYOUNG ST		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
114 E DEYOUNG ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
112 E DEYOUNG ST		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No	
1401 N Van Buren St		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1315 N VAN BUREN ST		No	No	1938	1938	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
3401 S MARKET ST #SPRINK		No	No	2020	2020	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1014 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1012 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1010 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1008 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1006 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1004 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1002 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1016 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1018 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1020 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1022 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1024 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1026 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1028 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1030 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1032 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1034 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1036 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1038 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1040 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1042 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1044 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1046 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1048 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1050 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1052 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1054 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1056 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1058 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1060 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1062 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1064 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1066 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1068 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1070 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1072 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
1074 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2201 WESTMINSTER DR #SPRIN		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1000 ROLLING ACRES DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1303 Camden Ct		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2605 VERNELL RD		No	No	1990	1990	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
412 N MARKET ST B		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3333 W DE YOUNG ST #SPRINK		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2800 W DEYOUNG ST		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2800 W DEYOUNG ST #SPRIN		No	No	2021	2021	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1900 THE HILL AVE		No	No	Unknown	Unknown	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
703 E CARTER ST		No	No	1925	1925	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1008 N OTIS ST #B		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
608 N MONROE ST #A		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No	
608 N MONROE ST #B		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
608 N MONROE ST #C		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1306 N STATE ST		No	No	1900	1900	Survey Response	Unknown	C	CLS	NL	N	N/R	No			No	
1205 N MARKET ST "Empty Lot"		No	No	1920	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
1127 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1111 N. CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
1109 N CARBON ST		No	No	1986	1986	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
205 E MAIN ST		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	11/2/2023	Yes	11/2/2023	P	No	
1207 TOWER SQUARE PLAZA		No	No	2024	2018	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
306 E CARTER ST		No	No	1940	1940	Maintenance Records	Unknown	G	G	NL	N	N/R	No			No	
1006 N HIGHLAND ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
200 W MAIN ST		No	Yes	2023	1935	Maintenance Records	Plastic	P	CLS	NL	N	10/30/2023	Yes	10/30/2023	P	No	
1506 W MAIN ST		No	No	2024	1950	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
712 N MARKET ST		No	No	1915	1915	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
401 N MADISON ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
201 E CALVERT ST A		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
201 E CALVERT ST B		No	No	2012	2012	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
502 W JACKSON ST		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No	
700 N COURT ST		No	No	2009	2009	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1007 MIDWAY CT "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1005 MIDWAY CT "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1302 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1212 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1200 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1202 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1315 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
302 E JACKSON ST		No	No	1930	1930	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
104 PRINT AVE		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
108 N VAN BUREN ST		No	No	1935	1935	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
110 N PRINT AVE		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1319 W HENDRICKSON ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1311 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1303 W HENDRICKSON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1110 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
1108 W CONCORD ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
403 W MAIN ST		No	Yes	2024	1935	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No	
1202 W COPELAND ST		No	No	1900	1900	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
603 S BUCHANAN ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1012 S Vicksburg st		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1217 W Hendrickson St "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
500 TOWER SQUARE PLZ		No	Yes	2023	1920	Maintenance Records	Plastic	P	CLS	NL	N	11/7/2023	Yes	11/8/2023	P	No	
605 TOWER SQUARE PLAZA		No	Yes	2023	1910	Maintenance Records	Plastic	P	P	NL	N	11/14/2023	Yes	11/15/2023	P	No	
600 TOWER SQUARE PLAZA		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	10/29/2023	Yes	10/30/2023	P	No	
1102 S MONROE ST #PARK		No	No	1986	1986	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
201 S HOLLAND ST		No	No	2023	2023	Construction Records	Copper	C	P	NL	N	N/R	No			No	
200 S MONROE ST		No	No	2023	2023	Construction Records	Copper	C	P	NL	N	N/R	No			No	
1804 RAMSEY DR		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2402 N SKYLINE DR		No	No	2014	2014	Construction Records	Plastic	P	C	NL	N	N/R	No			No	
207 W COLLEGE ST		No	No	2023	1926	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
702 N VAN BUREN ST		No	No	1945	1945	Maintenance Records	Unknown	C	CLS	NL	N	N/R	No			No	
407 S DUNCAN ST		No	No	1913	1913	Maintenance Records	Unknown	P	CLS	NL	N	N/R	No			No	
816 W PRAIRIE ST		No	No	1905	1905	Maintenance Records	Unknown	P	G	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)	
																		Examples:
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Lead (L) Galvanized Requiring Replacement (GRR) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Galvanized Requiring Replacement (GRR) Unknown (U) Non-Lead (NL) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
606 E JEFFERSON ST		No	No	1971	1971	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		
1521 MAUREEN DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1003 N GRANITE ST		No	No	1982	1982	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
308 W STOCKTON ST		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No			No		
902 S MECHANIC ST A		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
902 S MECHANIC ST B		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
902 S MECHANIC ST C		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
902 S MECHANIC ST D		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No		
919 E COLLEGE ST		No	No	2000	2000	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No		
1908 NORMAN RD		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No		
1101 W GOODALL ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
211 N MARKET ST		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	C	NL	N	N/R	No			No		
400 W JACKSON ST		No	No	1985	1985	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
306 W MAIN ST		No	Yes	2024	1900	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No		
300 W MAIN ST		No	Yes	2024	1935	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No		
307 N BENTLEY ST		No	No	2024	1925	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No		
906 S AIKMAN ST		No	No	1970	1970	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No		
7062 OLD RT 13		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No		
1102 S MECHANIC ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
1100 TOWER SQUARE PL		No	Yes	2023	Unknown	Maintenance Records	Plastic	P	P	NL	N	11/5/2023	Yes	11/6/2023	P	No		
1109 W WHITE ST		No	No	1920	1920	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No			No		
406 W CLINE ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
210 W BOULEVARD ST		No	No	1900	1900	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
1207 WAYNE DR		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1818 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1820 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1900 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1816 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1414 LIONCOURT DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1412 LIONHEART DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1408 LIONHEART DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1802 RAMSEY DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
408 S VAN BUREN ST A		No	No	2023	2023	Construction Records	Copper	C	P	NL	N	N/R	No		No		
408 S VAN BUREN ST B		No	No	2023	2023	Construction Records	Copper	C	P	NL	N	N/R	No		No		
1902 FIETSAM RD		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2700 W DEYOUNG ST B		No	No	2016	2016	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2900 JOSEPH CANNON WAY #SPRIN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1200 Tower Sq. Plaza		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	11/6/2023	Yes	11/6/2023	P	No	
2900 JOSEPH CANNON WAY		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2003 DEW DROP DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
911 E MAIN ST		No	No	1930	1930	Visual Inspection	Lead	C	P	NL	N	N/R	No		No		
916 E MAIN ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
106 N LILLIAN ST		No	No	1900	1900	Survey Response	Unknown	C	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
103 N MADISON ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
406 N MADISON ST		No	No	2024	1910	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
112 E MAIN ST		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	11/6/2023	Yes	11/6/2023	P	No	
1005 N MARKET ST		No	No	1900	1900	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
410 N MARKET ST #A-B		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
414 N MARKET ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
418 N MARKET ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
1115 N MONROE ST		No	No	1920	1920	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
1018 N GRANITE ST		No	No	2023	2023	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
500 W GOODALL ST		No	No	2024	1910	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
806 N COURT ST		No	No	1900	1900	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
906 W BOULEVARD ST		No	No	2024	1960	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1105 N COURT ST		No	No	2024	2024	Maintenance Records	Plastic	C	P	NL	N	N/R	No			No	
510 W MAIN ST		No	Yes	2024	1935	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No	
203 N COURT ST		No	No	1962	1962	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
203 N VICKSBURG ST		No	No	2024	1920	Maintenance Records	Plastic	P	G	NL	N	N/R	No			No	
213 N HAMLET ST		No	No	1930	1930	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
810 E MAIN ST		No	No	1920	1920	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
1203 TOWER SQUARE PLAZA		No	Yes	2023	1920	Maintenance Records	Plastic	P	CLS	NL	N	11/6/2023	Yes	11/6/2023	P	No	
204 N BUCHANAN ST		No	No	1890	1890	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
300 N BUCHANAN ST		No	No	1920	1920	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
300 E JEFFERSON ST		No	No	2024	1918	Maintenance Records	Copper	C	CLS	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
605 W WHITE ST		No	No	2024	1900	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1010 W GOODALL ST		No	No	2024	1930	Maintenance Records	Copper	C	G	NL	N	N/R	No			No	
2605 W MAIN ST		No	No	1951	1951	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
506 S FOZZARD ST		No	No	2024	1940	Maintenance Records	Copper	C	CLS	NL	N	N/R	No			No	
705 S AIKMAN ST		No	No	2024	1920	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
104 S LIBERTY ST 1-4		No	No	1935	1935	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
305 W MAIN ST		No	Yes	2024	1987	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No	
4403 W DE YOUNG ST		No	No	2015	2015	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
501 S LIBERTY ST A		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
501 S LIBERTY ST B		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1508 S MECHANIC ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2814 Joseph Cannon Way		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
2816 Joseph cannon way		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
900 N COURT ST		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2702 CREE DR #SPRINK		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
2203 STEEPLECHASE DR #SPRINK		No	No	1995	1995	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2103 WINDSOR DR #SPRINK		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1301 CAMDEN CT #SPRINK		No	No	1993	1993	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2208 BRENTWOOD DR #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2201 KINGSPONTE DR #SPRINK		No	No	2005	2005	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
801 W MAIN ST #SPRINK		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
501 W BOYTON ST #SPRINK		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Unknown (U)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
3314 W LAKEVIEW RD #SPRINK		No	No	1973	1973	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1710 W DE YOUNG ST SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2500 BLUE HERON DR		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
2500 BLUE HERON DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	C	C	NL	N	N/R	No		No		
701 N OTIS ST		No	No	1950	1950	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
500 N FAIR ST #B		No	No	2022	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
500 N FAIR ST #A		No	No	2022	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
900 N COURT ST #SPRINK		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2808 W DE YOUNG ST #SPRINK		No	No	2002	2002	Survey Response	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
2900 W DE YOUNG ST #SPRINK		No	No	1992	1992	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1303 N MARATHON DR #SPRINK		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2780 KOKOPELLI DR #SPRINK		No	No	1999	1999	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2705 PRESTWICK WAY #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2772 KOKOPELLI DR #SPRINK		No	No	2007	2007	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2735 KOKOPELLI DR #SPRINK		No	No	2008	2008	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
2741 KOKOPELLI DR #SPRINK		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
2761 KOKOPELLI DR #SPRINK		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1518 RYDER CUP BLVD #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		
1500 RYDER CUP BLVD #SPRINK		No	No	2002	2002	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3200 BANTERRA DR #SPRINK		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3401 HEARTLAND ST #SPRINK		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
3203 W DEYOUNG ST		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2603 VERNELL RD #SPRINK		No	No	1985	1985	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
3203 W DEYOUNG ST SPRIN		No	No	1991	1991	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
603 N OTIS ST #B		No	No	1980	1980	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1410 LIONHEART DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1407 LIONHEART DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1409 LIONHEART DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1411 LIONHEART DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1413 LIONHEART DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
901 N GARFIELD ST #B		No	No	Unknown	Unknown	Visual Inspection	Lead	C	C	NL	N	N/R	No		No		
402 S LIBERTY ST		No	No	1899	1899	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
704 N MCLAREN ST		No	No	1920	1920	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
202 E THORN ST		No	No	1920	1920	Maintenance Records	Unknown	G	CLS	NL	N	N/R	No		No		
1007 N MONROE ST		No	No	1982	1982	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1104 N MCLAREN ST		No	No	1969	1969	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1105 E DICKINSON DR		No	No	1972	1972	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
307 N LEAR ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
3308 WATER TOWER RD		No	No	1987	1987	Visual Inspection	Unknown/Not Lead	P	CLS	NL	N	N/R	No		No		
407 E MARION ST		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
507 S CARBON ST		No	No	1970	1970	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
715 E MAIN ST #E		No	No	Unknown	Unknown	Visual Inspection	Lead	P	P	NL	N	N/R	No		No		
811 N MARKET ST		No	No	1880	1880	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1301 E MAIN ST		No	No	1997	1997	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1303 E MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
804 E BOULEVARD ST		No	No	Unknown	Unknown	Visual Inspection	Lead	C	P	NL	N	N/R	No			No	
2105 W COPELAND ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No			No	
912 PENTECOST RD		No	No	2001	2001	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
5001 MEADOWLAND PKWAY		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
7335 COX DR		No	No	2010	2010	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
1602 W MAPLEWOOD ST		No	No	1940	1940	Visual Inspection	Unknown	C	G	NL	N	N/R	No			No	
9130 OLD ROUTE 13		No	No	1958	1958	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1503 SHINNECOCK CT Sprinkler		No	No	2004	2004	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
1109 HORIZON DR SPRINK		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1003 E MCKINLEY ST #B		No	No	2022	1979	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
1117 EARLY BIRD LN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
3207 W COMMERCIAL RD		No	No	1979	1979	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
2002 DEW DROP DR #SPRINK		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
502 S VICKSBURG ST		No	No	1900	1900	Maintenance Records	Unknown	C	CLS	NL	N	N/R	No			No	
806 W CHESTNUT ST		No	No	1922	1922	Maintenance Records	Unknown	C	CLS	NL	N	N/R	No			No	
817 W CHESTNUT ST		No	No	1931	1931	Maintenance Records	Unknown	C	CLS	NL	N	N/R	No			No	
903 W CHESTNUT ST		No	No	1901	1901	Maintenance Records	Unknown	P	P	NL	N	N/R	No			No	
102 S SECOND ST #A		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
102 S SECOND ST #B		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1815 GRANDIOSO ST		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1813 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1811 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1809 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
301 N 5TH ST		No	No	1955	1955	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1219 S COURT ST		No	No	1935	1935	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1221 S COURT ST		No	No	1930	1930	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1223 S COURT ST		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1507 Rendleman #2 "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No	No	
818 E MAIN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No	No	
1108 N WASHINGTON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No	No	
105 W DEYOUNG ST		No	No	2021	2021	Construction Records	Copper	C	P	NL	N	N/R	No		No	No	
1814 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1812 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1810 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1808 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1806 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1804 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1800 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1802 GRANDIOSO DR		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
403 BAINBRIDGE RD		No	No	1965	1965	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No	No	
401 BAINBRIDGE DR "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No	No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1500 W MAIN ST		No	No	1975	1975	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
803 W LEXINGTON ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
1910 MEADOWS LN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1912 MEADOWS LN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1916 MEADOWS LN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
822 W MALDEN ST		No	No	1920	1920	Visual Inspection	Unknown	C	G	NL	N	N/R	No		No		
900 W MALDEN ST		No	No	1984	1984	Visual Inspection	Unknown	P	CLS	NL	N	N/R	No		No		
2316 W MAIN ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	C	UNL	NL	N	N/R	No		No		
1907 DEW DROP		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
709 WEST GOODALL ST		No	No	1960	1960	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
710 NORTH JOHNSON		No	No	1998	1998	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No		No		
312 W MAIN		No	Yes	2024	1930	Maintenance Records	Plastic	P	CLS	NL	N	2/28/2024	Yes	2/28/2024	P	No	
808 N JOHNSON ST		No	No	1920	1920	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
1607 SOUTH CARBON		No	No	1910	1910	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
409 S CARBON		No	No	1955	1955	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
503 W COLLEGE ST		No	No	2024	1930	Maintenance Records	Plastic	P	G	NL	N	N/R	No		No		
1200 GLORY LN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1900 E BOYTON ST #A		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1900 E BOYTON ST #B		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1900 E BOYTON ST #C		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
1900 E BOYTON ST #D		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
800 OLD CREAL SPRINGS RD #A		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
800 OLD CREAL SPRINGS RD #B		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
800 OLD CREAL SPRINGS RD #C		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
800 OLD CREAL SPRINGS RD #D		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1116 EARLY BIRD LN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1112 EARLY BIRD LN		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
406 S DUNCAN ST "Empty Lot"		No	No	2023	Unknown	Maintenance Records	Plastic	P	UNL	NL	N	N/R	No			No	
1112 DAYBREAK DR #SPRINK		No	No	2022	2022	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1900 E BOYTON ST B		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1809 RAMSEY		No	No	2023	2023	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
SOUTH MARKET & GOLF COURSE RD		No	No	2024	2024	Construction Records	Plastic	P	C	NL	N	N/R	No			No	
442 COMFORT DR		Yes	No	2015	2015	Construction Records	Copper	C	P	NL	N	N/R	No			No	
3333 W DE YOUNG ST		Yes	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
3116 WILLIAMSON CO PKWY		Yes	No	1995	1995	Visual Inspection	Unknown/Not Lead	C	P	NL	N	N/R	No			No	
500 E DEYOUNG ST		Yes	No	Unknown	Unknown	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1200 DEW DROP DR		No	No	2014	2014	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2812 JOSEPH CANNON WAY		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
209 S COURT ST		No	No	1930	1930	Survey Response	Unknown	C	P	NL	N	N/R	No			No	
2003 WEST MAIN ST		No	No	1940	1940	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1801 WEST MAIN ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
608 OLD CREAL SPRINGS RD #A		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
608 OLD CREAL SPRINGS RD #B		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). / If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
606 OLD CREAL SPRINGS RD #A		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
606 OLD CREAL SPRINGS RD #B		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
203 S HOLLAND ST		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1602 PHILLIP LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
608 OLD CREAL SPRINGS RD #C		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
608 OLD CREAL SPRINGS RD #D		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
606 OLD CREAL SPRINGS RD #C		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
606 OLD CREAL SPRINGS RD #D		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1305 WEST MAIN ST		No	No	1910	1910	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1000 TOWER SQUARE PL		No	Yes	2023	2023	Maintenance Records	Plastic	P	P	NL	N	11/5/2023	Yes	11/6/2023	C	No	
800 NORTH FAIR ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No			No	
1610 PEABODY		No	No	1983	1983	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
1201 E REEVES ST		No	No	2024	2024	Construction Records	Copper	C	P	NL	N	N/R	No			No	
1203 E REEVES ST		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1202 E PARHAM ST		No	No	2024	1920	Maintenance Records	Copper	C	P	NL	N	N/R	No			No	
1810 N COURT ST		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	P	NL	N	N/R	No			No	
3004 EDGEWOOD PARK		No	No	1963	1963	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
711 SALUKI DR		No	No	2003	2003	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
905 SKYLINE DR "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No			No	
108 AIRWAY DR #SPRINK		No	No	1994	1994	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No			No	
2000 DEW DROP DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
		Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
103 N BENTLEY ST #B		No	No	2024	2003	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
103 N BENTLEY ST #C		No	No	2024	2003	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
205 N BENTLEY ST		No	No	2024	1955	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1806 RAMSEY DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
206 N COURT ST		No	No	2024	2010	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
1113 EARLY BIRD LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2804 JOSEPH CANNON WAY "IRRIGATION"		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2806 JOSEPH CANNON WAY "IRRIGATION"		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
302 S LIBERTY ST		No	No	2024	2024	Construction Records	Unknown	P	P	NL	N	N/R	No		No		
1811 RAMSEY		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
300 W DEYOUNG ST		No	No	1984	1984	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No		
1207 N MONROE ST		No	No	1982	1982	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
902 N HIGHLAND ST		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
803 N FAIR ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
709 N FAIR ST		No	No	1930	1930	Visual Inspection	Unknown	C	P	NL	N	N/R	No		No		
1010 N GARFIELD ST		No	No	1986	1986	Visual Inspection	Unknown	P	P	NL	N	N/R	No		No		
907 E BEECH ST "Empty Lot"		No	No	Unknown	Unknown	Visual Inspection	Unknown	P	UNL	NL	N	N/R	No		No		
206 W STOCKTON ST		No	No	2024	2024	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No		
2791 KOKOPELLI DR #SPRINK		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
2791 KOKOPELLI DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		
302 E THOMPSON ST		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No		



Marion IL



Lead Service Line Full Inspection Report

Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacemnt (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
2806 JOSEPH CANNON WAY		No	No	2024	2024	Construction Records	Copper	C	C	NL	N	N/R	No			No	
2804 JOSEPH CANNON WAY		No	No	2024	2024	Construction Records	Copper	C	C	NL	N	N/R	No			No	
501 E DEYOUNG ST		No	No	2024	2024	Construction Records	Copper	C	P	NL	N	N/R	No			No	
2820 JOSEPH CANNON WAY		No	No	2024	2024	Construction Records	Copper	C	C	NL	N	N/R	No			No	
2820 JOSEPH CANNON WAY #SPRINK		No	No	2024	2024	Construction Records	Copper	C	P	NL	N	N/R	No			No	
1410 E PARHAM ST		No	No	2024	1986	Maintenance Records	Plastic	P	P	NL	N	N/R	No			No	
908 S BUCHANAN ST		No	No	1920	2024	Maintenance Records	Unknown	C	P	NL	N	N/R	No			No	
1303 FOSSE RD		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1804 CALICO RD #SPRINK		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
109 S CARBON ST		No	No	1957	1957	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No			No	
10221 BRIGGS RD		No	No	1974	1974	Visual Inspection	Plastic	P	P	NL	N	N/R	No			No	
1326 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1324 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1322 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1320 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1323 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1321 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1325 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1327 LIONHEART DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1914 MEADOWS LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	
1929 MEADOWS LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No			No	



Marion IL

Lead Service Line Full Inspection Report



Service Addresses	Lead and Copper Sample Site Number	Is this a high-risk facility or area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Classification for Entire Service Line	Was galvanized service line material ever downstream of lead?	Date Customer Notified of Lead Service Line	Was a lead service line previously replaced at this location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of Customer Waiver or IDPH Notification (If Customer Refused Access to Property)
	Lead and Copper Sample site number is the 7 digit number starting with "LP" or "LA"	Examples: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities Yes (Y) or No (N)	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	Examples: How was the Material of this Service Line Identified? Examples: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	Examples: Lead (L) Non-Lead (NL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. Leave blank if previous column was (N).	Examples: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	IF customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. Leave blank if customer has not refused access.
1927 MEADOWS LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1919 MEADOWS LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1921 MEADOWS LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1923 MEADOWS LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1925 MEADOWS LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1407 BRYAN DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
104 N BENTLEY ST "Empty Lot"		No	No	2024	Unknown	Construction Records	Plastic	P	UNL	NL	N	N/R	No		No	No	
9380 LILLIE LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
9360 LILLIE LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
9340 LILLIE LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1603 POSEY ST		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1514 CHAMPIONS DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
1806 ROYE LN		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
102 SKYLINE DR		No	No	2024	2024	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	
309 OLD CREAL SPRINGS RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
202 OLD CREAL SPRINGS RD		No	No	2006	2006	Visual Inspection	Unknown/Not Lead	P	P	NL	N	N/R	No		No	No	
901 S COURT ST #Rear		No	No	1940	1940	Visual Inspection	Unknown	C	CLS	NL	N	N/R	No		No	No	
311 S 5TH ST		No	No	2024	1995	Maintenance Records	Plastic	P	P	NL	N	N/R	No		No	No	
2201 W MAIN ST #SPRINK		No	No	2024	2024	Construction Records	Copper	C	C	NL	N	N/R	No		No	No	
107 E PATRICK ST		No	No	2005	2005	Construction Records	Plastic	P	P	NL	N	N/R	No		No	No	